

# 振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883

Tel: 6747-4810 Fax: 6745-5018

cmmotors@singnet.com.sg

Our Ref: EST418/19/TP

Your Ref: TP claim against SHA2968U

## ESTIMATE

5-Dec-19

**MS First Capital Insurance Ltd**

36 Robinson Road

#16-01 City House

Singapore 068877

**Attn: Motor Claims Department**

Dear Sir/Ms,

**Re: Estimated cost of repair to Yamaha FZ150i no: TBG2721**

Date of accident: 01-11-2019

Parts supply:

1 pc Handle bar	BT	SS	120.00
1 set Handle bar grip	X SVC		40.00X
1 pc Handle bar top bracket	BT		45.00
2 pcs Handle bar balancer @\$12.00	SCH		24.00
1 pc Clutch lever	BR		22.00
1 pc Clutch cable	X SVC		45.00X
1 pc Brake lever	SCH		22.00
1 pc Brake cable	X SVC		45.00X
2 pcs Mirror assy @\$65.00	BR		130.00
1 pc Speedometer unit	CRU.		280.00
1 pc Speedometer unit bracket	BT		35.00
1 pc Headlamp	CRU.		160.00
1 pc Headlamp stay	CRA		35.00
1 pc Headlamp stay cowling	X SVC		65.00X
2 pcs Signal lamps @\$25.00	CRA		50.00
2 pcs Signal lamp side garnish @\$65.00	CRA		130.00
1 pc Horn	BT		25.00
1 pc Front visor	MIS		45.00
1 pc Front mudguard	CRU.		45.00
2 pcs Front fork @\$180.00	BT		360.00
1 pc Front fork centre bracket	?bt		45.00
1 pc Front fork top bracket	?bt		45.00
1 pc Front fork centre shaft	?bt		50.00
1 pc Front rim	BT		220.00
1 pc Radiator	?bt		350.00
2 pcs Front fairing @\$220.00	LH / CRA		440.00
1 pc Fuel tank	PD		380.00
1 pc Rear L/h signal lamp	CRA		35.00
1 pc Footrest L/h	SCH		25.00
1 pc Rear shift gear lever	SCH		45.00
1 pc Rear footrest L/h	X SVC		25.00X
1 pc Rear L/h fairing	CRA		120.00
1 pc Rear rim	X SVC		220.00X
1 set Sticker	NEC.		60.00

3,783.00 3,023

# 振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417003  
Tel: 6747-4810 Fax: 6745-5018  
cmmotors@singnet.com.sg

**Re: Estimated cost of repair to Yamaha FZ150i no: TBG2721**

Date of accident: 01-11-2019

Parts supply:

Balance b/f:

S\$	3,783.00
Less 10%:	<u>(378.30)</u>
	3,404.70

S/Nett Items

1 pc Front tyre (S/Nett) X NN

150.00X

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

500.00 300 /

To apply underseal

50.00X

To respray affected part.

350.00 150 /

To undergo wheel alignment

60.00 30 /

Transportation charges - Tomy.

40.00 / N/C

To check wirings.

30.00 20 /

S\$ 4,206.40

Repair day - 4 days

Sun P.m (Lkk)

13/12/2019.

Tp without prejudice.

8661 2627.

sunph@lkkauto.com

Lump Sum

After part photo

3,027
- 10%
<u>P = 2,720.7</u>
L = 540
<u>3,260.7</u>
- 20%
<u>2,608.56</u>

4/5  
\$ 2,600

4 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: