

INS. CASE OWNER:

CC 3/AIG180 11/97, 12/20/20

LKK:
IDAC:

ASSIGNMENT

Surveyor:

DOI:

Date/Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJN 56654

Claim No.:

Name of Insured:

SHATEKUL MAMUN 91W 8800L

Policy No.:

1900V6255

Insured Tel No.:

HP:

Make / Model:

Mazda

Excess Sec II :\$5

D.O.A.:

13/11/19

Place of Accident:

TO 4YE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

PA 829AH

SJN 56654

SGA 86875



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP: premium

Tel:

Liability:

RMKS:

TP



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time:

SGA 86875

SJN 56654

STAGE

DATE / PIC

25/2/2020

FILE PRO TO FILE MANDATE

5/3/2020

FILE PRO TO FILE TO CLOSE

CB - DV. veh no wrong.

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 4/3/2020

Confirm with: Nodig

Email

Call

Final Liability:

100

(Agreed / Assessed) BOLA S/N No. : 28

If NO or B 28, Ass. Lia : 02

Repair Cost: (w/mt)

\$5 3004.82

3 veh C.C. 02 most 2nd

Loss of Rental (LOR):

\$5 400.00

(4 days) x \$100

Loss of Use (LOU):

\$5 -

(\$ x days)

Loss of Income (LOI):

\$5 -

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

\$5 2.00

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost

\$5 -

Total:

\$5 7406.82

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5 7406.82

Name 1:

Premium Automobiles Pte Ltd

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

COPY SENT
6/3/2020

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: 3320

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 22950

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1485/2019/NS
Date	:	17-Dec-19

Vehicle NOT IN workshop. Please arrange for survey

Your Insured Vehicle no : **SJN 5665 G**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Lum Sow Kok
Address	:	29 West Coast Rise #11-15 Singapore 127472
Telephone	:	HP +65 97803301
Type of Claim	:	Third Party Claim
Policy No.	:	5098336803-01
Vehicle No	:	SGA 8887 S
Model Code	:	Audi A3 SEDAN 1.4 TFSI
Model / Year	:	27/3/2015
Engine No	:	CZC 220327
Chassis No	:	WAUZZZ8V7F1061296
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	13-Dec-19
Place of Accident	:	Slip Road On Jalan Ahmad Ibrahim Towards AYE (City)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGA 8887 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	✓
2	To remove and transfer rear lid's convenience lock system and wire harness for trail lights.	S/N \$ 280.00	✓
3	To dismantle and renew rear bumper and rear lid. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00	1000
4	To respray rear bumper and rear lid.	\$ 2,000.00	1100.
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,852.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGA 8887 S

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remarks
1	REAR BUMPER	S	1,708.00	dec 1366.40
2	REAR BUMPER FIXING PARTS	S	175.00	X n
3	REAR BUMPER GUIDE SECTION - LH/RH	2 S	30.00	7x n
4	LOCKING MECHANISM	2 S	53.00	7x n
5	REAR LIGHT REFLECTOR - LH/RH	2 S	76.00	X n
6	REAR BUMPER SPOILER - LH	S	216.00	7x n
7	REAR BUMPER SIDE REINFORCEMENT BEAM	S	522.00	7x n
8	REAR BUMPER BRACKET - LH / RH	2 S	24.00	7x n
9	REAR PARKING AID SENSOR - INNER / OUTER	2 S	462.00	X n
10	REAR PARKING AID SEAL RING	4 S	12.00	X n
11	REAR LID	S	2,417.00	bt 1933.60
12	REAR LID ATTACHEMENT PARTS	S	267.00	X n
13	REAR LID FLAP GASKET	S	185.00	net 147.60
14	REAR LID LOCK STRIKER	S	45.00	X
15	REAR LID LOCK	S	178.00	X
16	LID LOCK PUSH BUTTON	S	167.00	X
17	REAR LID PROTECT CAP	S	14.00	7x
18	PACKING ADHESIVE	S	18.00	X net 13.92
19	AUDI EMBLEM	S	113.00	net 90
20	A3 INSCRIPTION	S	87.00	net 69.28
21	TFSI INSCRIPTION	S	87.00	net 69.28
22	EXHAUST TAIL PIPE TRIM - LH	S	218.00	X n
23	REAR NO PLATE	S/N S	40.00	X n
24	SUNDRIES	S	300.00	7 4.48 net

TOTAL SPARE PARTS : \$ 7,414.00

TOTAL LABOUR CHARGES : \$ 4,852.00

GRAND TOTAL : \$ 12,266.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tanpin 97498429
'wp'
18/12/19 2:55pm
4 days
Resurvey before paint.
sur E. Khandan.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 22950

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1485/2019/NS
Date : 17-Dec-19

Vehicle NOT IN workshop. Please arrange for survey

Your Insured Vehicle no : **SJN 5665 G**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Taufikh

4 days - ok - jb - 20 Feb 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lum Sow Kok
Address : 29 West Coast Rise
#11-15
Singapore 127472
Telephone : HP +65 97803301
Type of Claim : Third Party Claim
Policy No. : 5098336803-01
Vehicle No : **SGA 8887 S**
Model Code : Audi A3 SEDAN 1.4 TFSI
Model / Year : 27/3/2015
Engine No : CZC 220327
Chassis No : WAUZZZ8V7F1061296
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Dec-19
Place of Accident : Slip Road On Jalan Ahmad Ibrahim Towards AYE (City)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGA 8887 S

S/n	Nature of Jobs		Estimated Charges	Surveyor's recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00	\$ 280.00
2	To remove and transfer rear lid's convenience lock system and wire harness for trail lights.	S/N \$	280.00	\$ 280.00
3	To dismantle and renew rear bumper and rear lid. Re-organise crash management components. Reinstall all parts removed.	\$	2,100.00	\$ 1,000.00
4	To respray rear bumper and rear lid.	\$	2,000.00	\$ 1,100.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 4,852.00	\$ 2,852.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGA 8887 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER	\$ 1,708.00	\$ 1,366.40
2	REAR BUMPER FIXING PARTS	\$ 175.00	
3	REAR BUMPER GUIDE SECTION - LH/RH	2 \$ 30.00	
4	LOCKING MECHANISM	2 \$ 53.00	
5	REAR LIGHT REFLECTOR - LH/RH	2 \$ 76.00	
6	REAR BUMPER SPOILER - LH	\$ 216.00	
7	REAR BUMPER SIDE REINFORCEMENT BEAM	\$ 522.00	
8	REAR BUMPER BRACKET - LH / RH	2 \$ 24.00	
9	REAR PARKING AID SENSOR - INNER / OUTER	2 \$ 462.00	
10	REAR PARKING AID SEAL RING	4 \$ 12.00	
11	REAR LID	\$ 2,417.00	\$ 1,933.60
12	REAR LID ATTACHEMENT PARTS	\$ 267.00	
13	REAR LID FLAP GASKET	\$ 185.00	\$ 147.60
14	REAR LID LOCK STRIKER	\$ 45.00	
15	REAR LID LOCK	\$ 178.00	
16	LID LOCK PUSH BUTTON	\$ 167.00	
17	REAR LID PROTECT CAP	\$ 14.00	
18	PACKING ADHESIVE	\$ 18.00	\$ 13.92
19	AUDI EMBLEM	\$ 113.00	\$ 90.00
20	A3 INSCRIPTION	\$ 87.00	\$ 69.28
21	TFSI INSCRIPTION	\$ 87.00	\$ 69.28
22	EXHAUST TAIL PIPE TRIM - LH	\$ 218.00	
23	REAR NO PLATE	S/N \$ 40.00	
24	SUNDRIES	\$ 300.00	\$ 4.48
TOTAL SPARE PARTS		: \$ 7,414.00	\$ 3,694.56
TOTAL LABOUR CHARGES		: \$ 4,852.00	\$ 2,852.00
GRAND TOTAL		: \$ 12,266.00	\$ 6,546.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

View Received Message

This mail is associated with :

***SGA8887S (8423743900SG)**
[SJN5665G]

TP

LUM SOW KOK

Dec 13 2019 4:00PM

[SHAHRL NIZAM BIN ABDUL MALIK]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 04/03/2020 11:22 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7406.82) - SGA8887S - Claim Handler: Syed-Yusoff, Saliha

Approved:7406.82:pls proceed with settlement @ \$7406.82 [COR-\$7004.82 LOR-\$400 LTA/GIA-\$2] **subject to final repair bill & ATA

DOCUMENTS SUMMARY

There are no documents.

LKK ref only.

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Premium Automobiles Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 7004.82 (Repair Cost), S\$ 400.00 (Loss of rental/use), S\$ 2.00 (Disbursement), for vehicle no. SGA8887S that was damaged pursuant to the accident which occurred on 13/12/2019 (date) along SLIP ROAD ON JALAN AHMAD IBRAHIM TOWARDS AYE(CITY) (location) involving vehicle no/s SJN5665G. This is pursuant to the inspection conducted on 18/12/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LUM SOW KOK ("the third party claimant") of vehicle no. SGA8887S make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGA8887S (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 4th (day) of MAR (month) 2020 (year)



MTM

Signed by appointed surveyor

MANDATE APPROVED ON 4/3/2020

MTM



Signed by "the workshop" (with chop)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Dec 2019 Edit Reg		18 Dec 2019 00:00 Edit Adj Rpt	\$56,546.56 Edit Estimates	\$56,546.56 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	SHAHRUL NIZAM BIN ABDUL MALIK, ID: S8409652J		
Main Claimant:	LUM SOW KOK, ID: S1740150E		
Vehicle Reg. No.:	SGA8887S	Date of Loss:	13/12/2019 16:00 - :59 [56 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8423743900SG	Policy/Cover Note No.:	1900062155 (Comprehensive)
Vehicle Reg. No. (Insured):	SJN5665G	Policy No. (Claimant):	5098336803-01
		Excess:	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/12/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (04/03/2020): Alert - Adj Mandate Approved (\$57406.82) - SGA8887S - Claim Handler: Syed-Yusoff...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGA8887S (8423743900SG)
[SJN5665G]
TP
LUM SOW KOK
Dec 13 2019 4:00PM
[SHAHRL NIZAM BIN ABDUL MALIK]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser v	
Video				
			1 per page v	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/12/19 15:25	Video - Accident	 Load MOV	
Letters/Correspondences				
			1 per page v	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	
Photos/Images				
			3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/03/20 16:42	Odometer Reading	 Load JPG	☒
2	03/03/20 16:42	General View	 Load JPG	☒
3	03/03/20 16:42	General View	 Load JPG	☒
4	03/03/20 16:42	General View	 Load JPG	☒
5	03/03/20 16:42	General View	 Load JPG	☒
6	03/03/20 16:42	General View	 Load JPG	☒
7	03/03/20 16:42	General View	 Load JPG	☒
8	03/03/20 16:42	General View	 Load JPG	☒
9	03/03/20 16:42	General View	 Load JPG	☒
10	03/03/20 16:42	General View	 Load JPG	☒
11	03/03/20 16:42	General View	 Load JPG	☒
12	03/03/20 16:42	General View	 Load JPG	☒
13	03/03/20 16:42	General View	 Load JPG	☒
14	03/03/20 16:42	General View	 Load JPG	☒
15	03/03/20 16:42	General View	 Load JPG	☒
16	03/03/20 16:42	General View	 Load JPG	☒
17	03/03/20 16:42	General View	 Load JPG	☒
18	03/03/20 16:42	General View	 Load JPG	☒
19	03/03/20 16:42	General View	 Load JPG	☒
20	03/03/20 16:42	General View	 Load JPG	☒
21	03/03/20 16:42	General View	 Load JPG	☒
22	03/03/20 16:42	General View	 Load JPG	☒
23	03/03/20 16:42	General View	 Load JPG	☒
24	03/03/20 16:42	General View	 Load JPG	☒
25	03/03/20 16:45	Reinspection Photo	 Load JPG	☒
26	03/03/20 16:45	Reinspection Photo	 Load JPG	☒
27	03/03/20 16:45	Reinspection Photo	 Load JPG	☒
28	03/03/20 16:45	Reinspection Photo	 Load JPG	☒
Documentation				
			1 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/12/19 15:16	TP GIA REPORT	 Load PDF	
2	27/02/20 11:40	LETTER TO OI	 Load PDF	
3	03/03/20 16:48	LOD	 Load PDF	
4	03/03/20 16:48	RENTAL RECEIPT	 Load PDF	
5	03/03/20 16:48	GIA SEARCH FEE	 Load PDF	
6	09/03/20 08:48	WORKSHOP INVOICE	 Load PDF	
7	09/03/20 08:48	AUTHORISATION TO ACT FORM	 Load PDF	

Video					1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
8	09/03/20 08:48	Release Voucher		Load PDF		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	17/12/19 11:03	OI GIA REPORT		Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJN5665G (Insd veh)	Model:	AUDI A3 1.4 SEDAN TFSI
	SGA8887S (TP veh)		(AMBIENTE) (A)
Date of Accident:	13/12/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	13,124.62
Final Repair Cost	:	\$	7,004.82
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	400.00 4 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	7,406.82
Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____(%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____100_____(%)		Assessed Liability (*): _____0_____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	:	\$ 7,406.82
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

09 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19022097/T1DS3Q2

Date: 09/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900062155
 Claimant SGA8887S Insured Vehicle No : SJN5665G
 Vehicle No : Date of Loss: 13/12/2019 Nature of Claim: TP Claim No: 8423743900SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGA8887S
 Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A) Engine No: CZC220327
 Reg. Date: 27/03/2015 (Man. Year: 2014) Chassis No: WAUZZZ8V7F1061296
 Colour: Black Odometer: 80391 km
 Engine Capacity: 1395 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,414.00	3,694.56	3,719.44	50.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,852.00	2,852.00	2,000.00	41.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,266.00	6,546.56	5,719.44	46.63
+ GST 7.00/7.00% (S\$)	858.62	458.26	400.36	46.63
Nett Amount (S\$)	13,124.62	7,004.82	6,119.80	46.63
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,406.82		

INSPECTION

Date of Assignment: 18/12/2019
 Date Inspected: 18/12/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
 55 Ubi Road 1
 Singapore 408699
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,708.00 FS	*1,366.40 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	175.00 FS	*- FS
3	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	30.00 FS	*- FS
4	2		*LICKING MECHANISM	Not Necessary	53.00 FS	*- FS
5	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	76.00 FS	*- FS
6	1		*REAR BUMPER SPOILER -LH	Not Necessary	216.00 FS	*- FS
7	1		*REAR BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	522.00 FS	*- FS
8	2		*REAR BUMPER BRACKET -LH/RH	Not Necessary	24.00 FS	*- FS
9	2		*REAR PARKING AID SENSOR -INNER /OUTER	Not Necessary	462.00 FS	*- FS
10	4		*REAR PARKING AID SEAL RING	Not Necessary	12.00 FS	*- FS
11	1		*REAR LID	Bent	2,417.00 FS	*1,933.60 FS
12	1		*REAR LID ATTACHMENT PARTS	Not Necessary	267.00 FS	*- FS
13	1		*REAR LID FLAP GASKET	Necessary	185.00 FS	*147.60 FS
14	1		*REAR LID LOCK STRIKER	Not Necessary	45.00 FS	*- FS
15	1		*REAR LID LOCK	Not Necessary	178.00 FS	*- FS
16	1		*LID LOCK PUSH BUTTON	Not Necessary	167.00 FS	*- FS
17	1		*REAR LID PROTECT CAP	Not Necessary	14.00 FS	*- FS
18	1		*PACKING ADHESIVE	Necessary	18.00 FS	*13.92 FS
19	1		*AUDI EMBLEM	Necessary	113.00 FS	*90.00 FS
20	1		*A3 INSCRIPTION	Necessary	87.00 FS	*69.28 FS
21	1		*TFSI INSCRIPTION	Necessary	87.00 FS	*69.28 FS
22	1		*EXHAUST TAIL PIPE TRIM -LH	Not Necessary	218.00 FS	*- FS
23	1		*REAR NO PLATE	Not Necessary	40.00 FS	*- FS
24	1		*SUNDRIES	Necessary	300.00 FS	*4.48 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	7,414.00	3,694.56
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TRAIL LIGHTS	New	280.00	280.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY REAR BUMPER AND REAR LID	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,852.00	2,852.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >