Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 22950

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/TP/1485/2019/NS

Date : 17-Dec-19

Vehicle NOT IN workshop. Please arrange for survey

Your Insured Vehicle no : SJN 5665 G

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Model Code

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lum Sow Kok
Address : 29 West Coast Rise

#11-15

Vehicle No : SGA 8887 S

Model / Year : 27/3/2015 Engine No : CZC 220327

Chassis No : WAUZZZ8V7F1061296

Mileage : Date In : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 13-Dec-19

Place of Accident : Slip Road On Jalan Ahmad Ibrahim Towards AYE (City)

Audi A3 SEDAN 1.4 TFSI

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGA 8887 S

S/n	Nature of Jobs	ú	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$ 280.00	/
2	To remove and transfer rear lid's convenience lock system and wire harness for trail lights.	S/N	\$ 280.00	
3	To dismantle and renew rear bumper and rear lid. Re-organise crash management components. Reinstall all parts removed.		\$ 2,100.00	1000
4	To respray rear bumper and rear lid.		\$ 2,000.00	1100.
5	To carry out diagnostic check.	S/N	\$ 192.00	
	TOTAL LABOUR CHARGES	:	\$ 4,852.00	1878 - N. P.

Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGA 8887 S

S/N	Parts Description		<u>Damaged Parts & Prices</u> S/Nett Remarks
1	REAR BUMPER		\$ 1,708.00 des
2	REAR BUMPER FIXING PARTS		\$ 175.00 🔏
3	REAR BUMPER GUIDE SECTION - LH/RH	2	\$ 30.00 ?
4	LOCKING MECHANISM	2	\$ 53.00
5	REAR LIGHT REFLECTOR - LH/RH	2	\$ 76.00 ×
6	REAR BUMPER SPOILER - LH		\$ 216.00 7
7	REAR BUMPER SIDE REINFORCEMENT BEAM		\$ 522.007
8	REAR BUMPER BRACKET - LH / RH	2	\$ 24.00
9	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 462.00×
10	REAR PARKING AID SEAL RING	4	\$ 12.00 🗙
11	REAR LID		\$ 2,417.00 67
12	REAR LID ATTACHEMENT PARTS		\$ 267.00 ⊀
13	REAR LID FLAP GASKET		\$ 185.00 101
14	REAR LID LOCK STRIKER		\$ 45.00 Ҳ
15	REAR LID LOCK		\$ 178.00 ★
16	LID LOCK PUSH BUTTON		\$ 167.00 ★
17	REAR LID PROTECT CAP		\$ 14.00 7
18	PACKING ADHESIVE		\$ 18.00 X
19	AUDI EMBLEM		\$ 113.00 NU
20	A3 INSCRIPTION		\$ 87.00 New
21	TFSI INSCRIPTION		\$ 87.00 W
22	EXHAUST TAIL PIPE TRIM - LH		\$ 218.00 🗙
23	REAR NO PLATE	S/N	\$ 40.00 ×
24	SUNDRIES		\$ 300.00 7
	TOTAL SPARE PARTS	:	\$ 7,414.00
	TOTAL LABOUR CHARGES	:	\$ 4,852.00
	GRAND TOTAL	:	\$ 12,266.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

Tauflin 9749 Freq

18/17/19 e 215pm

cur P Illia town

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

oignaturi

Date:

Johnny Boo Body Repair Manager Allan Wu

Claims Consultant