

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19022100/APA3Q2

Date: 06/07/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0000734
Claimant Vehicle No :	SJF3846G	Insured Vehicle No :	SMH2890M
Date of Loss:	12/12/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0001708

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF3846G	Engine No:	3ZZ4768532
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106109424
Reg. Date:	28/05/2008 (Man. Year: 2008)	Odometer:	194959 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,806.35	2,656.35	7,150.00	72.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,080.00	1,530.00	2,550.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,886.35	4,186.35	9,700.00	69.85
Approved Total (Overridden) (S\$)		3,300.00		
Nett Amount (S\$)	13,886.35	3,300.00	10,586.35	76.24
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,707.45		
Global Sum Settlement (S\$)		3,350.00		

INSPECTION

Date of Assignment:	16/12/2019	
Date Inspected:	16/12/2019 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$21,000.00(est) less LTA Rebate: \$13,489.00(est) = Nett Value :\$7,511.00(est)

Please note that third party vehicle COE expiry date is 28 Feb 2023.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Mar 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF3846G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BONNET	Repair	825.50 FL	*- FL
2	1	*FRONT BONNET LOCK	Not Necessary	87.30 FL	*- FL
3	2	*FRONT BONNET HINGE	Not Necessary	151.40 FL	*- FL
4	1	*FRONT BONNET INSULATOR	Not Necessary	281.50 FL	*- FL
5	1	*FRONT BONNET SEAL	Not Necessary	63.60 FL	*- FL
6	1	*FRONT SUPPORT PANEL	Not Necessary	804.60 FL	*- FL
7	1	*FRONT CENTRE BRACE PANEL	Not Necessary	117.80 FL	*- FL
8	1	*FRONT HEAD LAMP	O/S Cut	1,970.40 FL	*485.00 FL
9	1	*FRONT GRILLE	Not Necessary	396.60 FL	*- FL
10	1	*FRONT GRILLE EMBLEM	Not Necessary	56.30 FL	*- FL
11	1	*FRONT HORN	Not Necessary	63.50 FL	*- FL
12	1	*FRONT BUMPER	Deformed	625.20 FL	*452.00 FL
13	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	425.20 FL	*- FL
14	1	*FRONT BUMPER SIDE RETAINER	O/S Damaged	131.20 FL	*65.60 FL
15	1	*FRONT BUMPER LOWER GRILLE	Not Necessary	94.20 FL	*- FL
16	1	*FRONT BUMPER FOG LAMP RH	Cracked	295.10 FL	*295.10 FL
17	1	*FRONT BUMPER FOG LAMP COVER	Cracked	86.20 FL	*86.20 FL
18	1	*FRONT BUMPER TOP RUBBER SEAL	Not Necessary	35.20 FL	*- FL
19	1	*FRONT BUMPER REINFORCEMENT BRACKET RH	Not Necessary	256.30 FL	*- FL
20	1	*AIRCOND CONDENSER	Not Necessary	1,295.60 FL	*- FL
21	1	*RADIATOR	Not Necessary	1,691.80 FL	*- FL
22	1	*FRONT FENDER RH	Dented	401.20 FL	*401.20 FL
23	1	*FRONT FENDER SHIELD RH	Deformed	181.20 FL	*181.20 FL
24	1	*FRONT FENDER TOP SIDE GARNISH RH	Not Necessary	101.20 FL	*- FL
25	1	*FRONT FENDER EMBLEM (VVTI) RH	Necessary	49.20 FL	*49.20 FL
26	1	*WASHER TANK	Deformed	185.20 FL	*185.20 FL
27	1	*WASHER TANK MOTOR	Not Necessary	112.30 FL	*- FL
28	1	*FRONT SHOCK ABSORBER RH	Bent	502.40 FL	*393.70 FL
29	1	*FRONT KNUCKLE ARM RH	Bent	472.40 FL	*472.40 FL
30	1	*FRONT LOWER ARM RH	Bent	434.20 FL	*395.00 FL
31	1	*FRONT WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
32	10	*FRONT INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
33	10	*FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
34	1	*FRONT NUMBER PLATE	Not Necessary	45.00 FS	*- FS
35	1	*FRONT FENDER COWLING CLIP (16 PCS)	Necessary	80.00 FS	*30.00 FS
36	1	*FRONT RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
37	1	*BATTERY	Not Necessary	250.00 FS	*- FS
38	1	*IU BRACKET	Not Necessary	26.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,854.80	3,521.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,048.45	865.45
Total Parts (\$\$)	9,806.35	2,656.35

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TUFF KOTE	New	150.00	0.00
3	WHEEL ALIGNMENT	New	150.00	80.00
4	REMOVE AND REFIX REPLACE AIRCON CONDENSOR & REFILL GAS	New	150.00	0.00
5	REMOVE AND REPLACE RADIATOR	New	100.00	0.00
6	REMOVE AND REPLACE UNDERCARRIAGE (FRONT)	New	450.00	220.00
7	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	1,500.00	600.00
8	TO SPRAY PAINTING AND ETC	New	1,500.00	600.00
Gross Labour Cost (S\$)			4,080.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >