

CHOO MOTOR SPRAY PAINTER

PAGE 1 OF 2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Reg No: 22736900M

Estimate : 21586

Date : 16.12.2019

Vehicle Num : SJF 3846G

Make/Model : TOYOTA ALTIS

Chassis/Engine no :

Accident Date: 12.12.2019

Claim No : 1219-21586

Reference:

Policy No :

TP 111

Xiao Tong

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Front bonnet <i>Repair</i>	\$ 825.50 +
1 pc	Front bonnet lock <i>new</i>	\$ 87.30 +
2 pc	Front bonnet hinge @ 75.70 <i>2</i>	\$ 151.40 +
1 pc	Front bonnet insulator	\$ 281.50 +
1 pc	Front bonnet seal <i>new</i>	\$ 63.60 +
1 pc	Front support panel	\$ 804.60 +
1 pc	Front centre brace panel	\$ 117.80 +
2 pc	Front head lamp @ 985.20 <i>RH cut</i>	\$ 1,970.40 485 985.20
1 pc	Front grille <i>new</i>	\$ 396.60 +
1 pc	Front grille emblem <i>new</i>	\$ 56.30 +
1 pc	Front horn <i>new</i>	\$ 63.50 +
1 pc	Front bumper <i>Del'd</i>	\$ 625.20 452
1 pc	Front bumper reinforcement <i>new</i>	\$ 425.20 65.60
2 pc	Front bumper side retainer @ 65.60 <i>RH Dmg'd</i>	\$ 131.20 65.60
1 pc	Front bumper lower grille <i>new</i>	\$ 94.20 +
1 pc	Front bumper fog lamp RH <i>Del'd</i>	\$ 295.10 <i>2</i>
1 pc	Front bumper fog lamp cover <i>Del'd</i>	\$ 86.20 <i>2</i>
1 pc	Front bumper top rubber seal <i>new</i>	\$ 35.20 +
1 pc	Front bumper reinforcement bracket RH <i>new</i>	\$ 256.30 +
1 pc	Aircond condenser <i>3 new new</i>	\$ 1,295.60 +
1 pc	Radiator	\$ 1,691.80 +
1 pc	Front fender RH <i>Del'd</i>	\$ 401.20 -
1 pc	Front fender shield RH <i>Del'd</i>	\$ 181.20 -
1 pc	Front fender top side garnish RH <i>new</i>	\$ 101.20 +
1 pc	Front fender emblem (yvti) RH <i>new</i>	\$ 49.20 -
1 pc	Washer tank <i>Del'd</i>	\$ 185.20 -
1 pc	Washer tank motor <i>new</i>	\$ 112.30 + <i>383-70</i>
1 pc	Front shock absorber RH <i>Bent</i>	\$ 502.40 <i>2</i>
1 pc	Front knuckle arm RH <i>Bent</i>	\$ 472.40 <i>2</i>
1 pc	Front lower arm RH <i>Bent</i>	\$ 434.20 <i>385</i>
List Item Total		\$ 12,193.80
Discount 25%		\$ 3,048.45
		\$ 9,145.35

3461.80

2596.35

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Reg No: 22736900M

PAGE 2 OF 2

Estimate : 21586

Date : 16.12.2019

Vehicle Num : SJF 3846G

Make/Model : TOYOTA ALTIS

Chassis/Engine no :

Accident Date : 12.12.2019

Claim No : 1219-21586

Reference :

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

Special Nett Item :

1 pc Front windscreen sealant	\$	100.00 +
10pc Front insulator clip @ 5.00	\$	50.00 +
10pc Front bumper clip @ 5.00	\$	50.00 - 30
1 pc Front number plate	\$	45.00 +
16pc Front fender cowling clip @ 5.00	\$	80.00 - 30
1 pc Front radiator coolant	\$	60.00 +
1 pc Battery	\$	250.00 +
1 pc IU Braket	\$	26.00 +
Special Nett Total :	\$	661.00

Labour Charge :

To check wiring	\$	80.00 - 30
Tuff kote	\$	150.00 +
Wheel alignment	\$	150.00 - 80
Remove and refix replace aircon condensor & refill gas	\$	150.00 +
Remove and replace radiator	\$	100.00 +
Remove and replace undercarriage (Front)	\$	450.00 - 220
To remove and replace spare part and panel beating	\$	1,500.00 600
To spray painting and etc	\$	1,500.00 600
Labour Charge Total :	\$	4,080.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Amount : \$ 13,886.35

Adrian Lj
L/S 16/12/19.
05 Days.
Total: 4186.35
L/S: 33K

CHOO MOTOR SPRAY PAINTER