

ASSIGNMENT

Surveyor: BRYAN

DOI: 09/12/2019

Date / Time: 09/12/2019

Registered in Merimen: 16/12/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SDL 139Z

Claim No. : 1201900038703

Name of Insured : KHOO MIA SONG

Policy No. : PNCV2019-00001294

Insured Tel No. : HP: +65-96684263

Make / Model : TOYOTA HARRIER G GRADE

Excess Sec II :SS D.O.A : 06/12/2019 08:15

Place of Accident : PE/ SLE HEADING TOWARDS ANG MO KIO LAMP POST 566

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SHA 1666Y



INSRS: WSP: CHUNNI
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
	SLL 8136J - CC4/FCI19021822/Aka3; DOA: 06.12.19 SDL 139Z - X	
31/12/19	File -> Bryan to find file	
14/01/2020	gname 2/5 20008/- ote 12 dqs	
14/1/2020	File -> type mandate	
16/3/2020	File -> su ci to al BV	
18/3/2020	File pass to mk to close.	

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: S\$ days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: Confirm with: Email Call

Final Liability: % (Agreed / Assessed) BOLA S/N No: 28 If NO or B 28, Ass. Lia: 100%.

Repair Cost: S\$ 2140.00 (5 Veh. r. UID 1001)

Loss of Rental (LOR): S\$ 1504.80 (12 days) x 45/25.40

Loss of Use (LOU): S\$ (5 days)

Loss of Income (LOI): S\$ 600.00 (556 x 12 days)

LOR only LOU only LOR + LOU LOR + LOI (Tick only one)

GIA/LTA Search S\$ 0.00

Medical: S\$ -

Disbursement: S\$ - (e.g. Tow/ Independent)

Legal Cost: S\$ -

Total: S\$ 23506.80 Global Sum S\$: 23500.00

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: S\$ 23500.00 Name 1: Chunni Motor Work Pte Ltd

Payee 2: (Strike if N.A.) S\$ Name 2:

Payee 3: (Strike if N.A.) S\$ Name 3:

COPY SENT 18/3/2020


ADD. REQ. BY:

REP:

ASSIGNMENT

06 June 2025

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 12 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHA 1666 Y Yr Regn: 2017 June
 Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prius c.c. 1798
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 329142 T/Radio: Insured / Std / NI / NA
 Eng/No: 2ZRS054842
 C/No: JTDKB3FU803560989
 Gen. Cond: 8 Good / Fair / Poor / Burnt
 Steering: 8 Insured / Jammed / Leaked / Burnt or
 Brake: 8 Insured / Jammed / Leaked / Burnt or
 Modi: Nil / (S/Rim) / STD A/Rim or _____
 Tyre Size: F: 195/65 R 15
 R: — — —
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Davanti
 Front: _____ Rear: _____
 R/Bal: S mm R/Bal: S mm
 L/Bal: S mm L/Bal: S mm
 D.O.A. 06/12/2019 D.O.I. 09/12/2019
 Survey held at Churni AMK
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front y Rr
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>FWD SDL 139 Z</u>
<u>14/01/2020</u>	<u>Invoice 45 20000/- with 12 days of rep</u>
	<u>(Red # 27388.71 / 5840)</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee: _____
 Transportation: _____
 S + RS \$
 Photos
 Other
 TOTAL

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHA 1666Y

DATE : 6.12.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

FND

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
BONNET <i>BT</i>			S 950.50
INSULATOR, HOOD <i>NW</i>			S 398.10
BONNET HINGE (LH/RH) <i>NW</i>		S 57.70	S 115.40
BONNET LOCK <i>NW</i>			S 132.60
RADIATOR GRILLE <i>broken</i>			S 438.00
RADIATOR GRILLE EMBLEM <i>BT</i>			S 88.00
LAMP ASSY, FOG, RH <i>NW</i>			S 920.00
LAMP ASSY, FOG, LH <i>NW</i>			S 920.00
FRONT BUMPER COVER <i>Detail</i>			S 499.90
FRONT BUMPER REINFORCEMENT <i>broken</i>			S 696.40
FRONT BUMPER REINFORCEMENT ABSORBER <i>Detail</i>			S 115.70
FRONT BUMPER SPONGE <i>tan</i>			S 78.80
FRONT BUMPER CENTRE GRILLE <i>deformed</i>			S 301.90
FRONT BUMPER CLIPS <i>NW</i>			S 22.00
FRONT BUMPER SIDE RETAINER <i>NW</i>		S 77.00	S 154.00
FRONT BUMPER TOP GARNISH <i>S/C</i>			S 225.40
COVER, FRONT BUMPER HOLE, RH <i>distorted</i>			S 28.38
COVER, FRONT BUMPER HOLE, LH <i>eyr</i>			S 28.38
FRONT BUMPER CENTRE FRAME <i>NW</i>			S 236.90
BRACKET, FRONT BUMPER SIDE, RH <i>NW</i>			S 82.30
BRACKET, FRONT BUMPER SIDE, LH <i>NW</i>			S 82.30
UNIT ASSY, HEADLAMP, RH (LED) <i>mainly broken</i>			S 3,455.00
UNIT ASSY, HEADLAMP, LH (LED) <i>mainly broken</i>			S 3,455.00
HEAD LAMP PANEL (RH) <i>BT</i>			S 240.10
HEAD LAMP PANEL (LH) <i>BT</i>			S 240.10
TOP PANEL CENTRE <i>BT</i>			S 364.90
TOP PANELSIDE, LH <i>BT</i>			S 145.90
TOP PANEL SIDE, RH <i>BT</i>			S 145.90
BRACE PANEL <i>BT</i>			S 75.20
RADIATOR ASSY <i>BT / punctured</i>			S 1,841.80
RADIATOR FAN COWLING ASSY <i>NW</i>			S 661.30
RADIATOR BOTTOM MOUNTING <i>NW</i>			S 27.50
STAY, RADIATOR SUPPORT, RH <i>NW</i>			S 65.70
STAY, RADIATOR SUPPORT, LH <i>NW</i>			S 65.70
RADIATOR FAN BLADE (RH) <i>NW</i>			S 233.10
RADIATOR FAN BLADE (LH) <i>NW</i>			S 233.10
RADIATOR FAN MOTOR (RH) <i>NW</i>			S 543.70
RADIATOR FAN MOTOR (LH) <i>NW</i>			S 543.70
DEFLECTOR, RADIATOR SIDE, RH <i>BT / deformed</i>			S 83.50
DEFLECTOR, RADIATOR SIDE, LH <i>NW</i>			S 77.00
HORN <i>NW</i>		S 112.71	S 225.42
CLEANER ASSY, AIR <i>Detail / cracked</i>			S 970.30
AIR DUCT <i>broken / Dam</i>			S 129.40
INLET ASSY, AIR CLEANER <i>NW</i>			S 132.00
AIR DUCT CENTRE <i>NW</i>			S 94.03
CONDENSER ASSY, W/RECEIVER <i>BT / punctured</i>			S 1,336.60
WIRING FRONT <i>NW</i>			S 6,685.90

Handwritten checkmarks and 'X' marks in the right margin of the table, indicating the status of each item.

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
SUB TOTAL			S 28,586.81
LESS 20% <i>25%</i>		15703.28	S 5,717.36
DISCOUNTED TOTAL		11777.46	S 22,869.45
FRONT NO. PLATE <i>Wf</i>			S 25.00
FRONT NO PLATE TRIM COVER <i>broken</i>			S 45 } 30.00
FRONT NO.PLATE GARNISH <i>broken</i>		144.00	S 99.00
			S 154.00
LABOUR CHARGE			
Panel Beating			S 1,000.00
Spray Painting Charge			S 750.00
Wiring Charge			S 50.00
Towing Charge		1410.00	S 90.00
Remove/Refix Aircon & Refill Gas			S 150.00
Remove/Refix Engine			S 450.00
Diagnosis & Resetting To Erase Fault Code			S 480.00
TOTAL LABOUR			S 2,970.00
REAR TRUNK LID COVER <i>new</i>			S 1,126.60
REAR TRUNK LID LOCK <i>Down</i>			S 457.90
REAR TRUNK LID COVER TRIM BOARD <i>broken</i>			S 254.40
REAR TRUNK LID RUBBER <i>defunct</i>			S 365.20
REAR TRUNK LID GLASS (BLACK COLOR) <i>shattered</i>			S 1,569.70
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>broken</i>			S 889.70
REAR TRUNK LID LOGO(PRIUS) <i>new</i>			S 52.90
REAR TRUNK LID LOGO(HYBRID) <i>new</i>			S 52.90
REAR TRUNK LID LOGO(TOYOTA STAR) <i>new</i>			S 47.00
REAR BUMPER <i>Dented / torn</i>			S 458.60
REAR BUMPER RE-INFORCEMENT <i>Dented</i>			S 318.80
REAR BUMPER UNDER COVER <i>broken / Dented</i>			S 552.60
REAR BUMPER SIDE RETAINER <i>new</i>		S 112.70	S 225.40
REAR BUMPER UNDER SIDE COVER (RH) <i>dislodged / broken</i>			S 232.00
REAR BUMPER UNDER SIDE COVER (LH) <i>dislodged / broken</i>			S 232.00
REAR BUMPER UNDER SIDE CENTRE COVER <i>dislodged / broken</i>			S 552.60
REAR BUMPER TOWING COVER <i>defunct / dislodged</i>			S 82.70
REAR BUMPER CLIPS <i>new</i>			S 22.00
ARM SUB-ASSY, REAR BUMPER, RH <i>new</i>			S 139.60
ARM SUB-ASSY, REAR BUMPER, LH <i>new</i>			S 139.60
SEAL, REAR BUMPER SIDE, RH <i>dislodged / broken</i>			S 148.40
SEAL, REAR BUMPER SIDE, LH <i>dislodged / broken</i>			S 148.40
TAIL LAMP ASSY (UPPER) (LH/RH) <i>crack / missing glass</i>	S	557.90	S 1,115.80
TAIL LAMP ASSY (LOWER) (LH/RH) <i>crack / missing glass</i>	S	548.40	S 1,096.80

NETT ✓
NETT ✓
NETT ✓
S 154.00
S 1,000.00 800/-
S 750.00 500/-
S 50.00 30/-
S 90.00 75/-
S 150.00 80/-
S 450.00 75/-
S 480.00 75/-
S 2,970.00
S 1,126.60
S 457.90
S 254.40
S 365.20
S 1,569.70
S 889.70
S 52.90
S 52.90
S 47.00
S 458.60
S 318.80
S 552.60
S 225.40
S 232.00
S 232.00
S 552.60
S 82.70
S 22.00
S 139.60
S 139.60
S 148.40
S 148.40
S 1,115.80
S 1,096.80

SHA 1666Y

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR END PANEL <i>Sm</i>			\$ 602.10	✓
REAR END PANEL GARNISH <i>defused</i>			\$ 165.80	✓
REAR SPARE TYRE PANEL <i>Sm</i>			\$ 667.70	✓
REAR SPARE TYRE CUSHION (FLR BOARD CENTRE) <i>NH</i>			\$ 750.00	X
3RD BRAKE LIGHT <i>NH</i>			\$ 198.00	X
FIBER TOOLS BOX TRAY <i>broken</i>			\$ 398.00	✓
REAR EXHAUST PIPE <i>NH</i>			\$ 1,163.40	X
REAR EXHAUST PIPE HANGER <i>NH</i>			\$ 40.70	X
REAR EXHAUST PIPE INSULATOR <i>1st</i>			\$ 314.60	✓
REAR FENDER, LH <i>Painted</i>			\$ 836.70	✓
REAR FENDER AIR DUCT <i>NH</i>			\$ 165.10	X
REAR CHASSIS MEMBER <i>range NH</i>			\$ 1,180.80	X
REAR WINDSCREEN GLASS WITH MOULDING <i>Shatter</i>		14540.20	\$ 1,778.30	✓
REAR WIRING ASSY <i>NH</i>			\$ 582.40	X
SPOILER SUB-ASSY, REAR <i>NH</i>		10905.15	\$ 953.70	X
SUB TOTAL			\$ 20,078.90	
LESS 20% <i>25%</i>			\$ 4,015.78	
DISCOUNTED TOTAL			\$ 16,063.12	
REAR NO. PLATE WITH TRIM COVER <i>1st</i>			\$ 45/- 100.00	NETT ✓
REAR TRUNK LID APPS STICKER <i>New</i>			\$ 40.00	NETT ✓
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>New</i>		326.70	\$ 60.00	NETT ✓
REAR BUMPER REVERSE SENSOR <i>Down</i>			\$ 135.70	NETT ✓
REAR WINDSCREEN SEALANT <i>New</i>			\$ 46.00	NETT ✓
			\$ 381.70	
LABOUR CHARGE	<div style="border: 1px solid black; padding: 5px; font-size: small;"> LKK Auto Consultants hence is the Repairer of the following: <ul style="list-style-type: none"> To resurvey before/after spray To display damaged parts Parts prices are subject to Third party survey is on a No illegal modifications Supplementary items is subject to final </div>			
Panel Beating			\$ 2,200.00	1000/-
Spray Painting Charge			\$ 1,750.00	900/-
Wiring Charge			\$ 50.00	30/-
Tuff Kote			\$ 100.00	40/-
Front Chassis Alignment Charge			\$ 200.00	7/-
Remove/Refix Cushion & Upholstery <i>Rear</i>			\$ 150.00	80/-
Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
Remove/Refix Reverse Sensor			\$ 80.00	40/-
Remove/Refix Fuel Tank		2230.00	\$ 150.00	7/-
Remove/Refix Exhaust Pipe			\$ 150.00	60/-
TOTAL LABOUR			\$ 4,950.00	
ESTIMATE TOTAL			\$ 47,388.27	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO : SHA 1666Y (Supplementary)


DATE : 18.12.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	REAR DOOR COMFORT & APPS STICKER, LH <i>Hec</i> 			5 80.00	NETT ✓

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 24 Dec 2019

Preliminary Advice

Insured Vehicle No	: SDL139Z	Accident Date	: 06/12/2019
TP Vehicle No	: SHA1656Y	Assignment Date	: 16/12/2019
Make	: TOYOTA PRIUS	Est. Duration of Repair	: 12 days
Date of Inspection	: 09/12/2019		
Inspection At	: Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...front and rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	47,468.27
Revised Amount	:S\$	27,033.81
Check Items (Estimated)	:S\$	0.00
Total	:S\$	27,033.81

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

Hsiao Tong (LKKAuto)

From: Chunni motor Work <chunnimw@yahoo.com.sg>
Sent: Friday, 13 March 2020 1:45 PM
To: Hsiao Tong (LKKAuto)
Subject: Re: [EXTERNAL] Re: ACCIDENT INVOLVING SHA 1666 Y & SDL 139 Z ON 06-12-2019

Your Ref : SDL 139 Z (FWD)
Our Ref : SHA 1666 Y (061219)

WITHOUT PREJUDICE

Dear Hsiao Tong,

Your email of 13-03-2020 refers.

Strictly on a without prejudice basis and without any admission of liability, we confirm settlement for our client's property damage claim (Cost of repair, GIA search fee and the Loss of rental & income during the period of repair) at a global sum of \$23,500.00.

Please note that the settlement reached is strictly for the aforesaid property damage claim only and is without prejudice to the relief driver of SHA 1666 Y, Teng King Guan's injury claim & other losses against your principals, M/s FWD Singapore Pte Ltd and /or their insured through his own solicitor.

Kindly forward us your Discharge Voucher as soon as possible.

Thank you.

Best Regards
William
Claims Department

Chunni Motor Work Pte Ltd
10 Ang Mo Kio Industrial Park 2A
#03-19 AMK AutoPoint
Singapore 568047

Tel : 6483-6016 (Claims)

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

 Save the trees - Do you really need to print this e-mail?

On Friday, 13 March 2020, 8:27:58 am SGT, Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$23,500.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chunni motor Work <chunnimw@yahoo.com.sg>
Sent: Thursday, 12 March 2020 4:47 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Re: [EXTERNAL] Re: ACCIDENT INVOLVING SHA 1666 Y & SDL 139 Z ON 06-12-2019

Hi Hsiao Tong,

We refer to the below email from Lionel Tan from M/s FWD Singapore Pte Ltd.

Kindly look into this matter and revert with your offer of an amicable settlement as soon as possible.

Thank you.

Best Regards

William

Claims Department.

Chunni Motor Work Pte Ltd

10 Ang Mo Kio Industrial Park 2A

#03-19 AMK AutoPoint

Singapore 568047

Tel : 6483-6016 (Claims)

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this

message or any delay in delivery which may arise as a result of Internet transmission or any modification.



Save the trees - Do you really need to print this e-mail?

On Wednesday, 11 March 2020, 6:06:59 pm SGT, Lionel Tan Tian Pei - SGUser <lionel.tan@fwd.com> wrote:

Hi William,

Please follow up with surveyor, LKK

From: Chunni motor Work <chunnimw@yahoo.com.sg>
Sent: Wednesday, March 11, 2020 4:40 PM
To: Lionel Tan Tian Pei - SGUser <lionel.tan@fwd.com>
Subject: [EXTERNAL] Re: ACCIDENT INVOLVING SHA 1666 Y & SDL 139 Z ON 06-12-2019

Your Ref : SDL 139 Z
Our Ref : SHA 1666 Y (061219)

WITHOUT PREJUDICE

Dear Lionel,

We refer to our below emails.

Kindly revert with your offer of an amicable settlement soonest possible.

Thank you.

Best Regards
William
Claims Department

Chunni Motor Work Pte Ltd
10 Ang Mo Kio Industrial Park 2A
#03-19 AMK AutoPoint
Singapore 568047

Tel : 6483-6016 (Claims)


DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

 Save the trees - Do you really need to print this e-mail?

On Wednesday, 19 February 2020, 11:01:38 am SGT, Chunni motor Work <chunnimw@yahoo.com.sg> wrote:

Your Ref : SDL 139 Z
Our Ref : SHA 1666 Y (061219)

WITHOUT PREJUDICE

Dear Lionel,

We refer to our below emails.

Kindly expedite this matter and revert with your offer of an amicable settlement as soon as possible.

Thank you.


Best Regards
William
Claims Department

Chunni Motor Work Pte Ltd
10 Ang Mo Kio Industrial Park 2A
#03-19 AMK AutoPoint
Singapore 568047

Tel : 6483-6016 (Claims)

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

 Save the trees - Do you really need to print this e-mail?

On Monday, 3 February 2020, 10:19:07 am SGT, Chunni motor Work <chunnimw@yahoo.com.sg> wrote:

GENTLE REMINDER

On Thursday, 16 January 2020, 1:40:52 pm SGT, Chunni motor Work <chunnimw@yahoo.com.sg> wrote:

Your Ref : SDL 139 Z
Our Ref : SHA 1666 Y (061219)

WITHOUT PREJUDICE

Dear Lionel,

We refer to your email of 09-12-2019 refers,

We had on 09-01-2020 submitted our client's Letter of Demand together with all the necessary supporting documents inclusive the Video footage.

From the Video footage, the liability is clear.

This is a Direct Settlement, kindly reciprocate to expedite this matter and revert with your offer of an amicable settlement as soon as possible.

Thank you.

Best Regards
William
Claims Department

Chunni Motor Work Pte Ltd
10 Ang Mo Kio Industrial Park 2A
#03-19 AMK AutoPoint
Singapore 568047

Tel : 6483-6016 (Claims)

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.



Save the trees - Do you really need to print this e-mail?

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Our Ref : SHA 1666 Y (061219)

Your Ref : SDL 139 Z (FWD)

Date : 16-03-2020

M/s LKK Auto Consultants Pte Ltd
Blk 51 Paya Ubi Industrial Park
#02-25 Ubi Avenue 1
Singapore 408933

WITHOUT PREJUDICE

Attention : Hsiao Tong
Case Handler

Dear Sir/Madam,

**ACCIDENT INVOLVING SHA 1666 Y, SDL 139 Z & OTHERS ALONG TPE TOWARDS
SLE AFTER PUNGGOL EXIT ON 06-12-2019**

Your email of 13-03-2020 refers.

Strictly on a without prejudice basis and without any admission of liability, we confirm settlement for our client's property damage claim (Cost of repair, GIA search fee and the Loss of rental & income during the period of repair) at a global sum of \$23,500.00.

Please note that the settlement reached is strictly for the aforesaid property damage claim only and is without prejudice to the relief driver of SHA 1666 Y, Teng King Guan's injury and other losses against your principals. M/s FWD Singapore Pte Ltd and /or their insured through his own solicitor.

As requested, we return the attached Discharge Voucher duly executed for your kind attention.

Kindly expedite payment and forward us your cheque for the settlement sum of **\$23,500.00** made in favour of **M/s Chunni Motor Work Pte Ltd** as soon as possible.

Thank you.

Yours faithfully,

For **CHUNNI MOTOR WORK PTE LTD**

Claims Department

Enc

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Dec 2019 Edit Reg		09 Dec 2019 00:00 Edit Adj Rpt	\$20,000.00 Edit Estimates	\$20,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	KHOO MIA SONG , ID: 56834603G								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHA1666Y	Date of Loss:	06/12/2019 08:00 - :59 [29 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900038703	Policy/Cover Note No.:	PNCV2019-00001294 (Comprehensive) Coverage: 20/09/2019 - 19/09/2020						
Vehicle Reg. No. (Insured):	SDL139Z	Policy No. (Claimant):	D-18088936MFSH						
Repairer:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 26/12/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> FWD_SG (10/03/2020): Alert - Adj Mandate Approved (\$23506.80) - SHA1666Y - Claim Handler: Lionel Tan 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHA1666Y (1201900038703)
[SDL139Z]

TP

COMFORT TRANSPORTATION PTE LTD

Dec 6 2019 8:00AM

[KHOO MIA SONG]

























































Chunni Motor Work Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser	
Letters/Correspondences									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit						
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	24/12/19 15:23	Adjuster Immediate Advice	1	Load HTM						
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	04/01/20 12:32	Front View Right	1	Load JPG	<input checked="" type="checkbox"/>					
2	04/01/20 12:32	Front View Left	1	Load JPG	<input checked="" type="checkbox"/>					
3	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
4	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
5	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
6	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
7	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
8	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
9	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
10	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
11	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
12	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
13	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
14	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
15	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
16	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
17	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
18	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
19	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
20	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
21	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
22	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
23	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
24	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
25	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
26	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
27	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
28	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
29	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
30	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
31	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
32	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
33	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
34	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
35	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					
36	04/01/20 12:35	General View	1	Load JPG	<input checked="" type="checkbox"/>					

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
37	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
38	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
39	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
40	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
41	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
42	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
43	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
44	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
45	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
46	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
47	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
48	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
49	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
50	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
51	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
52	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
53	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
54	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
55	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
56	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
57	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
58	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
59	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
60	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
61	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
62	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
63	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
64	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
65	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
66	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
67	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
68	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
69	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
70	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
71	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
72	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
73	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
74	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
75	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
76	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
77	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
78	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
79	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
80	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
81	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
82	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
83	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
84	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
85	04/01/20 12:35	General View		Load JPG <input checked="" type="checkbox"/>
86	04/01/20 12:35	Rear View Right		Load JPG <input checked="" type="checkbox"/>
87	04/01/20 12:35	Rear View Left		Load JPG <input checked="" type="checkbox"/>
88	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
89	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
90	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
91	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
92	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
93	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
94	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
95	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
96	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
97	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
98	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
99	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
100	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
101	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
102	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
103	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
104	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
105	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
106	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
107	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
108	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
109	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
110	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
111	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
112	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
113	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
114	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
115	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
116	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
117	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
118	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
119	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
120	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
121	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
122	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
123	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
124	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
125	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
126	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
127	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
128	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
129	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
130	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
131	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
132	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
133	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
134	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
135	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
136	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
137	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
138	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
139	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
140	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
141	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
142	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
143	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
144	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
145	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
146	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
147	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>
148	04/01/20 12:37	General View		Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
149	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
150	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
151	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
152	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
153	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
154	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
155	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
156	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
157	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
158	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
159	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
160	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
161	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
162	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
163	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
164	04/01/20 12:37	General View		<input checked="" type="checkbox"/>
165	04/01/20 12:38	Odometer Reading		<input checked="" type="checkbox"/>
166	04/01/20 12:38	Chassis Number		<input checked="" type="checkbox"/>
167	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
168	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
169	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
170	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
171	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
172	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
173	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
174	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
175	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
176	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
177	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
178	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
179	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
180	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
181	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
182	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
183	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
184	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
185	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
186	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
187	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
188	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
189	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
190	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
191	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
192	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
193	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
194	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
195	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
196	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
197	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
198	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
199	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
200	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
201	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
202	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
203	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>
204	04/01/20 12:39	Reinspection Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
205	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
206	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
207	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
208	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
209	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
210	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
211	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
212	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
213	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
214	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
215	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
216	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
217	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
218	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
219	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
220	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
221	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
222	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
223	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
224	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
225	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
226	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
227	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
228	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
229	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
230	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
231	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
232	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
233	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
234	04/01/20 12:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
235	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
236	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
237	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
238	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
239	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
240	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
241	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
242	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
243	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
244	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
245	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
246	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
247	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
248	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
249	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
250	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
251	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
252	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
253	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
254	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
255	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
256	04/01/20 12:40	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
257	04/01/20 12:40	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
258	04/01/20 12:40	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
259	04/01/20 12:40	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
260	04/01/20 12:40	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
261	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>
262	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>
263	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>
264	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>
265	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>
266	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>
267	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>
268	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>
269	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>
270	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>
271	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>
272	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>
273	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>
274	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>
275	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>
276	04/01/20 12:40	After Repair Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/12/19 16:14	TP GIA REPORT		<input type="checkbox"/>
2	16/12/19 16:14	EMAIL FROM FWD DD 16.12.19		<input type="checkbox"/>
3	16/12/19 16:14	OI GIA REPORT		<input type="checkbox"/>
4	26/12/19 09:45	TP ESTIMATE - MARKED		<input type="checkbox"/>
5	19/03/20 10:03	WORKSHOP INVOICE		<input type="checkbox"/>
6	19/03/20 10:03	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
7	19/03/20 10:03	Release Voucher		<input type="checkbox"/>
8	19/03/20 10:03	RENTAL RECEIPT		<input type="checkbox"/>
9	19/03/20 10:03	RENTAL MILEAGE		<input type="checkbox"/>
10	19/03/20 10:03	LOD		<input type="checkbox"/>
11	19/03/20 10:03	GIA SEARCH		<input type="checkbox"/>

No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	17/01/20 11:55	LOD		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 30px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SDL139Z (Insd veh)	Model:	TOYOTA PRIUS 1.8 HYBRID CVT (A)
	SHA1666Y (TP veh)		
Date of Accident:	06/12/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	50,791.05
Final Repair Cost	:	\$	23,500.00
Loss of Income	:	\$	12.00 days at \$50.00 per day
Rental (if any)	:	\$	12 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	23,500.00

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ 100 _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	Chunni Motor Work Pte Ltd	\$ 23,500.00
2)		\$
3)		\$
4)		\$
5)		\$

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

19 Mar
2020
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199507198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19022104/DPA3Q2
Date: 19/03/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNCV2019-00001294
Claimant
Vehicle No : SHA1666Y **Insured Vehicle No :** SDL139Z
Date of Loss: 06/12/2019 **Nature of Claim:** TP **Claim No:** 1201900038703

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA1666Y**
 Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZRS054842
 Reg. Date: 29/06/2017 (Man. Year: 2017) Chassis No: JTDKB3FU803560989
 Colour: Blue Odometer: 329142 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Davanti 5 mm Rear Left Side: Davanti 5 mm
 Front Right Side: Davanti 5 mm Rear Right Side: Davanti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,548.27	23,233.31	16,314.96	41.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,920.00	3,640.00	4,280.00	54.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	47,468.27	26,873.31	20,594.96	43.39
Approved Total (Overridden) (S\$)		20,000.00		
(S\$)	47,468.27	20,000.00	27,468.27	57.87
+ GST 7.00/7.00% (S\$)	3,322.78	1,400.00	1,922.78	57.87
Nett Amount (S\$)	50,791.05	21,400.00	29,391.05	57.87
+ Loss of Use (12.0 x S\$50.00/day) (S\$)		600.00		
+ Car Rental (12.0 x S\$125.40/day) (S\$)		1,504.80		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		23,506.80		
Global Sum Settlement (S\$)		23,500.00		

INSPECTION

Date of Assignment: 09/12/2019
 Date Inspected: 09/12/2019 Inspected At: Chunni Motor Work Pte Ltd (HQ)
 Blk 10 Ang Mo Kio Industrial Park 2A,
 #03-19 AMK Autopoint
 Singapore 568047

Estimated Period of Repair: 12.0 days

Adjuster: BRYAN TANI

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Feb 2020)
Parts: 144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHA1666Y)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	950.50 FL	*950.50 FL
2	1		*INSULATOR ,HOOD	Not Necessary	398.10 FL	*- FL
3	2		*BONNET HINGE (LH/RH)	Not Necessary	115.40 FL	*- FL
4	1		*BONNET LOCK	Not Necessary	132.60 FL	*- FL
5	1		*RADIATOR GRILLE	Broken	438.00 FL	*438.00 FL
6	1		*RADIATOR GRILLE EMBLEM	Bent	88.00 FL	*88.00 FL
7	1		*LAMP ASSY ,FOG, RH	Not Necessary	920.00 FL	*- FL
8	1		*LAMP ASSY ,FOG, LH	Not Necessary	920.00 FL	*- FL
9	1		*FRONT BUMPER COVER	Dented	499.90 FL	*499.90 FL
10	1		*FRONT BUMPER REINFORCEMENT	Broken	696.40 FL	*696.40 FL
11	1		*FRONT BUMPER REINFORCEMENT ABSORBER	Dented	115.70 FL	*115.70 FL
12	1		*FRONT BUMPER SPONGE	Torn	78.80 FL	*78.80 FL
13	1		*FRONT BUMPER CENTRE GRILLE	Deformed	301.90 FL	*301.90 FL
14	1		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
15	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	154.00 FL	*- FL
16	1		*FRONT BUMPER TOP GARNISH	Serviceable	225.40 FL	*- FL
17	1		*COVER ,FRONT BUMPER HOLE, RH	Distorted	28.38 FL	*28.38 FL
18	1		*COVER ,FRONT BUMPER HOLE, LH	Repair	28.38 FL	*- FL
19	1		*FRONT BUMPER CENTRE FRAME	Not Necessary	236.90 FL	*- FL
20	1		*BRACKET ,FRONT BUMPER SIDE, RH	Not Necessary	82.30 FL	*- FL
21	1		*BRACKET ,FRONT BUMPER SIDE, LH	Not Necessary	82.30 FL	*- FL
22	1		*UNIT ASSY ,HEADLAMP ,RH (LED)	Mtg Broken	3,455.00 FL	*3,455.00 FL
23	1		*UNIT ASSY ,HEADLAMP ,LH (LED)	Mtg Broken	3,455.00 FL	*3,455.00 FL
24	1		*HEAD LAMP PANEL (RH)	Bent	240.10 FL	*240.10 FL
25	1		*HEAD LAMP PANEL (LH)	Bent	240.10 FL	*240.10 FL
26	1		*TOP PANEL CENTRE	Bent	364.90 FL	*364.90 FL
27	1		*TOP PANELSIDE ,LH	Bent	145.90 FL	*145.90 FL
28	1		*TOP PANELSIDE ,RH	Bent	145.90 FL	*145.90 FL
29	1		*BRACE PANEL	Bent	75.20 FL	*75.20 FL
30	1		*RADIATOR ASSY	Bent / Punctured	1,841.80 FL	*1,841.80 FL
31	1		*RADIATOR FAN COWLING ASSY	Not Necessary	661.30 FL	*- FL
32	1		*RADIATOR BOTTOM MOUNTING	Not Necessary	27.50 FL	*- FL
33	1		*STAY ,BRACKET SUPPORT ,RH	Not Necessary	65.70 FL	*- FL
34	1		*STAY ,BRACKET SUPPORT ,LH	Not Necessary	65.70 FL	*- FL
35	1		*RADIATOR FAN BLADE (RH)	Not Necessary	233.10 FL	*- FL
36	1		*RADIATOR FAN BLADE (LH)	Not Necessary	233.10 FL	*- FL
37	1		*RADIATOR FAN MOTOR (RH)	Not Necessary	543.70 FL	*- FL
38	1		*RADIATOR FAN MOTOR (LH)	Not Necessary	543.70 FL	*- FL
39	1		*DEFLECTOR ,RADIATOR SIDE, RH	Bent / Deformed	83.50 FL	*83.50 FL
40	1		*DEFLECTOR ,RADIATOR SIDE, LH	Not Necessary	77.00 FL	*- FL
41	2		*HORN	Not Necessary	225.42 FL	*- FL
42	1		*CLEANER ASSY ,AIR	Dented /Cracked	970.30 FL	*970.30 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*AIR DUCT	Broken / Damaged	129.40 FL	*129.40 FL
44	1		*INLET ASSY ,AIR CLEANER	Not Necessary	132.00 FL	*- FL
45	1		*AIR DUCT CENTRE	Not Necessary	94.03 FL	*- FL
46	1		*CONDENSER ASSY ,W/RECEIVER	Bent / Punctured	1,336.60 FL	*1,336.60 FL
47	1		*WIRING FRONT	Not Necessary	6,685.90 FL	*- FL
48	1		*REAR TRUNK LID COVER	Buckled	1,126.60 FL	*1,126.60 FL
49	1		*REAR TRUNK LID LOCK	Damaged	457.90 FL	*457.90 FL
50	1		*REAR TRUNK LID COVER TRIM BOARD	Broken	254.40 FL	*254.40 FL
51	1		*REAR TRUNK LID RUBBER	Deformed	365.20 FL	*365.20 FL
52	1		*REAR TRUNK LID GLASS (BLACK COLOR)	Shattered	1,569.70 FL	*1,569.70 FL
53	1		*GARNISH SUB-ASSY ,BACK DOOR OUTSIDE	Broken	889.70 FL	*889.70 FL
54	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	52.90 FL	*52.90 FL
55	1		*REAR TRUNK LID LOGO (HYBRID)	Necessary	52.90 FL	*52.90 FL
56	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Necessary	47.00 FL	*47.00 FL
57	1		*REAR BUMPER	Dented / Torn	458.60 FL	*458.60 FL
58	1		*REAR BUMPER REINFORCEMENT	Dented	318.80 FL	*318.80 FL
59	1		*REAR BUMPER UNDER COVER	Broken / Dented	552.60 FL	*552.60 FL
60	2		*REAR BUMPER SIDE RETAINER	Not Necessary	225.40 FL	*- FL
61	1		*REAR BUMPER UNDER SIDE COVER (RH)	Dislodged / Broken	232.00 FL	*232.00 FL
62	1		*REAR BUMPER UNDER SIDE COVER (LH)	Dislodged / Broken	232.00 FL	*232.00 FL
63	1		*REAR BUMPER UNDER SIDE CENTRE COVER	Dislodged / Broken	552.60 FL	*552.60 FL
64	1		*REAR BUMPER TOWING COVER	Deformed / Dislodged	82.70 FL	*82.70 FL
65	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
66	1		*ARM SUB-ASSY ,REAR BUMPER ,RH	Not Necessary	139.60 FL	*- FL
67	1		*ARM SUB-ASSY ,REAR BUMPER ,LH	Not Necessary	139.60 FL	*- FL
68	1		*SEAL ,REAR BUMPER SIDE, RH	Dislodged / Broken	148.40 FL	*148.40 FL
69	1		*SEAL ,REAR BUMPER SIDE, LH	Dislodged / Broken	148.40 FL	*148.40 FL
70	2		*TAIL LAMP ASSY (UPPER) (LH/RH)	Cracked / Mtg Cracked	1,115.80 FL	*1,115.80 FL
71	2		*TAIL LAMP ASSY (LOWER) (LH/RH)	Cracked / Mtg Cracked	1,096.80 FL	*1,096.80 FL
72	1		*REAR END PANEL	Broken	602.10 FL	*602.10 FL
73	1		*REAR END PANEL GARNISH	Deformed	165.80 FL	*165.80 FL
74	1		*REAR SPARE TYRE PANEL	Buckled	667.70 FL	*667.70 FL
75	1		*REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	Not Necessary	750.00 FL	*- FL
76	1		*3RD BRAKE LIGHT	Not Necessary	198.00 FL	*- FL
77	1		*FIBER TOOLS BOX TRAY	Broken	398.00 FL	*398.00 FL
78	1		*REAR EXHAUST PIPE	Not Necessary	1,163.40 FL	*- FL
79	1		*REAR EXHAUST PIPE HANGER	Not Necessary	40.70 FL	*- FL
80	1		*REAR EXHAUST PIPE INSULATOR	Bent	314.60 FL	*314.60 FL
81	1		*REAR FENDER ,LH	Dented	836.70 FL	*836.70 FL
82	1		*REAR FENDER AIR DUCT	Not Necessary	165.10 FL	*- FL
83	1		*REAR CHASSIS MEMBER	Not Necessary	1,180.80 FL	*- FL
84	1		*REAR WINDSCREEN GLASS WITH MOULDING	Shattered	1,778.30 FL	*1,778.30 FL
85	1		*REAR WIRING ASSY	Not Necessary	582.40 FL	*- FL
86	1		*SPOILER SUB-ASSY ,REAR	Not Necessary	953.70 FL	*- FL
87	1		*FRONT NO .PLATE }	Bent	25.00 FS	*45.00 FS
88	1		*FRONT NO.PLATE TRIM COVER }	Broken	30.00 FS	*- FS
89	1		*FRONT NO.PLATE GARNISH	Broken	99.00 FS	*99.00 FS
90	1		*REAR NO.PLATE WITH TRIM COVER	Bent	100.00 FS	*45.00 FS
91	1		*REAR TRUNK LID APPS STICKER	Necessary	40.00 FS	*40.00 FS
92	1		*REAR TRUNK LID COMFORT & TEL NO.STICKER	Necessary	60.00 FS	*60.00 FS
93	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
94	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
95	1		*REAR DOOR COMFORT & APPS STICKER ,LH	Necessary	80.00 FS	*80.00 FS
<small>F=Franchise part. S=SpcNeff. L=ListItemDisc.</small>						
Sub Total (S\$)					49,281.41	30,794.18
- List Item Discount on L Items 20.00/25.00% (S\$)					9,733.14	7,560.87
Total Parts (S\$)					39,548.27	23,233.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	3,200.00	1,800.00
2	SPRAY PAINTING CHARGE	New	2,500.00	1,400.00
3	WIRING CHARGE	New	100.00	60.00
4	TOWING CHARGE	New	90.00	0.00
5	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
6	REMOVE/REFIX ENGINE	New	450.00	0.00
7	DIAGNOSIS & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
8	TUFF KOTE	New	100.00	40.00
9	FRONT CHASSIS ALIGNMENT CHARGE	New	200.00	0.00
10	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
11	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
12	REMOVE/REFIX REVERSE SENSOR	New	80.00	40.00
13	REMOVE/REFIX FUEL TANK	New	150.00	0.00
14	REMOVE/REFIX EXHAUST PIPE	New	150.00	60.00
Gross Labour Cost (S\$)			7,920.00	3,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >