

ASS. REC. BY:

REF: CS/CTI 19022114 / GAF302

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): Ivan Tai

of CTI

Date/Time: 16.12.19 3:55p.m

Estimated Cost:

Bill to:

OD TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.: SKX 3790B

Insured: GBJ 6609D

at Workshop m/s Borneo motor

Tel: 9847609

of Tub Road 4

Policy No:

Claim No: SVM 19D 205 895

Sum Insured:

Excess:

Make of Veh:

D.O.A. 9.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Employment:

Date/Time: 16.12.19 4.47p.m

Person Contacted: Sam

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKX 3790B - x
	GBJ 6609D - x
	Part by Part \$114,810.60 (red: 3582.26, 19%)

Summer Lee (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Monday, 16 December, 2019 3:55 PM
To: SanJoi.Sam@borneomotors.com.sg; assignments; Admin A
Cc: Chong Boon Sen; Lim Shu Min
Subject: RE: OUR REF: SNM19D205895/GBJ6609D/CBS - FW: arrange direct settlement survey for vehicle SKX3790B

Dear Sir(LKK),

We refer to the above matter .

Please get your surveyor to liaise with BORNEO MOTOR to conduct survey.

Note: My colleague, Boon Sen is on MC today. I will get him to input details in MERIMEN tomorrow.

Regards,

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Monday, December 16, 2019 3:16 PM

To: Irene Tay <irene.tay@sg.cntaiping.com>

Subject: FW: OUR REF: SNM19D205895/GBJ6609D/CBS - FW: arrange direct settlement survey for vehicle SKX3790B

Thank You.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Sam San Joi UBI [<mailto:SanJoi.Sam@borneomotors.com.sg>]

Sent: Monday, 16 December, 2019 10:43 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: Re: OUR REF: SNM19D205895/GBJ6609D/CBS - FW: arrange direct settlement survey for vehicle SKX3790B

Dear boon Sen,

Car already in workshop and ready for survey.

Thanks you

Sam

98476209

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Sent: Monday, 16 December 2019 10:24 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Sam San Joi UBI <SanJoi.Sam@borneomotors.com.sg>

Subject: OUR REF: SNM19D205895/GBJ6609D/CBS - FW: arrange direct settlement survey for vehicle SKX3790B

CAUTION: This email originated from outside of the organization (Inchcape). Do not click links or open attachments unless you recognise the sender and know the content is safe.

Dear Sir,

Please note that officer in charge – Boon Sen.

Dear Boon Sen,

Fya

***** Kindly quote our reference number when replying.**

Thank You.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Sam San Joi UBI [<mailto:SanJoi.Sam@borneomotors.com.sg>]

Sent: Friday, 13 December, 2019 4:17 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: arrange direct settlement survey for vehicle SKX3790B

Dear officer,

Kindly arrange to survey the vehicle on Monday(16/12/2019) at Borneo Motors Ubi Centre.

Address: 17 Ubi Road 4 S408611.

Thanks you
Sam

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	290A
Vehicle No.:	SKX3790B
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Beige
Manufacturing Year:	2015
Engine No.:	2ZR1630175
Chassis No.:	JTDGG20W70J003014
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$23,454.00
Original Registration Date:	09 Dec 2015
First Registration Date:	09 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$24,836.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Dec 2025
PARF Rebate Amount:	\$18,627.00
COE Expiry Date:	08 Dec 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,190.00
COE Rebate Amount:	\$34,780.00
Total Rebate Amount:	\$53,407.00

The information contained herein is correct as at 16 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2019 13:27
Date Of Accident	09/12/2019 10:45
Exact Location Of Accident	AIRPORT ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX3790B
Insured/Policyholder	
Name Of Registered Owner	TIEN SOON HOE (CHENG SHUNHE)
NRIC No	S7137290A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91450289
Alternative Phone No	OTHERS-91450289

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ALLIANZ GLOBAL CORPORATE & SPECIALTY SE - SINGAPORE BRANCH
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SGV000009316191-0001
Cover Note Number	09.12.2019 TO 08.12.2020

Driver

Name of Driver	TIEN SOON HOE (CHENG SHUNHE)
NRIC No	S7137290A
Date Of Birth	24/09/1971
Occupation	OUTDOOR
Date Of Driving Pass	02/10/1989
Driving Experience	30 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91450289
Fax Number	
Contact Number	OTHERS-91450289

E-Mail Address	NOEMAIL
Address	BLOCK 310B PUNGGOL WALK #12-558
Postcode	822310
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 09.12.2019 at about 1045hrs, I stopped my vehicle (A: SKX3790B) on the centre lane along Airport Road towards Eunos Link due to traffic light was red. Suddenly, an impact from my vehicle's rear portion and discovered that a vehicle (B: GBJ6609D) had hit into rear portion of my vehicle. Nobody was injured in this accident.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ6609D
Vehicle Make/Model/Colour	TOYOTA DYNA
Details Of Properties	LORRY
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	VEERAAIAH BOOMINATHAN
NRIC/Passport Number	G2227223W
Contact Number	9466 5889
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to CIA report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Anthony Ben
Policyholder's Signature
Date & Time: 10/12/14
01545hr

Driver's Signature
(if driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name: Ron Wai Shing
NRIC/FIN NO.: SAKK3701

at / L...
CS
24

Allianz Global Corporate & Specialty SE Singapore Branch

Company Registration No. : T11FC0131K
Address : 12 Marina View, #14-01 Asia Square Tower 2, Singapore 018961
Tel : +65. 6297 2529 Fax : +65. 6297 1956
Website : http://www.agcs.allianz.com



Allianz Contact Centre
Tel : 1800 222 1818 or 65 6222 1919
Email : customerservice@allianz.com.sg

PRIVATE CAR SCHEDULE

TIEN SOON HOE (CHENG SHUNHE)

#12-558
310B PUNGGOL WALK
SINGAPORE 822310

Policyholder Name	: TIEN SOON HOE (CHENG SHUNHE)	Product Type	: ALLIANZ MOTOR PROTECT
Occupation	: OUTDOOR	Form	: MX1
Replacing Covering Note No.	: NA	Account Code	: SCB0000011
Policy No.	: SGV0000936191	Issue Date	: 08 NOVEMBER 2019
Period of Insurance	: From 09 DEC 2019 To 08 DEC 2020		
Premium before GST	: SGD 779.68		
GST (7%)	: SGD 54.58		
Total Premium Payable	: SGD 834.26		
Insurance Cover	: COMPREHENSIVE	Off-Peak Car	: N
Agreed Value	: MARKET VALUE	Good Driver Discount	: Y
Registration No.	: SKX3790B	Seating Capacity	: 7
Make and Model	: TOYOTA Wish ZGE20 Wagon 5dr 7st CVT 7sp FWD 1.8i (Standar	Body Type	: WAGON
Year of Manufacture	: 2015	Engine No.	: 2ZR1630175
Engine Capacity	: 1798 CC	WindScreen	: UNLIMITED
Chassis No.	: JTDGG20W70J003014	No Claim Discount	: 50 %
Hire Purchase Owner	: -		
Optional Coverage	: ANY WORKSHOP PA & MEDICAL EXPENSES		

Named Drivers

1. TIEN SOON HOE (CHENG SHUNHE)

Limitations as to Use*

Used only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

- (a) use for hire or reward
- (b) use for racing, pace-making, reliability trials or speed testing
- (c) use for the carriage of goods (other than samples) in connection with any trade or business
- (d) use for any purposes in connection with the Motor Trade

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	Mr Tien Soon Hoe (Cheng Shunhe) 310B Funggol Walk #12-558 Singapore 822310 Mobile: 91450289	
		Document No		
		0		
		Document Date		
		16/12/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S5	09/12/2015	SKX3790B	0	19499	67/DS/SKX3790B
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDGG20W70J003014	2ZR1630175	60	Sam San Joi	10/12/2019	15.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS ⁷²⁰				2880 3600.00
		STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				
13	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR ^{580 590}				2360 3540.00
		EAS				
14	1	T52159-68907 REAR BUMPER COVER, / bc	1.00	591.80		591.80
15	2	T52576-68020 L/R SIDE BPR RETAINER,	1.00	46.00		46.00
16	3	T52156-68030 L/RR BUMPER SUPPORT, / bc	1.00	97.40		97.40
17	4	T52575-68020 R/R SIDE BPR RETAINER	1.00	46.00		46.00
18	5	T52155-68030 R/RR BUMPER SUPPORT	1.00	97.40		97.40
19	6	S52161-0K040 CLIPS / Mc	10.00	4.10		41.00
20	7	T58307-68031 REAR LOWER FLR PANEL, X 68031	1.00	536.70		536.70
21	8	T52181-68010 ARM, RR BUMPER X	2.00	53.80		107.60
22	9	T57655-68010 REAR FLOOR MEMBER 2, X	1.00	110.50		110.50
23	0	T57666-68010 L/R LWR BACK PANEL, X	1.00	58.80		58.80
24	1	T58035-68010 R/RR FLOOR EXTENSION, X	1.00	93.90		93.90
25	2	T67935-68020 BO PLATE BACK DOOR	1.00	298.00		298.00
26	3	T67005-68041 PANEL ASSY, BACK DOOR / bnc	1.00	1477.30		1477.30
27	4	T67881-68030 WEATHERSTRIP, BACK	1.00	335.70		335.70
28	5	T68105-68071 REAR BACK DOOR GLASS, / Mc	1.00	1065.90		1065.90
29	6	T04562-12010 FRT W/SCREEN DAM KIT, /	1.00	121.00		121.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle _____	Parts	Amount Due
		Labour	
		Materials	
		Lubrication/Fluid	Less
		Others	

PLEASE TEAR ALONG PERFORATED LINE

4038565

TO SECURITY GUARD

4038565

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE 16/12/2019
 TIME 17:08

VEHICLE NO SKX3790B

CUSTOMER

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD


Borneo Motors

Incharge

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Tien Soon Hwe (Cheng Shunhe) 310B Punggol Walk #12-550 Singapore 822310 Mobile: 91450289		
		Document No			0
		Document Date			16/12/2019

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S5	09/12/2015	SKX3790B	0	19499	67/DS/SKX3790B
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDGG20W70J003014	22R1630175	60	Sam San Joi	10/12/2019 15.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	7	T21000-20	SIKA 182010 SIKA TACK GOI (BLA	2.00	108.00	✓ 216.00
31	8	T21000-22	SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00	✓ 200.00
32	9	T67750-68020 B1	REAR BACK DOOR BOARD, X	1.00	363.70	✓ 363.70
33	0	T74811-13010 C2	HANDLE, DOOR PULL X	1.00	23.00	✓ 23.00
34	1	T69350-28151	LOCK ASSY, BACK DOOR	1.00	412.70	✓ 412.70
35	2	T69430-28050	STRIKER ASSY, BACK X	1.00	40.90	✓ 40.90
36	3	T90975-02086	FRONT BONNET EMBLEM,	1.00	72.20	✓ 72.20
37	4	T75444-68010	PLATE, LUGGAGE COMPT (VALVE MATI	1.00	41.10	✓ 41.10
38	5	T75443-ELGAN	ELEGANCE EMBLEM	1.00	40.00	✓ 40.00
39	6	T76811-68130	GARNISH, BACK DOOR,	1.00	290.30	✓ 290.30
40	7	T75819-33010	CLIP, LUGGAGE	4.00	3.90	✓ 15.60
41	8	T89997-30070	ELECTRICAL ANTENNA,	1.00	192.20	✓ 192.20
42	9	SP2061-12010 27	478 SENSOR	1.00	151.60	✓ 151.60
43	0	T81271-72011	LENS, LICENSE LAMP	2.00	31.00	✓ 62.00
44	1	T81591-68020	LENS & BODY, RR	1.00	294.10	✓ 294.10
45	2	T81581-68020	LENS & BODY, RR	1.00	294.10	✓ 294.10

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

18392.80

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	18,166.50
	Please acknowledge receipt of vehicle	Parts	7,834.50	GST 7.00% Less Amount Due
		Labour	9,772.00	
		Materials	560.00	
		Lubrication/Fluid	0.00	
		Others	0.00	
				19,438.16

PLEASE TEAR ALONG PERFORATED LINE

4038566

TO SECURITY GUARD

4038566

 PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE 16/12/2019
 TIME 17:08

VEHICLE NO SKX3790B

CUSTOMER

 SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Incharge

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

 Online Service Booking :
 www.toyota.com.sg
 Toyota Bodycare Centre
 17 Ubi Road 4
 Singapore 409611
 Tel no.: 6631 1188

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	Mr Tien Soon Hoe (Cheng Shunhe) 310B Punggol Walk #12-55B Singapore 822310 Mobile: 91450289		
		Document No			0
		Document Date			16/12/2019

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S5	3GE20R	09/12/2015	SKX3790B	0	19499 67/DS/SKX3790B
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDGG20W70J003014	2ZR1630175	60	Sam San Joi	10/12/2019	15.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBJ6609D ACC DATE:09/12/2019 DRIVE IN:10/12/2019 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30.00
2	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				180.00
3	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				180.00
4	Z	BP-SLANT SUPPLY SEALANT (HSTPL) - TAILGATE, REAR EN D PANEL				160.00
5	B	BP-LAB2 REMOVE & INSTALL REAR SEAT, CARPET, GARNIS H AND TRIMMING TO ASSIST REPAIR				720.00
6	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS				462.00
7	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM				480.00
8	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA				360.00
9	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE				360.00
10	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
11	S	BP-SUBLET REAR NUMBER PLATE NC				80.00

Handwritten notes:
 8 Days
 18/12/19
 82880282
 before part photos
 16/12/19

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge the following: • To resurvey before water painting • To display damaged parts for survey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from insurance company	Acknowledged by Repairer Signature: _____ DATE: 16/12/2019 TIME: 17:08	Less
			Amount Due
			4038564

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

 VEHICLE NO **SKX3790B**

CUSTOMER

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD


Borneo Motors

Inchope



Online Service Booking:
www.toyota.com.sg
 Toyota Bodycare Centre
 17 Ubi Road #
 Singapore 409611
 Tel no.: 6631 1188

Co Reg No : 196700086Z
 ST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No S1000003 / ICC11	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	Document No 0	Mr Tien Soon Hoe (Cheng Shunhe) 110B Punggol Walk #12-55B Singapore 822310
	Document Date 23/12/2019	Mobile: 91450289

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	S5	09/12/2015	SKX3790B	0	19499	67/DS/SKX3790B

Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On
JTDGG20W70J003014	2ZR1630175	60	Sam San Jol	10/12/2019 15:00	23/12/2019 18:00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	7	T76811-68130 BACK DOOR GARNISH,	1.00	290.30		290.30
31	8	T75819-33010 CLIP, LUGGAGE	4.00	3.90		15.60
32	9	T81591-68020 L/REAR BODY LENS	1.00	294.10		294.10
33	0	T81581-68020 R/REAR BODY LENS	1.00	294.10		294.10
34	1	T58307-68031 PANEL LAMP LOWER	1.00	536.70		536.70
35	2	T89997-30070 ANTENNA, ELECTRICAL	1.00	192.20		192.20
36	3	T76822-68010 BACK DOOR PROTECTOR,	2.00	1.90		3.80
37	4	T75819-33010 REAR BOOT LUGGAGE CLIP	1.00	3.90		3.90
38	5	T76821-68070 PROTECTOR, BACK DOOR	1.00	10.80		10.80
39	6	T76824-68010 L/REAR BACK DOOR PROTECTOR,	1.00	1.90		1.90
40	7	T76823-68010 R/REAR BACK DOOR PROTECTOR,	1.00	1.90		1.90
41	8	T76817-50010 CLIP, BACK DOOR	4.00	2.40		9.60
42	9	T90179-06274 NUT	1.00	2.20		2.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	14,810.60
	Please acknowledge receipt of vehicle	Parts	6,558.60	GST 7.00% 1,036.74 Less 0.00 Amount Due 15,847.34
		Labour	7,692.00	
		Materials	560.00	
		Lubrication/Fluid	0.00	
		Others	0.00	

4038690

4038690

23/12/2019
11:24

SKX3790B



Inchoape

Borneo Motors



Borneo Motors (Singapore) Pte Ltd

o Reg No : 196700086Z
ST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking:
www.toyota.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / IOCHI	Mr Tien Soon Hoe (Cheng Shunhe) 310B Punggol Walk #12-55F Singapore 022310 Mobile: 91450289	
		Document No		
		0		
		Document Date		
		23/12/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP S5	ZGE20R	09/12/2015	SKX3790B	0	19499	67/DS/SKX3790B

Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On
JTDGG20W70J0003014	2ZR1630175	60	Sam San Jai	10/12/2019 15.00	23/12/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBJ6609D ACC DATE:09/12/2019 DRIVE IN:10/12/2019 DATE-IN:16/12/2019 DATE SURVEY:16/12/2019 NO OF REPAIR DAYS:8 DAYS BY:GUO QIANG (AXA)				30.00
2	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR *				180.00
3	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST *				180.00
4	Z	BP-SLANT SUPPLY SEALANT (NETT)- TAILGATE, REAR EN D PANEL				160.00
5	B	BP-LAB2 REMOVE & INSTALL REAR SEAT, CARPET, GARNIS H AND TRIMMING TO ASSIST REPAIR *				720.00
6	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS *				462.00
7	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR FM30 ILM				480.00
8	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA *				180.00
9	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE *				360.00
10	B	BP-ECU2 TO RESET ECU AND REPROGRAMME *				180.00
11	S	BP-SUBLET REAR NUMBER PLATE E33				80.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

4038688

4038688


23/12/2019
11:24

SKX3790B



Borneo Motors

WORKSHOP



Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z
 ST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking:
 www.toyota.com.sg
 Toyota Bodycare Centre
 17 Ubi Road 4
 Singapore 409611
 Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	Mr Tien Soon Hoe (Cheong Shunhe) 310a runggol walk #12-558 Singapore 822310 Mobile: 91450289	
		Document No		
		0		
		Document Date		
		23/12/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	HPXNP	SS	09/12/2015	SKX3790B	0	19499	67/DS/SKX3790B
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDGG20W70J003014	2ZR1630175	60	Sam San Joi	10/12/2019 15:00	23/12/2019 18:00		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS	*			2880.00
13	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS	*			2360.00
14	1	T52159-68907 COVER RR BUMPER	1.00	591.80		591.80
15	2	T52576-68020 L/REAR BUMPER RETAINER	1.00	46.00		46.00
16	3	T52156-68030 SUPPORT RR BUMPER LH	1.00	97.40		97.40
17	4	T52575-68020 R/REAR BUMPER RETAINER	1.00	46.00		46.00
18	5	T52155-68030 SUPPORT RR BUMPER RH	1.00	97.40		97.40
19	6	S52161-OK040 PIECE, RE BUMPER	10.00	4.10		41.00
20	7	T67005-68041 PANEL ASSY, BACK DOOR	1.00	1477.30		1477.30
21	8	T67881-68030 REAR BACK DOOR WEATHERSTRIP,	1.00	335.70		335.70
22	9	T68105-68071 BACK DOOR GLASS ASSY	1.00	1065.90		1065.90
23	0	T04562-12010 DAM KIT, WINDOW GLASS	1.00	121.00		121.00
24	1	T21000-20 SIKA 210002-0 TACK GO! (BLACK) SG	2.00	108.00		216.00
25	2	T21000-22 SIKA 210002-2 G+P 207 ADHESIVE PRIM	1.00	200.00		200.00
26	3	T69350-28151 LOCK ASSY, BACK DOOR	1.00	412.70		412.70
27	4	T90975-02086 EMBLEM, SYMBOL	1.00	72.20		72.20
28	5	T75444-68010 PLATE, LUGGAGE COMPT	1.00	41.10		41.10
29	6	T75443-ELGAN ELEGANCE EMBLEM	1.00	40.00		40.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

4038689

4038689

23/12/2019
11:24

SKX3790B

WORKSHOP



Borneo Motors

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119022114/GTF3N2
Date: 14/02/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30521319000
Claimant Vehicle No: SKX3790B Insured Vehicle No: GBJ6609D
Date of Loss: 09/12/2019 Nature of Claim: TP Claim No: SNM19D205895C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX3790B
Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 2ZR1630175
Reg. Date: 09/12/2015 (Man. Year: 2015) Chassis No: JTDGG20W70J003014
Colour: Beige Odometer: 86624 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,170.80	6,668.60	1,502.20	18.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,222.00	8,142.00	2,080.00	20.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,392.80	14,810.60	3,582.20	19.48
+ GST 7.00/7.00% (S\$)	1,287.50	1,036.74	250.76	19.48
Nett Amount (S\$)	19,680.30	15,847.34	3,832.96	19.48

INSPECTION

Date of Assignment: 13/02/2020
Date Inspected: 16/12/2019 Inspected At: Borneo Motors (S) Pte Ltd (Ubi)
17 Ubi Road 4
Singapore 408611
Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Feb 2020)
Parts: M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX3790B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER COVER	Deformed	591.80 FS	*591.80 FS	
2	1		*L/R SIDE BPR RETAINER	Necessary	46.00 FS	*46.00 FS	
3	1		*L/RR BUMPER SUPPORT	Necessary	97.40 FS	*97.40 FS	
4	1		*R/R SIDE BPR RETAINER	Necessary	46.00 FS	*46.00 FS	
5	1		*R/RR BUMPER SUPPORT	Necessary	97.40 FS	*97.40 FS	
6	10		*CLIPS	Necessary	41.00 FS	*41.00 FS	
7	1		*REAR LOWER FLR PANEL	Buckled	536.70 FS	*536.70 FS	
8	2		*ARM RR BUMPER	Not Necessary	107.60 FS	*- FS	
9	1		*REAR FLOOR MEMBER 2	Not Necessary	110.50 FS	*- FS	
10	1		*L/R LWR BACK PANEL	Not Necessary	58.80 FS	*- FS	
11	1		*R/RR FLOOR EXTENSION	Not Necessary	93.90 FS	*- FS	
12	1		*PLATE BACK DOOR	Not Necessary	298.00 FS	*- FS	
13	1		*PANEL ASSY,BACK DOOR	Buckled	1,477.30 FS	*1,477.30 FS	
14	1		*WEATHERSTRIP,BACK	Necessary	335.70 FS	*335.70 FS	
15	1		*FRT W/SCREEN DAM KIT	Necessary	121.00 FS	*121.00 FS	
16	2		*SIKA 182010 SIKA TACK GOI(BLA)	Necessary	216.00 FS	*216.00 FS	
17	1		*SIKA 207.G+P ADHESIVE PRIMER	Necessary	200.00 FS	*200.00 FS	
18	1		*REAR BACK DOOR BOARD	Not Necessary	363.70 FS	*- FS	
19	1		*HANDLE,DOOR PULL	Not Necessary	23.00 FS	*- FS	
20	1		*LOCK ASSY,BACK DOOR	Jammed	412.70 FS	*412.70 FS	
21	1		*STRIKER ASSY,BACK	Not Necessary	40.90 FS	*- FS	
22	1		*FRONT BONNET EMBLEM	Necessary	72.20 FS	*72.20 FS	
23	1		*PLATE,LUGGAGE COMPT (VALVE MATI)	Necessary	41.10 FS	*41.10 FS	
24	1		*ELEGANCE EMBLEM	Necessary	40.00 FS	*40.00 FS	
25	1		*GARNISH,BACK DOOR	Cracked	290.30 FS	*290.30 FS	
26	4		*CLIP,LUGGAGE	Necessary	15.60 FS	*15.60 FS	
27	1		*ELECTRICAL ANTENNA	Not Necessary	192.20 FS	*- FS	
28	1		*4T8 SENSOR	Not Necessary	151.60 FS	*- FS	
29	2		*LENS,LICENSE LAMP	Not Necessary	62.00 FS	*- FS	
30	1		*LENS & BODY,RR	Cut	294.10 FS	*294.10 FS	
31	1		*LENS & BODY,RR	Cut	294.10 FS	*294.10 FS	
32	1		*ANTENNA,ELECTRICAL	Damaged	192.20 FS	*192.20 FS	
33	2		*BACK DOOR PROTECTOR	Necessary	3.80 FS	*3.80 FS	
34	1		*REAR BOOT LUGGAGE CLIPS	Necessary	3.90 FS	*3.90 FS	
35	1		*PROTECTOR,BACK DOOR	Necessary	10.80 FS	*10.80 FS	
36	1		*L/REAR BACK DOOR PROTECTOR	Necessary	1.90 FS	*1.90 FS	
37	1		*R/REAR BACK DOOR PROTECTOR	Necessary	1.90 FS	*1.90 FS	
38	4		*CLIP,BACK DOOR	Necessary	9.60 FS	*9.60 FS	
39	1		*NUT	Necessary	2.20 FS	*2.20 FS	
40	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS	
41	1		*REAR NUMBER PLATE	Necessary	80.00 FS	*80.00 FS	
42	1		*REAR BACK DOOR GLASS	Necessary	1,065.90 FS	*1,065.90 FS	
					Total Parts (\$\$)	8,170.80	6,668.60

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DRILL HOLE & INSTALL REAR REVERSE SENSOR	New	180.00	180.00
2	CHECK LIGHTING & CONDUCT WATER LEAK TEST	New	180.00	180.00
3	REMOVE & INSTALL REAR SEAT,CARPET,GARNISH AND TRIMMING TO ASSIST REPAIR	New	720.00	720.00
4	REPLACE & INSTALL REAR WINDSCREEN GLASS	New	462.00	462.00
5	INSTALL REAR WINDSCREEN GLASS 3M SOLAR FILM	New	480.00	480.00
6	REMOVE & INSTALL REAR REVERSE CAMERA	New	360.00	180.00
7	TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE	New	360.00	360.00
8	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
9	REPLACE REAR ACCIDENT DAMAGED PARTS.STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS	New	3,600.00	2,880.00
10	RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS	New	3,540.00	2,360.00
11	SUPPLY SEALANT-TAILGATE,REAR END PANEL	New	160.00	160.00
Gross Labour Cost (\$\$)			10,222.00	8,142.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >