

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 #01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel 6419 - 3000
 Fax : 6835 - 7416

Quotation

DATE : 18.12.2019
 VEH NO : SLP2586L
 MODEL : Mazda 3
 D O A : 15.12.2019
 YR REF : SLK4366T

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLP2586L (MAZDA 3)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted</i>	1	1,075.00 ✓
2	Rear Bumper Clips <i>re</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>re</i>	2	110.00 ✓
4	Rear Bumper Towing Cover <i>Missing</i>	2	68.00 ✓
5	Rear Bumper Reinforcement <i>Bent</i>	1	538.00 ✓
6	Rear Bumper Reflector - LH & RH <i>re re</i>	2	230.00 x
7	Rear End Panel <i>Distorted</i>	1	530.00 ✓
8	Rear End Panel Top Garnish <i>Del</i>	1	185.00 ✓
9	Taillamp - LH & RH <i>Cracked</i>	2	1,170.00 ✓
10	Taillamp Panel - LH & RH <i>Reps</i>	2	702.00 +
11	Bootlid <i>Distorted</i>	1	1,005.00 ✓
12	Bootlid Lock <i>Damaged</i>	1	198.00 ✓
13	Bootlid Weatherstripe <i>ut</i>	1	135.00 ✓
14	Bootlid Reflector - LH & RH <i>unl</i>	2	590.00 ✓
15	Bootlid Inner Trim <i>re re</i>	1	195.00 +
16	Bootlid Inner Trim Clips <i>re</i>	1	30.00 ✓
17	Bootlid Hinges - LH & RH <i>Bent</i>	2	292.00 ✓
18	Bootlid Hinges Cover - LH & RH <i>re re</i>	2	68.00 +
19	Mazda Logo <i>?</i>	1	56.00 ✓
20	Mazda 3 Wording <i>re</i>	1	65.00 ✓
21	Sky Activ Emblem <i>?</i>	1	69.00 ✓
22	Rear Fender - LH & RH <i>Reps</i>	2	2,370.00 x
23	Rear Fender Inner Trim - LH & RH <i>re re</i>	2	472.00 +
24	Rear Fender Inner Trim Clips <i>re</i>	1	60.00 ✓
25	Spare Tyre Panel Top Cover <i>Del</i>	1	308.00 ✓
26	Spare Tyre Panel Top Sponge Tray <i>Del</i>	1	252.00 ✓
27	Rear Windscreen Moulding <i>re re</i>	1	168.00 x
28	Rear Exhaust Pipe <i>re re</i>	1	1,075.00 x

RE : ESTIMATE FOR ACCIDENT REPAIR SLP2586L (MAZDA 3)

29 Rear Exhaust Mounting *HP new* 1 42.00 X

6766

5412.80

Less 20%

12,088.00

(2,417.60)

\$ 9,670.40

S/NETT ITEMS

1	Rear Number Plate <i>Best</i>	1	\$	30.00 ✓
2	Rear Number Plate Holder <i>delud</i>	1	\$	30.00 ✓
3	Reverse Sensor <i>Daeng</i>	4	\$	360.00 300
4	Rear End Panel Sealant <i>Xen</i>	1	\$	60.00 ✓
5	Rear Camera <i>HP new</i> 420	1	\$	480.00 X
6	Rear Windscreen Sealant <i>HP new</i>	1	\$	60.00 X

\$ 1,010.00

Total Parts

\$ 10,680.40

5832.80

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,800.00 1400
2	To putty & spray up paint works	\$	1,600.00 1400
3	To check wiring	\$	50.00 30
4	To remove reverse sensor	\$	100.00 60
5	To remove upholstery	\$	150.00 80
6	To remove rear camera 3100	\$	100.00 50
7	To transfer bootlid fittings	\$	150.00 80
8	To remove fuel tank	\$	150.00 X
9	To remove exhaust pipe	\$	150.00 X
10	To remove rear windscreen	\$	180.00 X

Total Labour

\$ 4,430.00

Grand Total

\$ 15,110.40

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN

total: 8932.80

L/S: 7150 ✓

08 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: