

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 22100**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/1470/2019/NS  
**Date** : 13-Dec-19

**Vehicle NOT IN Workshop. Kindly Arrange For Survey.**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Khoo Rongwen (Qiu Yongwen)  
**Address** : 73 Anchorvale Crescent  
#09-07  
Singapore 544661  
**Telephone** : HP +65 96282254  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 1900108509  
**Vehicle No** : **SML 9740 X**  
**Model Code** : Audi A3 Sedan 1.0 TFSI 8V  
**Model / Year** : Jun-17  
**Engine No** : CHZ C27820  
**Chassis No** : WAUZZZ8V0K1025220  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 6-Dec-19  
**Place of Accident** : 7-Dec-19

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SML 9740 X

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00	✓ NEC
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$	1,050.00	500.00 /
3	To respray rear bumper.	\$	900.00	550.00
4	To carry out diagnostic check.	S/N \$	192.00	✓ NEC
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 2,422.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SML 9740 X

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,793.00	DPS ✓
2	REAR BUMPER STICKY PAD	4 \$ 21.00	} NNA
3	REAR BUMPER FIXING PARTS	\$ 175.00	
4	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 30.00	
5	REAR BUMPER LOCKING MECHANISM	2 \$ 53.00	
6	REAR BUMPER SPOILER - LH	\$ 216.00	SCR ✓
7	REAR LIGHT REFLECTOR - LH / RH	2 \$ 76.00	} NNA
8	REAR BUMPER SIDE REINFORCEMENT BEAM	\$ 522.00	
9	REAR BUMPER BRACKET - LH	\$ 25.00	
10	REAR BUMPER BRACKET - RH	\$ 26.00	
11	REAR PARKING AID SENSOR - INNER / OUTER	2 \$ 462.00	
12	REAR PARKING AID SEAL RING	4 \$ 12.00	} ?
13	SUNDRIES	\$ 200.00	
<b>TOTAL SPARE PARTS</b>		<b>: \$ 3,611.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 2,422.00</b>	
<b>GRAND TOTAL</b>		<b>: \$ 6,033.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : TGTm hi  
Surveyed Date : 13/12/19  
Authorised Date :  
Excess Cost : TBA  
Liability :  
Remarks : Not Authorised  
Repair days 3

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant