

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP19-164

Date : 11/12/2019

Vehicle Num. : SGK1313A

Make/Model : Honda Stream-2007

Chassis/Eng# : RN61049220/R18A1754894

Accident Date : 09/12/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 pc	Rear Bumper <i>Rehnd</i>		688.90 ✓
2.	8 pcs	Rear Bumper Clips <i>new</i>	5.50	44.00 ✓
3.	1 pc	Rear Bumper Side Holder RH <i>new</i>		37.90 ✓
4.	1 pc	Rear Bumper Inner Side Shield RH <i>new</i>		61.80 +
5.	1 pc	Rear Fender RH <i>Repair</i>		858.30 +
6.	1 pc	Side Rocker Skirt RH <i>Repair</i>		500.30 *

List TotalS\$:
20.00% Discount S\$:

2,191.20
438.24

1,752.96

SPECIAL NETT ITEMS :				
1.	1 pc	Rear Sport Rim RH <i>ut</i>	420	420.00 ✓
Special Nett Total S\$:				420.00

LABOUR :

To remove, repair and replaced damaged bodyparts,
realign bodyworks & where consistent to the accident

To putty and respray painting on affected area.

Labour Total S\$:

900.00 *400*

850.00 *600*

1,750.00

Total S\$: 3,922.96

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2036.64

2/s: 1.6K

Adrian Lj
4/s 16/12/19
04 Days