

ASS. REC. BY:

REF:

REF: CS/SMD19022160/BYf302

Special instruction:

Surveyor: Lim

ASSIGNMENT (Office)

From (Person):

Grada Teo

of

SMO

Date/Time:

17.12.19 11.189 m

~~Estimated Cost:~~

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 96646

Insured:

SGT 7544M

at Workshop m/s

Team autopilot

Tel:

62581955

of

160 San Ming Dr #101-14

Policy No:

Claim No:

(MTD) 1905836 / GPL

Sum Insured:

Excess:

Make of Vch:

DOA

16.12.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

17.12.19 1.44 p.m.

Person Contacted:

Peach

Vehicle IN / OUT

Date/Time

Action/Instruction

✓

Estimate

SJS 9664G - NA/A2G 18019610/24

DOA - 27/10/2019

SGT 7544M-X



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1905836/GPL

Date: 15 Jan 2020

Our Ref: CS/SMO19022160/Byf3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE PL

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJS9664G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/12/2019 at the premises of M/s TEAM AUTOPRO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>41,272.18</u> .
Revised Estimate Amount	: S\$ <u>23,032.53</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the front & rear o/s body.



Yours faithfully

Lim Teow Guan
Licensed Appraiser

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Wednesday, January 15, 2020 5:32 PM
To: 'Ye, Yong Kang Melvin'
Cc: SUR
Subject: RE: CMTD1905836/GPL - LKK/ 2 Days Notice: SJS9664G(Our Ref) and SGT7544M (Your Ref) Dated 16thDecember 2019
Attachments: SJS9664G PRELI ADVISE.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SJS9664
Date of survey : 17/12/2019
Number of days : 14 days

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnwong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, January 15, 2020 5:08 PM
To: SUR <sur@lkkauto.com>
Subject: FW: CMTD1905836/GPL - LKK/ 2 Days Notice: SJS9664G(Our Ref) and SGT7544M (Your Ref) Dated 16thDecember 2019

"Wishing you a Happy and Prosperous Lunar New Year"



Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 17 December 2019 11:18 AM
To: TeamAutoPro North; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Gnoh, Pau Loong; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1905836/GPL - LKK/ 2 Days Notice: SJS9664G(Our Ref) and SGT7544M (Your Ref) Dated 16thDecember 2019
Attachments: PRS 9664.7544.pdf

Without Prejudice

Our Reference: CMTD1905836/GPL

Your Reference: SJS9664G

Hi Michelle,

We acknowledged receipt of your claim documents.

Please be informed that **Mr. Gnoh Pau Loong** is the handler of this case who can be contacted at 63295 217/ PauLoong.Gnoh@sompo.com.sg.

We will appoint **LKK AUTO** to survey the above vehicle.

Aside to **LKK AUTO**,

Please make the arrangement to survey for **SJS9664G** on a without prejudice basis and revert your report upon completion of survey to my colleague, Mr. Pau Loong.

Thank you.

Our office will be closed on Christmas, New Year's Eve and New Year Day. Business will resume on 26th December 2019 and 2nd January 2020 respectively.

We wish you a Merry Christmas and a Happy New Year!

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: TeamAutoPro North <teamautopl@gmail.com>

Sent: Monday, December 16, 2019 6:56 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: 2 Days Notice: SJS 9664 G(Our Ref) and SGT 7544 M (Your Ref) Dated 16thDecember 2019

Dear Sir/Madam,

Road Traffic Accident Involving SJS 9664 G (Our Ref) and SGT 7544 M (Your Ref)

Dated 16th December 2019, Time around 15:20hrs

@ PIE Jurong after exit 12

We represent our client ; 5M Partners Pte Ltd , to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: SJS 9664 G and your insured's vehicle registration number: SGT 7544 M.

Enclosed herewith a copy of our 2 Days Notice Letter and the relevant Singapore Accident Statement filed for your reference.

For efficiency purpose, we are agreeable with the appointment of **Mr Lim - LKK** as the SJE for subject claim. Please let us know within **2 working days** from today your agreeing to the above otherwise kindly send us your list of at least **ten (10) motor surveyors, via email to the following personnel:-**

Contact Person	Eric Lee	8269 9999
Email Address	teamautopl@gmail.com	
Survey Address	160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722	

Thank you for your attention to this email and we look forward to your earliest reply.

--

The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Cheers,
Michelle Lim

Team AutoPro Pte Ltd
Tel: 6258 1955
Fax: 6258 1956

(Newly Shifted) Main Office: 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722
Workshop/Survey Venue: 160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	126M
Vehicle Details	
Vehicle No.:	SJS9664G
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PICNIC AUTO W/O ROOF RACK
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	1AZH363533
Chassis No.:	JTEGH23B500026976
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$24,216.00
Original Registration Date:	17 Sep 2009
First Registration Date:	17 Sep 2009
Transfer Count:	1
Actual ARF Paid:	\$24,216.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Sep 2024
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$18,971.00
COE Rebate Amount:	\$18,007.00
Total Rebate Amount:	\$18,007.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 18 Dec 2019

OK

Dep 7,580/yr
632/mth

MV 38,800/2
PV 18,007/2
NV 19,993/2

TCM
18/11/19



BIDDED CARPLATE NUMBERS FOR SALE

Find and buy your favourite car plate number here!

START SEARCH NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Renewal COE Toyota Vios 1.5A



2.88% P.A, \$0 Down, \$0 Admin,
Monthly From \$138, 2 Yrs
Warranty Engine n Gearbox
GV Credit [StarAt](#)



Think One Automobile

NEW & USED COMMERCIAL VEHICLES



Browse by Category ▾

« Back (1 2 3 4 5) Next »

Sort by Reg. Date ▾

20 results/page ▾

86 vehicles

Toyota Picnic

Advanced Search: 

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Picnic		Any	Any	> 10 year(s) old	Any	Any	Any	All
	Toyota Picnic	2.0A (New 5-yr COE)	\$36,800	\$7,350 /yr	28-Oct-2009	1,998 cc	103,000 km	MPV	Available
Reliable Toyota MPV With Rear Aircon! Superb Well Maintained, New Paint, Smooth Engine, Easy To Maintain Unit. Price Exclude Booking Fee. Hurry Call Our Friendly Sales Executive For More Information Or Schedule For A Viewing With Us Today Before It's Gone.									
SmartCars Boutique Pte Ltd									
Posted: 16-Dec-2019 Tags: 2009 Toyota Picnic, 2009 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota									
	Toyota Picnic	2.0A (COE till 05/2024)	\$35,800	\$8,040 /yr	28-Oct-2009	1,998 cc	90,000 km	MPV	Available
Well Maintained, Super Low Genuine Mileage Done. Well Groomed Inside Out. No Repairs Needed. Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event Of Emergency. We Provide Loans, Trade In, Insurance And Scrap Services...									
Posted: 16-Dec-2019 Tags: 2009 Toyota Picnic, 2009 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota									
	Toyota Picnic	2.0A (New 10-yr COE)	\$59,800	\$5,980 /yr	27-Oct-2009	1,998 cc	120,000 km	MPV	Available
Only 1 Owner, Full Loan Available. Comes With 6 Months Warranty, Clean And Neat Interior, Trade-In Welcome, Call Now For Test Drive.									
Posted: 14-Dec-2019 Tags: 2009 Toyota Picnic, 2009 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota									
	Toyota Picnic	2.0A (COE till 10/2024)	-	N.A	27-Oct-2009	1,998 cc	-	MPV	SOLD
\$0 Driveaway Plan Available! One Owner, New Leather Seat And Paintwork, Show Room Condition, 100% Loan Available, View To Believe!									
ABWIN (1994) Pte Ltd									
Posted: 03-Dec-2019 Tags: 2009 Toyota Picnic, 2009 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota									
	Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	Toyota Picnic	2.0A (COE till 10/2024)	\$36,800	\$7,580 /yr	26-Oct-2009	1,998 cc	133,168 km	MPV	Available
Toyota Is The Most Reliable And Low Maintenance Car In The Market. Superbly Well Maintained By Fussy Owner. Gearbox And Engine Still In Excellent State. No Further Repair Needed. Warranty Provided. Flexible Loan Scheme And Trade In Are Welcome. Please Contact...									
SmartCars Boutique Pte Ltd									
Posted: 17-Dec-2019 Tags: 2009 Toyota Picnic, 2009 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota									
	Toyota Picnic	2.0A (New 5-yr COE)	\$39,888	\$7,970 /yr	21-Oct-2009	1,998 cc	108,000 km	MPV	Available
Full Loan Available, Well Maintained Interior And Exterior, Half Year Warranty, Trade In Welcome, Call Now For Test Drive.									
Posted: 13-Dec-2019 Tags: 2009 Toyota Picnic, 2009 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota									
Compare	-		-	N.A	21-Oct-2009	1,998 cc	-	MPV	SOLD

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 16/12/19 (dd/mm/yy) Time of Accident: 15:20 (24-HR-FORMAT)

Vehicle No.: SJS 9664 G Vehicle Make & Model: Toyota Picnic

Exact location of Accident: PIE Jurong after Exit 12

Policyholder's Name / IC No.: 5M Partners Pte Ltd 201811126M

Driver's Name / IC No.: Zulkifle Bin Madon / 51715340D (As Above) ☐

Driver's Contact No.: 8155 4252 Company Contact No: _____

Driver's Address: 7 GAMBAS CRESCENT #05-03 S (757087)

Insurance Company: Tokio Marine Email address (if any): _____

Relationship between Owner & Driver: Hire

or Others specify: _____

What do you wish to claim? (Please TICK one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

Exact purpose for which the vehicle
Was being used at time of accident?

Occupation (nature of job) ☒ Indoor/ ☐ Outdoor

☒ Private use / ☐ Work purpose

No. of Passengers (Including Driver): 01

Passenger Name : _____

Gender : _____

Passenger Name : _____

Gender : _____

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☒ Yes / ☐ No (If YES) Injured Person's Name: Zulkifle Bin Madon

Injuries Sustain: leg Injured Person in Which Vehicle: SJS 9664 G

Police Report filed: ☐ Yes / ☒ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No.: Yen Chia Chieh / 57887494E Vehicle No: SGT 7544M (B)

Driver's Contact No: _____ Insurance Company (If any): _____

2. Driver's Name / IC No.: Chiong Ban Chin / 57611441B Vehicle No: SLT 1370C (C)

Driver's Contact No: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN

PIE towards Jurong

Vehicle A: SJS 9664 G

Vehicle B: SGT 7544 M

Vehicle C: SLT 1370 C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle A was travelling straight on my rightful lane. Vehicle C in front of me stopped. I followed suit. Suddenly Vehicle B hit onto my stationary Vehicle rear portion. The impact is so huge it caused my stationary vehicle to propel forward and hit onto Vehicle C rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SJE : _____ Vehicle Nos : **SJS 9664 G**
 Date of Survey : _____ Make : Toyota
 Date of ReSurvey: _____ After-Paint: _____ Model : Picnic
 Contacts : _____ Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	BONNET	1	\$ 1,120.00	\$ ✓ 1,120.00	DDV
2	BONNET CHROME GRILLE	1	\$ 683.40	\$ 379.10 683.40	BR ✓
3	BONNET INSULATOR	1	\$ 286.20	\$ 286.20	NSPX
4	BONNET LOCK	1	\$ 134.00	\$ ✓ 134.00	JAMV
5	BONNET LOCK STRICKER	1	\$ 86.00	\$ 50.00 86.00	BT ✓
6	FRONT GRILLE	1	\$ 543.80	\$ ✓ 543.80	DLV
7	HEADLAMP RH	1	\$ 1,206.90	\$ ✓ 1,206.90	BR ✓
8	HEADLAMP LH	1	\$ 1,206.90	\$ ✓ 1,206.90	BR ✓
9	HEADLAMP BRACKET RH	1	\$ 154.00	\$ 154.00	} NDX
10	HEADLAMP BRACKET LH	1	\$ 154.00	\$ 154.00	
11	FRONT BUMPER	1	\$ 1,096.00	\$ 868.00 1,096.00	DDV
12	FRONT BUMPER SIDE RETAINER	2	\$ 82.90 165.80	\$ 164.00 331.60	NECV
13	FRONT BUMPER CENTER GRILLE	1	\$ 236.80	\$ ✓ 236.80	BRV
14	FRONT BUMPER REINFORCEMENT	1	\$ 462.80	\$ 310.30 462.80	BT ✓
15	FRONT BUMPER INNER SPOOGE	1	\$ 182.00	\$ ✓ 182.00	BRV
16	FRONT SUPPORT PANEL	1	\$ 699.40	\$ ✓ 699.40	BT ✓
17	FRONT SUPPORT PANEL TOP GARNISH	1	\$ 327.50	\$ 327.50	NSPX
18	FRONT FOG LAMP CAVER	2	\$ 127.50	\$ 255.00	} NDX
19	FRONT FOG LAMP	2	\$ 318.20	\$ 636.40	
20	FRONT RIGHT FENDER	1	\$ 964.20	\$ 889.40 964.20	BT ✓
21	FRONT RIGHT INNER COWLING	1	\$ 358.60	\$ 358.60	NDX
22	FRONT RIGHT FENDER SIGNAL LIGHT	1	\$ 126.30	\$ ✓ 126.30	DLV
23	FRONT RIGHT FENDER EMBLEM "VVTI"	1	\$ 105.40	\$ 69.20 105.40	NECV
24	FRONT RIGHT SIDE GLASS	1	\$ 486.20	\$ 486.20	NDX
25	FRONT RIGHT SIDE GLASS MOUDING	1	\$ 156.20	\$ ✓ 156.20	NECV
26	FRONT LEFT FENDER	1	\$ 964.20	\$ 964.20	RX
27	FRONT LEFT INNER COWLING	1	\$ 358.60	\$ 358.60	} NDX
28	FRONT LEFT FENDER SIGNAL LIGHT	1	\$ 126.30	\$ 126.30	

29	FRONT LEFT FENDER EMBLEM "VTI"	1	\$	105.40	\$ 45.30	105.40	NECV
30	RADIATOR	1	\$	954.70	\$	✓ 954.70	BTV
31	AIR CON CONDENSER	1	\$	862.40	\$ 862.40	862.40	BTV
32	AIR CON LOW PRESSURE PIPE	1	\$	243.10	\$	✓ 243.10	BTV
33	AIR CON HIGH PRESSURE PIPE	1	\$	294.40	\$	✓ 294.40	BTV
34	RADIATOR FAN COWLING	1	\$	657.00	\$ 269.40	657.00	BRV
35	REAR BUMPER	1	\$	1,852.00	\$ 1,265.00	1,852.00	BRV
36	REAR BUMPER REFLECTORS	2	\$	69.90 213.40	\$ 139.80	426.80	MIS/BR
37	REAR BUMPER SUPPORT BRACKET	2	\$	125.00 137.40	\$ 250.00	274.80	BT
38	REAR BUMPER TOW CAP	2	\$	36.00 186.20	\$ 72.00	372.40	MISV
39	REAR BUMPER SIDE RETAINER	2	\$	90.00 186.70	\$ 180.00	373.40	NECV
40	REAR AIR VENTS	2	\$	146.20	\$	292.40	NDX
41	TAILGATE	1	\$	1,375.90	\$	✓ 1,375.90	DDV
42	TAILGATE INNER TRIM BOARD	1	\$	498.20	\$ 498.20	✓ 498.20	BRV
43	TAILGATE MOULDING	1	\$	287.50	\$ 144.80	287.50	BRV
44	TAILGATE HINGE	2	\$	298.40	\$	596.80	NDX
45	TAILGATE DAMPER	2	\$	349.60	\$	699.20	
46	TAILGATE WEATHERSTRIP	1	\$	188.30	\$	✓ 188.30	DISV
47	TAILGATE LAMP	2	\$	329.75 996.00	\$ 659.50	1,992.00	BRV
48	TAILGATE STOPPER	2	\$	75.80	\$	151.60	NNX
49	TAILGATE INNER LOCK	1	\$	404.80	\$	✓ 404.80	JAMV
50	TAILGATE WIPER MOTOR	1	\$	529.30	\$	529.30	NDX
51	TAILGATE OPENER SWITCH	1	\$	104.50	\$	104.50	NDX
52	TAILGATE LOGO	1	\$	143.20	\$ 68.50	143.20	NECV
53	TAILGATE EMBLEM "TOYOTA"	1	\$	108.60	\$ 50.80	108.60	
54	TAILGATE EMBLEM "PICNIC"	1	\$	105.30	\$ 52.30	105.30	NECV
55	REAR WINDSCREEN RUBBER MOULDING	1	\$	187.90	\$	✓ 187.90	NECV
56	REAR END PANEL	1	\$	712.50	\$	✓ 712.50	DDV
57	REAR END PANEL TOP GARNISH	1	\$	321.00	\$	✓ 321.00	DLV
58	REAR FLOOR PANEL	1	\$	1,025.30	\$	✓ 1,025.30	DISV
59	REAR FLOOR PANEL TOP BOARD	2	\$	580.70	\$ 736.20	1,161.40	DISV
60	REAR FLOOR PANEL TOP SIDE BOARD	2	\$	201.30 318.00	\$ 402.60	636.00	DISV
61	REAR FLOOR PANEL TOP BOARD REAR GARNISH	1	\$	398.00	\$	✓ 398.00	DIS
62	REAR FENDER SIDE INNER TRIMBOARD	2	\$	808.90 1,770.60	\$ 1,617.80	3,541.20	BRV
63	TAILLAMP	2	\$	396.72 1,364.00	\$ 793.44	2,728.00	BRV
64	EXHAUST PIPE SILENCER	1	\$	820.90	\$	✓ 820.90	BTV
65	EXHAUST PIPE MOUNTING	2	\$	64.00	\$	✓ 128.00	DLV
					Parts Sub Total :	\$ 23505.14	39,002.90
25%					Discount	\$ 5876.27	9,750.73
					PARTS TOTAL :	\$ 17628.86	29,252.18

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$		
1	NUMBER PLATE WITH CASING	1	\$ 80.00	\$ 50.00	80.00	BR/MIS ✓
2	FRONT GRILLE CLIPS	1	\$ 50.00	\$ 30.00	50.00	NECV ✓
3	FRONT BUMPER CLIPS	1	\$ 50.00	\$ 30.00	50.00	NECV ✓
4	FRONT SUPPORT PANEL TOP GARNISH CLIPS	1	\$ 50.00	\$	50.00	NNX ✓
5	BONNET INSULATOR CLIPS	1	\$ 50.00	\$	50.00	NNX ✓
6	FRONT FOG LAMP CAVER CLIPS	1	\$ 50.00	\$	50.00	NNX ✓
7	FRONT CENTER GRILLE CLIPS	1	\$ 50.00	\$ 30.00	50.00	NECV ✓
8	FRONT RIGHT FENDER SEALANT	1	\$ 80.00	\$ 30.00	80.00	NECV ✓
9	FRONT RIGHT INNER COWLING CLIPS	1	\$ 50.00	\$	50.00	NNX ✓
10	FRONT RIGHT SIDE GLASS SEALANT	1	\$ 80.00	\$	80.00	NNX ✓
11	FRONT LEFT FENDER SEALANT	1	\$ 80.00	\$	80.00	NNX ✓
12	FRONT LEFT INNER COWLING CLIPS	1	\$ 50.00	\$	50.00	NNX ✓
13	RADIATOR COOLANT	1	\$ 80.00	\$ 40.00	80.00	NECV ✓
14	A/C FLUID	1	\$ 80.00	\$ 40.00	80.00	NECV ✓
15	REVERSE CAMERA	1	\$ 400.00	\$ 300.00	400.00	WTV ✓
16	REVERSE SENSOR SET	3	\$ 180.00	\$ 200.00	540.00	MIS/WTV ✓
17	REAR NUMBER PLATE WITH CASING	1	\$ 80.00	\$	80.00	NNX ✓
18	REAR BUMPER CLIPS	1	\$ 80.00	\$ 30.00	80.00	NECV ✓
19	REAR FENDER SIDE INNER TRIMBOARD CLIPS	1	\$ 50.00	\$ 30.00	50.00	NECV ✓
20	TAILGATE SEALANT	1	\$ 120.00	\$ 30.00	120.00	NECV ✓
21	TAILGATE INNER TRIM CLIPS	1	\$ 50.00	\$ 30.00	50.00	NECV ✓
22	REAR END PANEL TOP GARNISH CLIPS	1	\$ 50.00	\$ 30.00	50.00	NECV ✓
23	REAR WINDSCREEN INNER SEAL	1	\$ 120.00	\$ 50.00	120.00	NECV ✓
24	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ 40.00	80.00	NECV ✓
25	REAR END PANEL SEALANT	1	\$ 80.00	\$ 40.00	80.00	NECV ✓
26	REAR FLOOR PANEL SEALANT	1	\$ 80.00	\$ 40.00	80.00	NECV ✓
27	REAR FLOOR PANEL INSULATOR	1	\$ 250.00	\$ 150.00	250.00	NECV ✓
28	REAR TAILLAMP PANEL CLIPS	2	\$ 50.00	\$ 30.00	100.00	NECV ✓
29	REAR TAILLAMP PANEL SEALANT	2	\$ 120.00	\$ 50.00	240.00	NECV ✓
30	SUNDRIES	1	\$ 80.00	\$	80.00	NNX ✓
31	STICKER	1	\$ 250.00	\$	250.00	NNX ✓
SPECIAL NETT TOTAL :				\$ 1300.00	3,530.00	

Nos.	LABOUR	S\$		
1	FRONT PANEL BEATING	\$ 600.00	1,600.00	/
2	R&R RADIATOR	\$ 80.00	150.00	/
3	R&R AIR CON CONDENSER	\$ 80.00	150.00	/
4	FRONT SPRAY PAINT	\$ 600.00	1,600.00	/
5	DIAGNOSTIC & RESET FAULT CODE	\$	150.00	NNX
6	REAR PANEL BEATING	\$ 1000.00	1,800.00	✓
7	REAR SPRAY PAINT	\$ 1200.00	1,600.00	✓
8	ALIGNMENT CHASSIS	\$	300.00	NNX
9	R&R EXHAUST PIPE	\$ 80.00	180.00	/
10	CHECK WIRING	\$ 50.00	150.00	/
11	RUST PROOFING	\$ 50.00	100.00	✓
12	CONDUCT WATER LEAKAGE TEST	\$	150.00	NNX
13	R&R TAILGATE COMPONENT <i>Boot lid</i>	\$	200.00	
14	R&R WINDSCREEN GLASS	\$	180.00	NNX
15	SPRAY REVERSE SENSOR	\$	180.00	
LABOUR TOTAL :		\$ 3740.00	8,490.00	

Survey 17/12/19

1530 hrs

TGrim lim

Lump sum repair

Resurvey 20/12/19

1535 hrs

TGrim lim

Repair days 14

PARTS TOTAL : \$17,628.86 29,252.18

SPECIAL NETT TOTAL : \$1,300.00 3,530.00

LABOUR TOTAL : \$3,740.00 8,490.00

GRAND TOTAL : \$ 41,272.18

22,668.86

@20% 4,533.77

18135.10

L/S 18,100/2

TGrim lim
14/1/2020

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19022160/Byf3e2		
50 RAFFLES PLACE		Date : 12-03-2020		
#05-01/06		Code : SMO		
SINGAPORE LAND TOWERSINGAPORE 048623				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGT 7544M	Veh. Inspected	SJS 9664G	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1905836/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	17/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PICNIC	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTEGH23B500026976	Colour	SILVER	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	POOR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	APLUS	5 mm	
L/H Front Tyre	205/55 R16	APLUS	5 mm	
R/H Rear Tyre	205/55 R16	APLUS	5 mm	
L/H Rear Tyre	205/55 R16	APLUS	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY, FRONT AND REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/12/2019	Inspection Date	17/12/2019	
Survey held at	TEAM AUTOPRO PTE LTD 160 Sin Ming Dr #01-14 Sin Ming AutoCity Singapore 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 9664G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	DENTED	1,120.00	1,120.00
1	BONNET CHROME GRILLE	BROKEN	683.40	379.10
1	BONNET INSULATOR	NO SUCH PARTS	286.20	-
1	BONNET LOCK	JAMMED	134.00	134.00
1	BONNET LOCK STRICKER	BENT	86.00	50.00
1	FRONT GRILLE	DISLODGE	543.80	543.80
1	HEADLAMP RH	BROKEN	1,206.90	1,206.90
1	HEADLAMP LH	BROKEN	1,206.90	1,206.90
1	HEADLAMP BRACKET RH	NOT DAMAGED	154.00	-
1	HEADLAMP BRACKET LH	NOT DAMAGED	154.00	-
1	FRONT BUMPER	DENTED	1,096.00	868.00
2	FRONT BUMPER SIDE RETAINER @\$165.80	NECESSARY	331.60	164.00
1	FRONT BUMPER CENTER GRILLE	BROKEN	236.80	236.80
1	FRONT BUMPER REINFORCEMENT	BENT	462.80	310.30
1	FRONT BUMPER INNER SPONGE	BROKEN	182.00	182.00
1	FRONT SUPPORT PANEL	BENT	699.40	699.40
1	FRONT SUPPORT PANEL TOP GARNISH	NO SUCH PARTS	327.50	-
2	FRONT FOG LAMP CAVER @\$127.50	NOT DAMAGED	255.00	-
2	FRONT FOG LAMP @\$318.20	NOT DAMAGED	636.40	-
1	FRONT RIGHT FENDER	BENT	964.20	889.40
1	FRONT RIGHT INNER COWLING	NOT DAMAGED	358.60	-
1	FRONT RIGHT FENDER SIGNAL LIGHT	DISLODGE	126.30	126.30
1	FRONT RIGHT FENDER EMBLEM "VVTI"	NECESSARY	105.40	69.20
1	FRONT RIGHT SIDE GLASS	NOT DAMAGED	486.20	-
1	FRONT RIGHT SIDE GLASS MOUDING	NECESSARY	156.20	156.20
1	FRONT LEFT FENDER	TO REPAIR SEE LABOUR	964.20	-
1	FRONT LEFT INNER COWLING	NOT DAMAGED	358.60	-
1	FRONT LEFT FENDER SIGNAL LIGHT	NOT DAMAGED	126.30	-
1	FRONT LEFT FENDER EMBLEM "VVTI"	NECESSARY	105.40	45.30
1	RADIATOR	BENT	954.70	954.70

Report Ref No. CS/SMO19022160/Byf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CON CONDENSER	BENT	862.40	862.40
1	AIR CON LOW PRESSURE PIPE	BENT	243.10	243.10
1	AIR CON HIGH PRESSURE PIPE	BENT	294.40	294.40
1	RADIATOR FAN COWLING	BROKEN	657.00	269.40
1	REAR BUMPER	BROKEN	1,852.00	1,265.00
2	REAR BUMPER REFLECTORS @\$213.40	MISSING / BROKEN	426.80	139.80
2	REAR BUMPER SUPPORT BRACKET @\$137.40	BENT	274.80	250.00
2	REAR BUMPER TOW CAP @\$186.20	MISSING	372.40	72.00
2	REAR BUMPER SIDE RETAINER @\$186.70	NECESSARY	373.40	180.00
2	REAR AIR VENTS @\$146.20	NOT DAMAGED	292.40	-
1	TAILGATE	DENTED	1,375.90	1,375.90
1	TAILGATE INNER TRIM BOARD	BROKEN	498.20	498.20
1	TAILGATE MOULDING	BROKEN	287.50	144.80
2	TAILGATE HINGE @\$298.40	NOT DAMAGED	596.80	-
2	TAILGATE DAMPER @\$349.60	NOT DAMAGED	699.20	-
1	TAILGATE WEATHERSTRIP	DISTORTED	188.30	188.30
2	TAILGATE LAMP @\$996.00	BROKEN	1,992.00	659.50
2	TAILGATE STOPPER @\$75.80	NOT NECESSARY	151.60	-
1	TAILGATE INNER LOCK	JAMMED	404.80	404.80
1	TAILGATE WIPER MOTOR	NOT DAMAGED	529.30	-
1	TAILGATE OPENER SWITCH	NOT DAMAGED	104.50	-
1	TAILGATE LOGO	NECESSARY	143.20	68.50
1	TAILGATE EMBLEM "TOYOTA"	NECESSARY	108.60	50.80
1	TAILGATE EMBLEM "PICNIC"	NECESSARY	105.30	52.30
1	REAR WINDSCREEN RUBBER MOULDING	NECESSARY	187.90	187.90
1	REAR END PANEL	DENTED	712.50	712.50
1	REAR END PANEL TOP GARNISH	DISLODGE	321.00	321.00
1	REAR FLOOR PANEL	DISTORTED	1,025.30	1,025.30
2	REAR FLOOR PANEL TOP BOARD @\$580.70	DISTORTED	1,161.40	736.20
2	REAR FLOOR PANEL TOP SIDE BOARD @\$318.00	DISTORTED	636.00	402.60
1	REAR FLOOR PANEL TOP BOARD REAR GARNISH	DISTORTED	398.00	398.00
2	REAR FENDER SIDE INNER TRIMBOARD @\$1770.60	BROKEN	3,541.20	1,617.80
2	TAILLAMP @\$1364.00	BROKEN	2,728.00	793.44

Report Ref No. CS/SMO19022160/Byf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST PIPE SILENCER	BENT	820.90	820.90
2	EXHAUST PIPE MOUNTING @\$64.00	DISLODGE	128.00	128.00
	LESS 25% DISCOUNT		-9,750.73	-5,876.29
			29,252.17	17,628.85
	<u>SPECIAL NETT ITEMS</u>			
1	NUMBER PLATE WITH CASING (SN)	BROKEN / MISSING	80.00	50.00
1	FRONT GRILLE CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
1	BONNET INSULATOR CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRONT FOG LAMP CAVER CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRONT CENTER GRILLE CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT RIGHT FENDER SEALANT (SN)	NECESSARY	80.00	30.00
1	FRONT RIGHT INNER COWLING CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRONT RIGHT SIDE GLASS SEALANT (SN)	NOT NECESSARY	80.00	-
1	FRONT LEFT FENDER SEALANT (SN)	NOT NECESSARY	80.00	-
1	FRONT LEFT INNER COWLING CLIPS (SN)	NOT NECESSARY	50.00	-
1	RADIATOR COOLANT (SN)	NECESSARY	80.00	40.00
1	A/C FLUID (SN)	NECESSARY	80.00	40.00
1	REVERSE CAMERA (SN)	CUT	400.00	300.00
3	SET REVERSE SENSOR @\$180.00 (SN)	MISSING / CUT	540.00	200.00
1	REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	80.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	REAR FENDER SIDE INNER TRIMBOARD CLIPS (SN)	NECESSARY	50.00	30.00
1	TAILGATE SEALANT (SN)	NECESSARY	120.00	30.00
1	TAILGATE INNER TRIM CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	120.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR FLOOR PANEL SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR FLOOR PANEL INSULATOR (SN)	NECESSARY	250.00	150.00
2	REAR TAILLAMP PANEL CLIPS @\$50.00 (SN)	NECESSARY	100.00	30.00

Report Ref No. CS/SMO19022160/Byf3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR TAILLAMP PANEL SEALANT @\$120.00 (SN)	NECESSARY	240.00	50.00
1	SUNDRIES (SN)	NOT NECESSARY	80.00	-
1	STICKER (SN)	NOT NECESSARY	250.00	-
			3,530.00	1,300.00
	LABOUR			
	FRONT PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT LEFT FENDER.		1,600.00	600.00
	R&R RADIATOR.		150.00	80.00
	R&R AIR CON CONDENSER.		150.00	80.00
	FRONT SPRAY PAINT.		1,600.00	600.00
	DIAGNOSTIC & RESET FAULT CODE.	NOT NECESSARY	150.00	-
	REAR PANEL BEATING.		1,800.00	1,000.00
	REAR SPRAY PAINT.		1,600.00	1,200.00
	ALIGNMENT CHASSIS.	NOT NECESSARY	300.00	-
	R&R EXHAUST PIPE.		180.00	80.00
	CHECK WIRING.		150.00	50.00
	RUST PROOFING.		100.00	50.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	150.00	-
	R&R TAILGATE COMPONENT.	NOT NECESSARY	200.00	-
	R&R WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	SPRAY REVERSE SENSOR.	NOT NECESSARY	180.00	-
			8,490.00	3,740.00
GRAND TOTAL			41,272.17	22,668.85
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,950.00

Report Ref No. CS/SMO19022160/Byf3e2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.