vit/g/iti	Adwan	ASSIGNA	MENT (Office))	
From (Person	The Control of the Co			Dute/Time: [4-12-14 11-	34am
Estimple Co			Bill to:	Trans Tilles	
To Inspect V	and a	es/eva/inv/mv DQ 945	I CS	Insured: SEB 934 P	
	m/s WSmn /			Tet: 98564815	
of 8 lak	i Bukit Ave	4 #08-09	Premier		
Policy No:_			Claim No:	(10004912	
Sum Insured			Excess:		
Make of Veh (Client's Recon				D.O.A. 14.0. 2019	
CA / REV	/ REP. / REV 24 1 -12.19 1.53p. i		miduh	Vehicle IN OUT	
Date/Time	Action/Instruction	(V) Estinu	to.		
	SDQ 945-				
	SEB 934P	- BIPCI HOURS	4 Aphinz	1.0n - Julon/3017	

450

Nivitha (LKK Auto)

From:

lvy Ratilla <ivy.r@budgetdirect.com.sg>

Sent:

Tuesday, 17 December 2019 11:34 AM

To:

Nivitha (LKK Auto)

Cc:

SUR; Loganathan Agoram

Subject:

FW: SDQ94S (Pre-inspection) / Your vehicle : SKB934P || C10004912

Attachments:

TP PRS.pdf; OI Report.pdf; TP Report.pdf

Hi Team,

We would like to arrange TP PRS for SDQ94S.

Workshop information: 8 Kaki Bukit Avenue 4 #08-09Premier @ Kaki Bukit Singapore (415875)

Tel: 6341 6789 Fax: 6341 6778

Please confirm. Thank you.

Regards,

Ivy Ratilla Executive, Claims Admin

T +65 6540 2185 F +65 6725 0853 E ivy.r@budgetdirect.com.sg



Trusted Service Award

Customer Care +65 6221 2111 Claims +65 6221 2199 Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01 Singapore Shopping Centre Singapore 239924 budgetdirect.com.sq

auto 🗟 general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as <u>Budget</u> <u>Direct Insurance</u>.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee,

confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Dynamic Autowork <dynamicautowork@gmail.com>

Sent: Tuesday, 17 December 2019 11:02 AM To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>

Cc: Claims <claims@budgetdirect.com.sg>; Loganathan Agoram <loganathan.a@budgetdirect.com.sg>

Subject: Re: SDQ94S (Pre-inspection) / Your vehicle : SKB934P | | C10004912

Dear All.

Thanks for reply.

Please arrange LKK Auto Consultants Pte Ltd to survey the above vehicle.

** PLEASE ADVISE LIABILITY AFTER YOUR CLIENT LODGE THE GIA REPORT **

Thank You.

Yours Sincerely,

Michelle HP: 9856 4815

8 Kaki Bukit Avenue 4 #08-09Premier @ Kaki Bukit Singapore (415875)

Tel: 6341 6789 Fax: 6341 6778

From: Dynamic Autowork < dynamicautowork@gmall.com>


Sent: Monday, 16 December 2019 4:59 PM

To: Claims < claims@budgetdirect.com.sg>; Albert Hong < albert.hong@budgetdirect.com.sg>

Subject: SDQ945 (Pre-inspection) / Your vehicle: SKB934P

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.



This email is sent by Auto & General Insurance (Singapore) Pte. Limited, Auto & General (SEA) Services Pte. Limited, Easy Compare (Thailand) Co., Ltd or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. If you are not the intended



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out m






Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! 2016 BMW 2 Series 216d Gran Tourer Luxury At \$83k Agent (PML) Unit , Fully tained By PML Workshop,Low Mile

A Lake View Credit Pte Ltd > Low prices guaranteed > Specialist in Japanese cars

> Easy loan approval > All terms are negotiable



Honda Civic Type R 2.8M (COE till 11/2027)

till 11/2027)

\$81,500

\$10,280 /yr

3 x Original Defi Gauges, Hondata, J's Racing Header And Exhuats, Ap Racing 6Pot, Choon's Intake, TC105X, CF Parts, Mitin Suspension, Nice Bidded Number To Go With. Viewing By Appointment Only. Price Negotiable.

68-Jan-2008

1.998 cc

Sports

Available

DESCRIPTION OF

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC	
Owner ID:	643Z	
Vehicle Details	William Control of the Control of th	
Vehicle No.:	5DQ945	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	17 Dec 2019	
Vehicle Make:	HONDA	
Vehicle Model:	CIVIC 3DRS TYPE R	
Primary Colour:	Blue	
Secondary Colour:	Black	
Manufacturing Year:	2007	
Engine No.:	K20Z41007299	
Chassis No.:	SHHFN23607U100796	
Maximum Power Output:	148.0 kW (198 bhp)	
Open Market Value:	\$33,343,00	
Original Registration Date:	26 Sep 2007	
First Registration Date:	26 Sep 2007	
Transfer Count:	7	
Actual ARF Paid:	\$36,678,00	
Intended PARE Repart Details		THE RESERVE
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:	E	
PARF Rebate Amount:	\$0.00	
Interness COE Religita Distails		10 3 11
COE Expiry Date:	25 Sep 2027	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	10	
PQP Paid:	\$50,355.00	
COE Rebate Amount:	\$39,137,00	
Total Rebate Amount:	\$39,137,00	

The information contained herein is correct as at 17 Dec 2019

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C) 8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778 E-mail:dynamicautowork@gmail.com LKX Auto Corp. Total Conference Totally the Repairer of the following:

- To resurvey before latter spray painting
- . To display damaged partial during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is tillowed
- . Supplem DATE : 16.12.19

TO

: BUDGET DIRECT MOTOR CLAIMS DEPTS

VEHICLE NO

: SDQ94S

MODEL

: HONDA CIVIC

DATE OF ACCIDENT

: 14.12.19

TIME OF ACCIDENT

: 13:20HRS

Ivone .

Signature:

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	U	INIT LIST PRICE	TOTAL LIST PRICE	
1	REAR BUMPER Seld	1	\$	1,095.20	\$	1,095.20
2	REAR BUMPER SIDE RETAINER	2	s	35.20	\$	70.40
3	TAIL GATE DENTED	1	\$	950.20	\$	950.20
4	TAIL GATE LAMP RH and	2	\$	420.40	\$	840.80
5	TAIL GATE OUTER GARNISH	1	\$	1,379.20	\$	1,379.20
6	TAIL GATE DAMPER NY ~~	2	\$	104.20	\$	208.40
7	TAIL GATE STOPPER M ~	2	\$	12.00	\$	24.00
8	TAIL GATE INNER LOCK	1	s	231.40	s	231.40
9	TAIL GATE LOCK CATCH M ~~	1	\$	25.00	\$	25.00
10	TAIL GATE WEATHER STRIP C+	1	\$	150.80	\$	150.80
11	TAIL GATE INNER TRIM	1	s	385.90	s	385.90
12	TAIL GATE WINDSCREEN MOULDING A	2	\$	95.00	\$	190.00
13	REAR FENDER ARCED GARNISH NY	2	S	230.40	S	460.80
14	REAR FENDER INNER COWLING & ~	2	\$	85.20	\$	170.40
15	REAR FENDER INNER TRIM	2	\$	752.40	s	1,504.80
16	REAR END PANEL Devild	1	\$	575.20	\$	575.20
17	REAR END PANEL TOP GARNISH	1	\$	152.40	s	152.40
18	REAR FLOOR PANEL TOP BOARD X4 -	1	\$	584.60	s	584.60

5215-20 TOTAL PRICE \$ LESS 20% 417216 SUB TOTAL PRICE

8,999.50

1,799.90

7,199.60

S/N	DESCRIPTION	QTY	UN	IT S/NETT	TOT	AL S/NETT
1	REAR NUMBER PLATE	1	\$	50.00	\$	50.00
2	REAR BUMPER CLIP (SET) No.	:1	s	80.00	s	80.00
3	REAR BUMPER SPOILER (SPECIAL TYPE)	1	\$	3,800.00	s	3,800:00
4	TAIL GATE OUTER GARNISH CLIP (SET)	1	s	50.00	s	50.00
5	TAIL GATE INNER TRIM CLIP (SET)	1	s	50.00	\$	50.00
6	TAIL GATE WINDSCEEN SEALANT /	9	S	80.00	\$	80.00



TO : BUDGET DIRECT MOTOR CLAIMS DEPTS

VEHICLE NO : SDQ94S

MODEL : HONDA CIVIC

DATE OF ACCIDENT : 14.12.19 TIME OF ACCIDENT : 13:20HRS

	3660		TOT	AL	5	9,060.00
13	REAR END PANEL TOP GARNISH CLIPS (SET)	1	\$	30.00	\$	30,00
12	REAR END PANEL INSULATION SEAL	1	\$	150.00	\$	150.00
11	REAR FENDER INNER TRIM CLIPS (SET) And	1	\$	80.00	\$	80.00
10	REAR FENDER INNER COWLING CLIP (SET)	1	\$	80.00	\$	80.00
9	TAIL LAMP CLIP (SET)	1	\$	50.00	\$	50:00
8	CAR STICKER (SPECIAL TYPE) (SET) No.	1	\$	4,500.00	\$	4,500:00
7	TAIL GATE WINDSCEEN INNER SEAL	1	\$	60.00	\$	60.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION		PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$	1,600.00	8W
2	TO SPRAY PAINT AFFECTED AREA	s	1,600.00	1000
3	TUFF COAT	s	250,00	60
4	WIRING CHECK	\$	180,80	30
5	CONDUCT WATER LEAKAGE TEST	\$	80.00	X
6	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$	350,00	60
7	REAR CHASSIS ALIGNMENT	\$	200,00	X
8	REMOVE AND REFIX TAILGATE WINDSCREEN	s	129,06	/
9	TRANSFER TAILGATE MECHANISM	\$	80,00	/
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	s	280.00	×

TOTAL 4740

ESTIMATE REPORT

TOTAL PARTS COST : \$ 16,259.60 TOTAL LABOUR COST : \$ 4,740.00 TOTAL REPAIR COST : \$ 20,999.60

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

2,50

06 Page.
total: 99821.
LS: 75K

16-12-19:14:50 :

1/ 1

To: JAE-AH LONG (FAX:6745 4442)

From : DYNAMIC Autowork (AH GU)

Tel: 9730 5584 Fax: 6341 6778

Vehicle No: SDQ94S

Vehicle Model: HONDA CIVIC 3DRS TYPE R

Chassis No: SHHFN23607U100796

Year: 2007

** Please Quote

Thanks

No	Description	Qty	LIST PRICE
1	REAR BUMPER	1	1095.3
2	REAR BUMPER SIDE RETAINER	1	23.4
3	TAIL GATE	1	950-3
4	TAIL GATE LAMP	1	4.064
5	TAIL GATE OUTER GARNISH	1	1379-0
6	TAIL GATE DAMPER	1	185.4
7	TAIL GATE STOPPER	-1	8-4
8	TAIL GATE INNER LOCK	1	231.4
9	TAIL GATE LOCK CATCH	1	98.7
10	TAIL GATE WEATHER STRIP	1	140.8
11	TAIL GATE INNER TRIM	1	381 9
12	TAIL GATE WINDSCREEN MOULDING	1	88.4
13	REAR FENDER ARCED GARNISH	1	230-4
14	REAR FENDER INNER COWLING	1	82.3
15	REAR FENDER INNER TRIM	1	Y-62F
16	REAR END PANEL	1	6.2/2
17	REAR END PANEL TOP GARNISH	1	4-621
18	REAR FLOOR PANEL TOP BOARD	1	484.6



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI19022162/Ayf3n2

(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01

Date: 29-01-2020



SINGAPORE SHOPPING CENTRESINGAPORE 239924

1.		Policy Particula	ars :- THIRD PARTY CLA	MM
	Insured Veh.	SKB 934P	Veh. Inspected	SDQ 94S
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10004912	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	17/12/2019
2.	DATE OF	Vehicle Pa	articulars & Condition	
	Make & Model	HONDA CIVIC TYPE R	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	SHHFN23607U100796	Colour	BLUE
	Odometer	185068	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Con	nditions of Tyres	N - 12 E
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	YOKOHAMA	6 mm
	L/H Front Tyre	225/45 R17	YOKOHAMA	6 mm
	R/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm
	L/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm
4.		Descr	iption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE ETAILS.	REAR PORTION.	
5.			neral Information	No. of Concession, Name of Street, or other Persons of Str
	Accident Date	14/12/2019	Inspection Date	17/12/2019
	Survey held at	VISION AUTOWORK PTE L	.TD	
		8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI E SINGAPORE 415875	викіт	
5a.			Remarks	ED-THEFT O
	A)THE INSPECTION B)IN ACCORDANGE	ON WAS CONDUCTED ON A CE TO YOUR INSTRUCTION	"WITHOUT PREJUDICE" BA S, WE HAVE NOT AUTHOR	ISIS. ISED REPAIRS.
5b.		Estim	nate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	6 Working Da	ivs



LKK Auto Consultants Pte L 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 LKK Auto Consultants Pte Ltd

TEL: 8256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDQ 94S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	1,095.20	1,095.20
2	REAR BUMPER SIDE RETAINER @\$35.20	NECESSARY	70.40	70:40
1	TAIL GATE	DENTED	950.20	950.20
2	TAIL GATE LAMP @\$420.40	O/S DAMAGED	840.80	420.40
1	TAIL GATE OUTER GARNISH	CRACKED	1,379.20	1,379.20
2	TAIL GATE DAMPER @\$104.20	NOT NECESSARY	208.40	
2	TAIL GATE STOPPER @\$12.00	NOT NECESSARY	24.00	
1	TAIL GATE INNER LOCK	DAMAGED	231.40	231.40
1	TAIL GATE LOCK CATCH	NOT NECESSARY	25.00	
1	TAIL GATE WEATHER STRIP	CUT	150.80	150.80
1	TAIL GATE INNER TRIM	NOT NECESSARY	385.90	
2	TAIL GATE WINDSCREEN MOULDING @\$95.00	NECESSARY	190.00	190.00
2	REAR FENDER ARCED GARNISH @\$230.40	NOT NECESSARY	460.80	
2	REAR FENDER INNER COWLING @\$85.20	NOT NECESSARY	170.40	
2	REAR FENDER INNER TRIM @\$752.40	NOT NECESSARY	1,504.80	
1	REAR END PANEL	DENTED	575.20	575.20
1	REAR END PANEL TOP GARNISH	DEFORMED	152.40	152.40
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	584.60	
	LESS 20% DISCOUNT		-1,799.90	-1,043.04
			7,199.60	4,172.16
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	
1	SET REAR BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	REAR BUMPER SPOILER (SPECIAL TYPE)(SN)	CRACKED	3,800.00	1,400.00
1	SET TAIL GATE OUTER GARNISH CLIP (SN)	NECESSARY	50.00	30.00
1	SET TAIL GATE INNER TRIM CLIP (SN)	NOT NECESSARY	50.00	
1	TAIL GATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
1	TAIL GATE WINDSCREEN INNER SEAL (SN)	NECESSARY	60.00	60.00
1	SET CAR STICKER (SPECIAL TYPE)(SN)	NECESSARY	4,500.00	2,000.00
1	SET TAIL LAMP CLIP (SN)	NECESSARY	50.00	10.00
1	SET REAR FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	80.00	
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	80.00	
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	150.00	60.00

Report Ref No. CS/AGI19022162/Ayf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
- 1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	30.00	10.00
			9,060.00	3,660.00
	LABOUR			
	PANEL BEATING, REMOVAL AND REPLACING PARTS.		1,600.00	800.00
	TO SPRAY PAINT AFFECTED AREA.		1,600.00	1,000.00
	TUFF COAT.		250.00	60.00
	WIRING CHECK.		180.00	30.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	80.00	3
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.		350.00	60.00
	REAR CHASSIS ALIGNMENT.	NOT NECESSARY	200.00	
	REMOVE AND REFIX TAILGATE WINDSCREEN.		120.00	120.00
	TRANSFER TAILGATE MECHANISM.		80.00	80.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	280.00	ē.
			4,740.00	2,150.00
	GRAND TOTAL		20,999.60	9,982.16

RECOMMENDED COST OF LUMP SUM REPAIRS	7,900.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/AGI19022162/Ayf3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whetever, in contact or tori, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report in whole or in part, does so at his or her own risk.