



ALFRED AUTO

Services & Supplies

Bik 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No: 161219

Date: 16.12.2019

Lim Heok Long Clifton

156 Joo Chiat Terrance #04-04

Singapore 427303

Volkswagen Passat B8 1.8

Estimated Repair Cost for Vehicle Reg. No: SLZ 3803 B

REPLACEMENT OF DAMAGED PANELS / PARTS

1 Pc. Front Bonnet	/ BUC	899.30	/
1 Pc. Front Bonnet Rubber	X NN	238.50	X
1 Pc. Front Bonnet Lock	/ DM	266.10	/
2 Pcs. Front Bonnet Adjuster	X SNN @ 68.00	136.00	X
1 Pc. Front Bonnet Sponge	X	310.00	X
10 Pcs. Front Bonnet Sponge Clips	/ BUC @ 8.00	80.00	/
1 Pc. Front Grille	/ BR	499.00	/
1 Pc. Front Grille Logo	/ BUC	198.00	/
2 Pcs. Front Head Lamp Assy RH/LH	/ Cut @ 2,155.00	4,310.00	/
2 Pcs. Front Head Lamp Chrome RH/LH	X @ 98.00	196.00	X
2 Pcs. Front Head Lamp Support	X SNN @ 29.50	59.00	X
1 Pc. Front Support Panel	X	592.60	X
2 Pcs. Front Support Garnish	/ CAA @ 178.00	356.00	/
10 Pcs. Front Support Garnish Clips	/ BUC @ 8.00	80.00	/
1 Pc. Front Bumper	/ BR	908.50	/
1 Pc. Front Bumper Towing Cover	/ BR	90.10	/
2 Pcs. Front Bumper Washer Cover	X NN @ 72.00	144.00	X
10 Pcs. Front Bumper Clips	/ BUC @ 8.00	80.00	/
1 Pc. Front Bumper Top Garnish	/ Cut	199.00	/
1 Pc. Front Bumper Reinforcement	/ BT	598.00	/
1 Pc. Front Bumper Reinforcement Top Beam	/ BR	185.50	/
1 Pc. Front Bumper Reinforcement Bottom Beam	X Repair	180.00	X
2 Pcs. Front Bumper Reinforcement Bracket	X @ 95.00	190.00	X
1 Pc. Front Bumper Sponge	/ CAA NN	210.00	/
2 Pcs. Front Bumper Side Retainer	/ BR @ 125.00	250.00	/
1 Pc. Front Bumper Grille	/ BR	210.60	/
1 Pc. Front Bumper Grille Chrome	/ SCR	129.50	/
2 Pcs. Front Fog Lamp	X NN @ 499.00	998.00	X



ALFRED AUTO

Services & Supplies

Bik 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre & Sports Rim



2 Pcs. Front Fog Lamp Grille	UH / SCR, PHXNN	@ 205.00	410.00	205
2 Pcs. Front Fog Lamp Grille Chrome	SCR	@ 135.00	270.00	
1 Pc. Front Lower Chrome	SCR		299.80	
2 Pcs. Front Side Chrome	SCR	@ 78.00	156.00	
1 Pc. Front No. Plate Garnish	CRA		98.50	
1 Pc. Front Bumper Lower Cover	TN		295.00	
2 Pcs. Front Parking Sensor	2PCS NW	@ 228.00	912.00	456
1 Pc. Rear Boot	X Repair		897.80	X
1 Pc. Rear Boot Lock	X		199.50	X
2 Pcs. Rear Boot Lamp	X GNN	@ 220.00	440.00	X
1 Pc. Rear Boot Logo			110.20	
1 Pc. Rear Boot Passat Emblem			95.30	
1 Pc. Rear Boot Opener Handle	X		199.00	X
1 Pc. Rear End Panel	X Repair		405.00	X
1 Pc. Rear Weather Stripe	X GNN		196.50	X
1 Pc. Rear Panel Garnish	X		288.00	X
2 Pcs. Rear Lamp	UH / CRA, PHXNN	@ 435.00	870.00	435
1 Pc. Rear Bumper	re		910.00	
1 Pc. Rear Bumper Sponge	CRA		318.50	
1 Pc. Rear Bumper Reinforcement	X Repair		422.00	X
2 Pcs. Rear Bumper Bracket	re	@ 105.00	210.00	
2 Pcs. Rear Bumper Retainer	X NN	@ 148.00	296.00	X
10 Pcs. Rear Bumper Clips	nb	@ 8.00	80.00	
1 Pc. Rear Bumper Centre Chrome	SCR		210.00	
2 Pcs. Rear Bumper Side Chrome		@ 132.00	264.00	
1 Pc. Rear Bumper Lower Spoiler	re		198.30	
1 Pc. Coolant	nb		120.00	40 (Snett)
2 Sets. Front & Rear No. Plate & Box	Cut	@ 70.00	140.00	80 (SN)
4 Pcs. Rear Parking Sensor	2PCS DM	@ 288.00	912.00	576
1 Pc. Rear Exhaust	X Repair		699.80	X
2 Pcs. Rear Reflector	X NN		180.00	90.00 X

Total (Panels / Parts):

23,696.90 (SGD)

14736.6
-10%: 13262.94

LABOR CHARGES

To check wiring & remove & refit all accident affected
Wiring & coding system.

280.00

50.00
30



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No: 161219

Date: 16.12.2019

Lim Heok Long Clifton
156 Joo Chiat Terrance #04-04
Singapore 427303
Volkswagen Passat B8 1.8

Supplementary Repair Cost for Vehicle Reg. No: SLZ 3803 B

REPLACEMENT OF DAMAGED PANELS / PARTS

1 Set Parking Sensor (Front) Bracket	89.00
1 Set Parking Sensor Bracket	89.00

Total (Panels / Parts): 178.00 (SGD)

TOTAL COST SUMMARY


PANELS / PARTS

178.00

Grand Total: 178.00 (SGD)

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'ALFRED AUTO SERVICES & SUPPLIES'.


ALFRED AUTO SERVICES & SUPPLIES



ALFRED AUTO

Services & Supplies

Bk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com



To remove & refit radiator, hose, pipe & all affected Accident area.	180.00	180.00
To remove & refit air-con condenser check & top-up Gas & oil.	200.00	100.00
To remove & refit interior garnish, side board garnish & all affected area.	250.00	60.00
To knocking, straightening repair & renew all accident affected area.	2,200.00	800.00
To respray painting on all accident affected area.	2,400.00	900.00
To rust proof all accident affected area.	300.00	300.00
Total (Labor Charges):		<u>5,810.00 (SGD)</u> 189.00

TOTAL COST SUMMARY

PANELS / PARTS	23,696.90
LABOR CHARGES	5,810.00
Grand Total:	<u>29,506.90 (SGD)</u>

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'ALFRED AUTO SERVICES & SUPPLIES'.

SN: 120

control
ALFRED AUTO SERVICES & SUPPLIES

Total: 15433.14

6 Days.