

X 25000

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SLF3191M
 MODEL : HONDA VEZEL
 DATE OF ACCIDENT : 16.12.19
 TIME OF ACCIDENT : 08:30HRS

29	REAR FLOOR PANEL BOTTOM GARNISH	1	\$ 269.00	\$ 269.00
30	REAR FLOOR PANEL TOP BOARD	1	\$ 300.40	\$ 300.40
31	REAR STORAGE SPONGE	1	\$ 106.00	\$ 106.00
32	EDLC MODULE	1	\$ 984.00	\$ 984.00
33	REAR CHASSIS MEMBER LH	1	\$ 797.40	\$ 797.40

TOTAL PRICE \$ 12,873.30
 LESS 20% \$ 2,574.66
 SUB TOTAL PRICE \$ 10,298.64

8263.60
 1652.72
 6610.88

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE (SET)	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS (SET)	1	\$ 80.00	\$ 80.00
3	TAILGATE OUTER GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
4	TAILGATE INNER TRIM BOARD CLIP (SET)	1	\$ 80.00	\$ 80.00
5	TAILGATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00
6	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
7	TAIL LAMP CLIP (SET)	1	\$ 40.00	\$ 40.00
8	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 80.00	\$ 80.00
9	REAR FENDER COWLING CLIP (SET)	1	\$ 80.00	\$ 80.00
10	REAR FENDER ARCED GARNISH CLIP (SET)	1	\$ 80.00	\$ 80.00
11	REAR END PANEL TOP GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
12	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00
13	REAR FLOOR PANEL SEALANT	1	\$ 350.00	\$ 350.00
14	REAR FLOOR PANEL BOTTOM GARNISH CLIP (SET)	1	\$ 80.00	\$ 80.00
15	REVERSE SENSOR	1	\$ 220.00	\$ 220.00
16	REVERSE CAMERA	1	\$ 450.00	\$ 450.00

TOTAL \$ 1,980.00

500

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	1200
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1000
3	TUFF COAT	\$ 250.00	60
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	80

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SLF3191M
 MODEL : HONDA VEZEL
 DATE OF ACCIDENT : 16.12.19
 TIME OF ACCIDENT : 08:30HRS

5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
7	REAR CHASSIS ALIGNMENT	\$ 250.00	+
8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	+
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
10	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	+
12	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ 80.00	+
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	+

TOTAL \$ 5,250.00 2640 -

TOTAL PARTS COST : \$ 12,278.64
 TOTAL LABOUR COST : \$ 5,250.00
 TOTAL REPAIR COST : \$ 17,528.64

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

6610.88
 500
 2640

9750.88
 1950.18

7800.70

Adrian L
 h/s 17/12/19

09 Pm/s.