

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 1576Z

DATE : 13.12.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Indig

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper scr / distorted			\$ 553.00
	Rear Bumper Clip 10 pcs scr / huc			\$ 22.00
	Rear Bumper Bracket, RH scr huc huc			\$ 35.60
	Tail Lamp (RH) scr / scratched			\$ 697.80
	Rear Fender With Housing (RH) scr / Dented		2020.00	\$ 4,736.80
	Rear Fender Inner Lining (RH) ? huc			\$ 169.30
	Rear Fender Air-Duct X huc			\$ 51.60
	Rear Windscreen Moulding scr / huc			\$ 28.30
	Rear Tyre Rim (RH) X distorted			\$ 325.30
	Rear Wheel Hup-Cap (RH) scr / cut			\$ 107.10
	Rear Wheelbearing ING & Hub 2. Dam			\$ 362.00
	Rear Trailing Arm (RH) X distorted			\$ 192.00
	Rear Assist (RH) X distorted			\$ 145.70
	Rear Shock Absorber (RH) X distorted			\$ 276.30
	Rear Shock Absorber Mounting (RH) X huc			\$ 81.30
	Rear Crossmember X huc			\$ 1,021.50
	Stabilizer Bar X huc			\$ 199.60
	Stabilizer Link X huc			\$ 85.90
	Rear Upper Arm (RH) X distorted			\$ 335.75
	Rear Lower Arm (RH) X distorted			\$ 353.80
	Rear Knuckle Arm (RH) scr / distorted			\$ 545.60
			5964.65	
			4771.72	
	SUB TOTAL			\$ 10,326.25
	LESS 20%			\$ 2,065.25
	DISCOUNTED TOTAL			\$ 8,261.00
	Rear Bumper Advertisement Logo scr / huc			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) scr / huc		\$ 100.00	\$ 200.00
	Rear Windscreen Sealant scr / huc			\$ 46.00
	Rear Tyre (RH) X huc 296.00			\$ 216.00
				\$ 512.00
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 750.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Undercarriage (RR)			\$ 200.00
	Rear Wheel Alignment			\$ 120.00
	Re-set Rear ABS System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
				\$ 3,320.00
	TOTAL LABOUR			\$ 3,320.00
	ESTIMATE TOTAL			\$ 12,093.00

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

\$ 100.00

Hp 900/10068

8 1/2 days

1/5

16/12/19 @ 1140

Rear after repair

6637.72

1/5 5300

Nett ✓

Nett ✓

Nett ✓

Nett X

600

400

30

401-

60

801-

80 1501-

60

60

150 & ?