-	-	
ν	II	٠.
га		R S.

Paint Work	SYSTEM AZT		Tin	ne Basis	s 10 WU/h
Code	Description - TWO COAT METALLIC			WU	Price SGD
	FRONT BUMPER REPAIR PAINT PLASTIC L/F WING REPAIR PAINTING <50%			15.0 10.0	
Paint Materi	al Per Part				
Code	Description				Price SGD
0283 0741	FRONT BUMPER REPAIR PAINT PLASTIC L/F WING REPAIR PAINTING <50%				43.74 10.66
	Labour Cost - Paint Factor Time Paint	45.00 SGD/h	Hrs	wu	Price SGD
	Preparation Main Work Metal Preparation Comp. Work Plastic Total	10 WU/h	2.50 0.80 5.80	25.0 25.0 8.0 58.0	112.50 36.00 261.00
	Material Cost - Paint Repair Painting Repair Painting Plastic Material-constant Metal Preparation Material-constant Plastic Total				Price SGD 10.66 43.74 28.60 12.70 95.70

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01 Price SGD
7053 7081 7087 7117 7271	L/LOWER CONTROL ARM J L/F STEERING KNUCKLE JL/F STRUT JL/F WHEEL BEARING L/F OUT STABI MNTG	151360SAAJ01 51215SAAE10 51606SAA014 44300SAA003 51321SAAJ01	get get	135.00 ? 165.00 ? 95.00 ? 85.00 ? 50.00?
f: OEM Parts n: Non-OEM Par u: Used parts	Savings ts Subtotal Addition(+10.00%)			0.00 530.00 53.00
	Total			583.00

For un rade end \$65 Fen un tie rod end \$60

Us \$ 1202.50

Final Calculation

	SGD	SGD
Parts	530.00	
Addition(+10.00%)	53.00	
Total Parts		583.00
Labour Time Base 10 WU/h		
Total 43.0 WU X 45.00 SGD/h	193.50	
Fixed Rate	15.00	
Total of Labour	15.00	208.50
Paint Work Time Base 10 WU/h		
Labour Cost 58.0 WU X 45.00 SGD/h	261.00	
Material Cost	95.70	
Total Paint Including Material	33.70	356.70
Repair Cost Excludes GST		1,148.20
GST (+7.0%)		
Repair Cost Included GST		80.37
		1,228.57

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Audatex System Using Manufacturer Times

Page 3 of 3

PRINT DATE 17/12/2019

Adrian Li L/S 17/12/19. 04Py Excess: \$500 Authorised Reports.

SME Motor Pte Ltd 1 Kaki Bukit Ave 6, BLK D, #02-15 417883

Insurer Reference:

Full Report Registration: SJE6477Z Repairer Reference: 19/AXA/0D-601(12) Printed: 17/12/2019 11:13 AM Date calculated: 12/12/2019 5:04 PM

Summary Information

Claim

Location: Printed by: Singapore (SG) Gary Seah

Work Provider: Currency:

AXA Insurance Pte Ltd SGD 11/12/19

Claim Reference: Estimated Repair Time: Actual Repair Days:

Date of Incident: Hire Car Start: Hire Car End:

Vehicle Details

Vehicle

Manufacturer: Model:

HONDA FIT

Sub Model:

BASE MODEL 35 50 01

Model Sheet Number: Registration: VIN number:

SJE6477Z

Odometer: **Model Specs**

TWO COAT METALLIC

PREPARE OFF VEHICLE

Labour

	Time Base 10 WU/h	Price = 45	5.00 SGD/h
Code	Description	WU	Price SGD
4161C5)	R + R L/STABILIZER ROD	1.0	4.50
4161C7)	R + R L/- AND R/STABILIZER ROD	2.0	9.00
4151A2)	R + R LEFT FRONT WHEEL BEARING INCLUDES: R + R WHEEL, BRAKE DISC, STEERING KNUCKLE AND WHEEL HUB	13.0	58.50
414105)	R + R L/F SUSPENSION STRUT CPL	6.0	27.00
219130)	DETACH + REFIT L/- AND R/DRIVE SHAFT	1.0	4.50
416118)	R + R L/F LWR CONTR ARM (WHEEL REMOVED)	6.0	27.00
414125)	DISS/ASS L/F SUSPENSION STRUT REMOVED	4.0	18.00
0283	FRONT BUMPER REPAIR	5.0*	22.50
0741	L/F WING REPAIR	5.0*	22.50
1000	L/F SPORTS RIM REPAIR		15.00*
	Labour Cost	Hrs WU	
	Panel / Mechanical Labour Fixed Rate	4.30 43.0	193.50 15.00
	Total of Labour		208.50

Paint

Paint Work	SYSTEM AZT			Time Basis 10 WU/l		
Code	Description - TWO COAT METALLIC			WU	Price SGD	
	FRONT BUMPER REPAIR PAINT PLASTIC L/F WING REPAIR PAINTING <50%			15.0 10.0		
Paint Materi	ial Per Part					
Code	Description				Price SGD	
0283 0741	FRONT BUMPER REPAIR PAINT PLASTIC L/F WING REPAIR PAINTING <50%				43.74 10.66	
	Labour Cost - Paint Factor Time Paint	45.00 SGD/h	Hrs	WU 25.0	Price SGD	
	Preparation Main Work Metal Preparation Comp. Work Plastic Total	10 WU/h	2.50 0.80 5.80	25.0 8.0 58.0	112.50 36.00 261.00	
	Material Cost - Paint Repair Painting Repair Painting Plastic Material-constant Metal Preparation Material-constant Plastic Total				Price SGD 10.66 43.74 28.60 12.70 95.70	

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01 Price SGD
7053	L/LOWER CONTROL ARM	51360SAAJ01		135.00
7081	L/F STEERING KNUCKLE			165.00
7087	L/F STRUT	51606SAA014		95.00
7117	L/F WHEEL BEARING	44300SAA003		85.00
7271	L/F OUT STABI MNTG	51321SAAJ01		50.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			530.00
u: Used parts	Addition(+10.00%)			53.00
	Total			583.00

Page 2 of 3

Final Calculation

	SGD	SGD
Parts	530.00	
Addition(+10.00%)	53.00	
Total Parts		583.00
Labour Time Base 10 WU/h		
Total 43.0 WU X 45.00 SGD/h	193.50	
Fixed Rate	15.00	
Total of Labour		208.50
Paint Work Time Base 10 WU/h		
Labour Cost 58.0 WU X 45.00 SGD/h	261.00	
Material Cost	95.70	
Total Paint Including Material		356.70
Repair Cost Excludes GST		1,148.20
GST (+7.0%)		80.37
Repair Cost Included GST		1,228.57

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.