



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving1 2008 HONDA FIT 1.3 (SJE6477Z)

Date of Loss10 December 2019

Time of Loss22.30

Loss DescriptionSJE6477Z (INSD) COLLIDED INTO PROPERTY

Comment

Workshop Details

Total Rebate Amount

13014

Nett Loss Amount\$6,986.00

Assigned WorkshopLKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion

20

*

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#	SJE6477Z	Purchase Date	<div>dd/mm/yyyy</div> <div>📅</div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>30/04/2008</div> <div>📅</div>
Mileage	<div>185304</div>	Age of Vehicle	11

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2008	<div>2008</div>
Make	HONDA	<div>HONDA</div>
Model	FIT 1.3	<div>FIT 1.3G A</div>
		<div></div>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	VINCENT TEOH	<div></div>
Date of Birth	26 September 1991	<div>dd/mm/yyyy</div> <div>📅</div>
Age	28	

Type	POLICY	ASSESSMENT INFORMATION
CATEGORY	INFORMATION	
Type of Paint		
Chassis No	GE61059204	GE61059204
Engine No	L13A4066724	L13A4066724
Engine Capacity		1339
Sum Insured	0	0
Market Value	0	20000

CATEGORY	ENROLLMENT INFORMATION
Education Qualification	Other
Driving Experience	9
Driver License #	
License Type	
License Issue Date	dd/mm/yyy
License Expiration Date	dd/mm/yyy
Address	BLK 687B CHOA CHUA KANG, #03-378, 682687, Singapore
Address type	Residential

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	<div>▼</div>
Marital status	Married	<div>▼</div>
Identification #	S9175066Z	<div></div>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

17/12/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Un
named Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

195/55R15

Front left side

GOODYEAR6mm

Front right side

GOODYEAR6mm

Rear Tyre Size

195/55R15

Rear left side

GOODYEAR6mm

Rear right side

GOODYEAR6mm

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="0"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		L/LOWER CONTROL ARM (WCP) (10%) (ADDITIONAL DISC 15%)	Bent	0	126.23	No		0			126.23	Reviewing	
<input type="checkbox"/>		0	1		L/F STEERING KNUCKLE (WCP) (10%) (ADDITIONAL DISC 15%)	Bent	0	154.28	No		0			154.28	Reviewing	
<input type="checkbox"/>		0	1		L/F STRUT (WCP) (10%) (ADDITIONAL DISC 15%)	Bent	0	88.83	No		0			88.83	Reviewing	
<input type="checkbox"/>		0	1		L/F WHEEL BEARING (WCP) (10%) (ADDITIONAL DISC 15%)	Damaged	0	79.47	No		0			79.47	Reviewing	
<input type="checkbox"/>		0	1		L/F OUT STABI MNTG (WCP) (10%) (ADDITIONAL DISC 15%)	Bent	0	46.75	No		0			46.75	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		L/TIE ROD (WCP) (10%) (ADDITIONAL DISC 15%)	Bent	0	60.77	No		0			60.77	Reviewing	
<input type="checkbox"/>		0	1		L/TIE ROD BALL JOINT (WCP) (10%) (ADDITIONAL DISC 15%)	Bent	0	56.1	No		0			56.1	Reviewing	







Labour

Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
<input type="checkbox"/>		0		75.0 WU X 45.00 SGD/H (ADDITIONAL DISC 15%)	0	286.87	0	0	Reviewing		
<input type="checkbox"/>		0		LABOUR COST 58.0 WU X 45.00 SGD/H (ADDITIONAL DISC 15%)	0	221.85	0	0	Reviewing		
<input type="checkbox"/>		0		MATERIAL COST (ADDITIONAL DISC 15%)	0	81.34	0	0	Reviewing		

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous


Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	0	DAYS OF REPAIR : 4 DAYS	Reviewing		0		



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$1,202.49

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$612.43
Labour	\$0.00	\$590.06

Submit for Review