


Section A - Accident Details

Registration Number	SHB5285G
Case Reference Number	TAX/12/19/2066
Registration Date	10/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LEE YONG SHENG
Type of Accident	Head To Side
Accident Date and Time	13/12/2019 3:00 PM
Accident Reported Date and Time	14/12/2019 11:29 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104875
Special Instruction to ARC, if any	TP
Prepared Date and Time	16/12/2019 9:54 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates
Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$500.00
Total Spray Cost	\$3,348.00	\$880.00
Total Spare Part Cost	\$15,271.47	\$3,138.42
Total Other Cost	\$720.00	\$120.00
TOTAL COST	\$20,015.47	\$4,638.42 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / EQ
ARC / Surveyor Sign Off Date	19/12/2019 11:39 AM	19/12/2019 2:26 PM
Signature		
Remarks	Total number of repair days = 4 days. SUP = 0 day.	P/P Repair, Take before spray photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1912-0464	Invoice Number	
Quotation Date	30.12.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$676.00	\$500.00 ✓
Total Labour	\$676.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$0.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY RIM	\$360.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00 ✓
TO RESPRAY REAR DOOR LH	\$378.00	\$200.00 ✓
RESPRAY MIRROR COVER LH	\$180.00	\$80.00 ✓
TO RESPRAY FRONT FENDER LH	\$378.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00 ✓
Total Spray Painting & Panel Beating	\$3,348.00	\$880.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00 ✓
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$20.00 ✓
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$720.00	\$120.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		4261147450	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given X
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X
		7586047900	MOULDING ASSY, BODY ROCKER PANEL, LH	1.00	\$576.00	100.00	\$0.00	Replace	Old Damage X
		6160247160	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$824.80	100.00	\$0.00	Replace	Repair R

SVC

SVC

nn

SMRT Accident Vehicle Repair Estimates

Date Generated : 27/12/2019

User ID : PohSuan

	4261147450	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X	SVC
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	SVC
	4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given	X	SVC
	6700247162	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,249.60	25.00	\$937.20	Replace	Replace	X	DD
	4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given	X	SVC
		STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	X	nec
	6861047040	CHECK ASSY, FRONT DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Check	X	SVC
	6921047051A1	DOOR OUTER HANDLE FRONT, LH	1.00	\$378.90	25.00	\$284.18	Replace	Replace	X	sch
	6872012151	HINGE ASSY, FRONT DOOR, UPPER LH	0.00	\$82.10	0.00	\$0.00	Replace	Check	X	SVC
	6874012120	HINGE ASSY, FRONT DOOR, LOWER LH	0.00	\$92.10	0.00	\$0.00	Replace	Check	X	SVC
	6700447210	PANEL SUB-ASSY, REAR DOOR, LH	1.00	\$1,243.90	25.00	\$932.93	Replace	Replace	X	DD
	8794047440	MIRROR ASSY, OUTER REAR VIEW, LH	0.00	\$1,283.90	0.00	\$0.00	Replace	Not Given	X	SVC
	8794547060A1	COVER, OUTER MIRROR, LH	1.00	\$89.50	100.00	\$0.00	Replace	Repair	X	
	6904047100	LOCK ASSY, FRONT DOOR LH	1.00	\$544.70	10.00	\$490.23	Replace	Replace	X	Jammed
	6941020110	DOOR LOCK STRIKER	0.00	\$38.00	0.00	\$0.00	Replace	Not Given	X	SVC
	6941020110	DOOR FRONT WINDOW REGULATOR SUB-ASSY,	0.00	\$230.80	0.00	\$0.00	Replace	Check	X	Jammed
	8572047140	DOOR FRONT MOTOR ASSY, POWER WINDOW	0.00	\$768.60	0.00	\$0.00	Replace	Check	X	
	5211947962	COVER, FR BUMPER	0.00	\$495.50	0.00	\$0.00	Replace	Not Given	X	SVC
	5211547050	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Not Given	X	
	5211647050	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given	X	
	5311247240	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Not Given	X	
	5216116010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given	X	SVC
	5142047030	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given	X	
	5141047020	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$452.80	0.00	\$0.00	Replace	Not Given	X	
	5144747030	COVER, ENGINE UNDER CENTER	0.00	\$94.50	0.00	\$0.00	Replace	Not Given	X	
	5310147080	GRILLE SUB-ASSY	0.00	\$335.60	0.00	\$0.00	Replace	Not Given	X	SVC
	5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair	X	
	5216116010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given	X	
	5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Not Given	X	
	5219147030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given	X	
	5246247030	PAD, RR BUMPER, RH & LH, 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given	X	
	5246247020	PAD, RR BUMPER, RH & LH, 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given	X	
	5246247010	PAD, RR BUMPER, RH & LH, 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given	X	SVC
	5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given	X	
	5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given	X	
	5259147050	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X	
	5259247040	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X	
		PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	X	nec
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X	
	5245347010	GUARD, RR BUMPER, LOWER	0.00	\$558.30	0.00	\$0.00	Replace	Not Given	X	SVC
	5256547900	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X	

		52566479 00	FILLER, RR BUMPER , LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X
		81561471 51	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
		81591470 10	LENS & BODY ASSY , RR BUMPER , LH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
		53802471 00	FENDER SUB-ASSY, FR , LH	0.00	\$933.10	0.00	\$0.00	Replace	Not Given	X
		53876471 10	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Not Given	X
		53852470 41	PAD, FR WHEEL LH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given	X
Total					\$18,281.98		\$2,824.54			

} SVC

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		68418201	DOOR FRONT WINDOW	1.00	\$288.00	25.00	\$216.00	Replace	Replace
		85720471	REGULATOR SUB-ASSY,	0.00	\$768.00	0.00	\$0.00	Replace	Not Given
		40	ASSY, POWER WINDOW						
		69202470	DOOR FRAME INNER	1.00	\$187.70	25.00	\$140.78	Replace	Replace
		40	HANDLE FRONT , LH						
Total					1,187.10		313.88		

✓ nec

3138.42
+ 500.00
+ 1000.00

4638.42

23,273.68#

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: