

KT GARAGE PTE LTD UEN: 201906115R

Auto Bay@ Kaki Bukit Entrance A

BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

Date : 14/12/2019

Total Pages : 1

TO: **AIG Asia Pacific Pte Ltd**
 AIG Building, 78 Shenton Way#08-16
 Singapore 079120

Our Customer : Global Advance Leasing

Vehicle No : SLN40366

Model : Audi A4

Manufacture Year : 2017

Date of Accident : 11/12/2019

Total Estimate Repair Days : 7

Attn : Motor Claim Department


Email :

Re: Repair Estimate For Third Party Claim against : GN5321J

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



| No. | Item Descriptions | Qty | Unit Price | Amount | Remarks From Surveyor |
|-----------|---|---------|------------|-------------------|-----------------------|
| A. | Spare Parts | | | | |
| 1 | Rear bumper ✓ cut | 1 | \$1,500.00 | \$1,500.00 | |
| 2 | Rear bumper clips ✓ nec | 10 | \$8.00 | \$80.00 | 30 |
| 3 | Rear bumper lower extension ✓ (scr) | 1 | \$450.00 | \$450.00 | |
| 4 | Rear bumper chrome moulding X | 1 | \$480.00 | \$480.00 | |
| 5 | Rear bumper tow cover X (svc) | 1 | \$58.00 | \$58.00 | |
| 6 | Rear bumper reverse sensor ✓ short | 1 (set) | \$280.00 | \$280.00 | |
| 7 | Rear bumper reverse sensor holder ✓ nec | 1 (set) | \$45.00 | \$45.00 | |
| 8 | Rear bumper side retainer X (svc) | 2 | \$80.00 | \$160.00 | |
| 9 | Rear bumper reflector X (svc) | 2 | \$285.00 | \$570.00 | |
| 10 | Rear bumper foam X (svc) | 1 | \$80.00 | \$80.00 | |
| 11 | Rear bumper stay X (svc) | 1 | \$150.00 | \$150.00 | |
| 12 | Rear bumper beam X (svc) | 1 | \$560.00 | \$560.00 | |
| 13 | Rear end panel X (R) | 1 | \$750.00 | \$750.00 | |
| 14 | Rear bootlid ✓ B+ | 1 | \$1,700.00 | \$1,700.00 | |
| 15 | Rear boot lock ✓ sm | 1 | \$250.00 | \$250.00 | |
| 16 | Rear boot striker X (svc) | 1 | \$75.00 | \$75.00 | |
| 17 | Rear boot weatherstrip X (svc) | 1 | \$420.00 | \$420.00 | |
| 18 | Rear boot reflector X (svc) | 2 | \$290.00 | \$580.00 | |
| 19 | Rear boot control switch X (svc) | 1 | \$500.00 | \$500.00 | |
| 20 | Rear number plate lamp X (svc) | 1 | \$38.00 | \$38.00 | |
| 21 | Rear boot 'A4' emblem ✓ nec | 1 | \$128.00 | \$128.00 | |
| 22 | Rear boot 'TFSI' emblem ✓ nec | 1 | \$128.00 | \$128.00 | |
| 23 | Rear boot logo ✓ nec | 1 | \$148.00 | \$148.00 | |
| 24 | Rear number plate ✓ scr | 1 | \$55.00 | \$55.00 | |
| | Sub Total | | | \$9,185.00 | |
| | Less 20% | | | \$1,837.00 | |
| | Sub Total 1 | | | \$7,348.00 | |
| B. | Labour | | | | |
| 1 | To knock and straighten necessary portion. To remove and renew damaged panel. To adjust and realign the same | | \$800.00 | \$800.00 | 500 |
| 2 | To putty and spray all affected areas | | \$450.00 | \$450.00 | 450 |
| 3 | To remove and refit bootlid trim board, lock mechanism, wire harness, garnish, and conduct water test and window noise test ✓ | | \$180.00 | \$180.00 | 40 |
| 4 | To do water seepage test ✓ | | \$80.00 | \$80.00 | 50 |
| 5 | To rust proof all affected areas ✓ | | \$80.00 | \$80.00 | 20 |
| 6 | To check wiring and all lighting ✓ | | \$60.00 | \$60.00 | 30 |
| | Total Labour | | | \$1,320.00 | |
| | Total Repair Cost | | | \$8,668.00 | |

1/5 mpr
 without pre-judge
 4 day
 Repair after part
 Hock ANN
 P5314823
 3.45pm
 16/12/19
 Hock ANN @ LKK Auto Consultants