

INS. CASE OWNER:

CC 4 / FCI190 221A1, Feb 9

LKK:

IDAC:

Surveyor:

STG

DOI:

18/1/19

Date / Time:

17/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SHA 3007L

Name of Insured :

LTPV

Insured Tel No. :

HP:

Excess Sec II :S\$

D.O.A :

10/12/18

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

VET RUCK KHOOV PETER

Driver Tel No. :

(V/L: YES / NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

0190889264 FSK

MERIDORS

WESTKONT KH

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SFD 838BA



INSRS:

WSP:

Tel :

Liability :

RMKS:

STUTGART



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/Time

SPD 838BA

SHA 3007L

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Cty

Repair Cost:

PP \$56,019.86

(3 days) Reduction:

25 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 02.03.20

Confirm with Services:

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 22

If NO or B 28, Ass. Lia :

Repair Cost:

GIA: \$56,505.45

OIO HIR TP PAIDED YEM

Loss of Rental (LOR):

\$5 -

(days)

Loss of Use (LOU):

\$5 450.00

(\$50 x 3 days)

Loss of Income (LOI):

\$5 -

(\$5 x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

\$57.45

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost

\$5 -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: -B

3) Survey fee: 350

Total:

\$56,962.90

Global Sum S\$:

FINAL PAYMENT

Date/Time: 02.03.20

Confirm with: -HARRIS

Email ☒ Call ☐

Payee 1:

\$56,962.90

Name 1:

STUTTGART AUTO RE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

Steve

FCL

ASSIGNMENT

Date: 18.12.2019

Veh No: SFD 8383A

Regn: 14/7/17

Policy No:

Type: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Insured: ☒ TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

Inspected Vehicle No: SFD 8383A

Make: Porsche Cayenne

EC: 3598

Workshop info: Euro Cars Group

Colour: Grey

A/C: Insured / Std / NI / NA

27 A Tanjung Perak

Sp Reading: 49907

T/Radio: Insured / Std / NI / NA

Insured:

Eng No:

Policy No:

C No:

Claims No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

2pm omv waly

Mod: Nil / S/Rim / STD A/Rim or

L310693

Tyre Size:

F:

265/50R19

R:

1

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

5

mm

L/Bal:

5

mm

D.O.A:

10/12/19

D.O.I:

18/12/19

Survey held at:

Trans Eureka

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Front RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction

MV- 280k

Pp: +6.079.86 (Red: +2.031.33 20%)

Date/Time, File Path for:

☐

Preli. Report

Days Of Repair:

☐

Final Report

Resurvey No. of Trip:

Survey Fee:

Transportation

Date/Time, File Path for:

Date/Time, File Path for:

Acid Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Insp: \$

☐

Welding: \$

Photo:

Video:

Other:

Total:



PORSCHE

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

ELROKARS GROUP

MS FIRST CAPITAL INSURANCE LTD 6 Raffles Quay #21-00 Singapore 048580		NAME: Mr Teo Ho Soon ADDRESS: 533 Bedok Reservoir Road #05-114 Singapore 479283 TEL:		WIP: 53834 EXCESS: DATE: 13-Dec-19	
ATTN.: MOTOR CLAIMS FAX:		VEH NO: SFD8383A CHASSIS NO: WP1ZZZ92ZHKA89911 MODEL: Cayenne		DATE IN: MILEAGE: DATE REG.: 14.07.2017 CONTACT PERSON: EVA TYPE OF CLAIM: TP POLICY NO.: 63310683	
NATURE OF WORKS					
S/NO	Parts Description			REVISED	PRICES
		QTY			
1	FRONT BUMPER / DD	1	P958-505-217-07-G2X		\$ 1,557.20
2	BUMPER GRILLE FRAME RH X / OR	1	P958-505-682-40-989		\$ 129.20
3	AIR DUCT OUTER RH / CUT	1	P958-505-946-00-		\$ 233.00
4	GRILLE FRAME COVER RH ? / OR	1	P958-505-484-50-		\$ 218.60
5	CLIP X MR	2	P999-507-836-09-		\$ 2.60
6	GRILLE GARNISH UPPER RH X N/A	1	P958-505-686-40-989		\$ 60.50
7	GRILLE GARNISH LOWER RH X N/A	1	P958-505-686-45-989		\$ 60.50
8	SENSOR ? X N/A	1	P5Q0-919-275-B -G2X		\$ 238.50
9	GASKET X N/A	1	P5Q0-919-133- -989		\$ 2.60
10	NUT X N/A	2	PN -902-184-03-		\$ 9.00
11	FOG LAMP COVER RH ? / OR	1	P958-505-824-00-989		\$ 49.20
12	WHEEL ARCH COVER RH / CUT	1	P958-559-728-20-989		\$ 408.80
13	ADDITIONAL HEADLAMP RH X N/A	1	P958-631-182-31-		\$ 828.30
14	OVAL-HEAD SCREW X N/A	4	PWHT-003-954- -		\$ 3.20
TOTAL PARTS					\$ 3,801.20
TOTAL PARTS COST					\$ 3,801.20
Labour Description					
1	TO REPLACE FRONT BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. 1560 x 1			1560	\$ 2,340.00
2	TO RESPRAY FRONT BUMPER. / x 1300			1300	\$ 1,500.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			NETT	\$ 200.00
4	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			NETT	\$ 600.00
5	SUNDRIES. N/A			NETT	\$ 50.00
TOTAL LABOUR				\$ -	\$ 4,690.00
TOTAL PARTS				\$ -	\$ 3,801.20

TOTAL	\$ -	\$ 8,491.20
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

***DISCLAIMER**

- 1 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.
- 2 TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.
- 3 THIS IS ONLY AN ESTIMATE BASED ON PARTS AVAILABILITIES AT CURRENT LOCAL SINGAPORE WAREHOUSE. IF THERE IS A NEED TO INCLUDE AIRFREIGHT PARTS, WE WILL INFORM DULY.

Steve CLKKJ - Val R/L

18/12/19, 2.30pm

3 days

Ry R/L S/L

PIP



PORSCHE

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
SUPPLEMENTARY



MS FIRST CAPITAL INSURANCE LTD 6 Raffles Quay #21-00 Singapore 048580		NAME : Mr Teo Ho Soon		WIP : 53834	
ATTN. : MOTOR CLAIMS		ADDRESS : 533 Bedok Reservoir Road #05-114 Singapore 479283		EXCESS :	
FAX :		TEL :		DATE: 15-Jan-20	
VEH NO :	SFD8383A	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP1ZZZ92ZHKAB9911	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Cayenne	DATE REG.:	14.07.2017	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description				
	QTY			REVISED	PRICES
1	HEADLAMP CONNECTOR HOUSING / DR	2	L3C0-973-737- -	NON DISCOUNT	\$ 53.46
TOTAL PARTS					\$ 53.46
TOTAL PARTS COST					\$ 53.46
Labour Description					
TOTAL LABOUR				\$ -	\$ -
TOTAL PARTS				\$ -	\$ 53.46
TOTAL				\$ -	\$ 53.46
LESS EXCESS				\$ -	\$ -
TOTAL AFTER EXCESS				\$ -	
GST 7%				\$ -	\$ -
GRAND TOTAL				\$ -	\$ -

***DISCLAIMER**

- 1 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.
- 2 TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.
- 3 THIS IS ONLY AN ESTIMATE BASED ON PARTS AVAILABILITIES AT CURRENT LOCAL SINGAPORE WAREHOUSE. IF THERE IS A NEED TO INCLUDE AIRFREIGHT PARTS, WE WILL INFORM DULY.

P- 2336.40
Supp- 53.46
L- 3590
6079.86



PORSCHE

STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION COST OF REPAIRS



MS FIRST CAPITAL INSURANCE LTD		NAME : Mr Teo Ho Soon		WIP : 53834	
6 Raffles Quay #21-00		ADDRESS : 533 Bedok Reservoir Road		EXCESS :	
Singapore 048580		#05-114		DATE : 13-Dec-19	
ATTN. : MOTOR CLAIMS		TEL :			
FAX :					
VEH NO :	SFD8383A	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP1ZZ292ZHK89911	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Cayenne	DATE REG.:	14.07.2017	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description				
	QTY		REVISED	PRICES	
1	FRONT BUMPER	1	P958-505-217-07-G2X	\$ 1,557.20	\$ 1,557.20 ✓
2	BUMPER GRILLE FRAME RH	1	P958-505-682-40-989	\$ 129.20	\$ 129.20 ✓
3	AIR DUCT OUTER RH	1	P958-505-946-00-	\$ 233.00	\$ 233.00 ✓
4	GRILLE FRAME COVER RH	1	P958-505-484-50-	\$ 218.60	\$ 218.60 ✓
5	CLIP	2	P999-507-836-09-	\$ -	\$ 2.60 X
6	GRILLE GARNISH UPPER RH	1	P958-505-686-40-989	\$ -	\$ 60.50 X
7	GRILLE GARNISH LOWER RH	1	P958-505-686-45-989	\$ -	\$ 60.50 X
8	SENSOR	1	P5Q0-919-275-B -G2X	\$ -	\$ 238.50 X
9	GASKET	1	P5Q0-919-133- -989	\$ -	\$ 2.60 X
10	NUT	2	PN -902-184-03-	\$ -	\$ 9.00 X
11	FOG LAMP COVER RH	1	P958-505-824-00-989	\$ 49.20	\$ 49.20 ✓
12	WHEEL ARCH COVER RH	1	P958-559-728-20-989	\$ 408.80	\$ 408.80 ✓
13	ADDITIONAL HEADLAMP RH	1	P958-631-182-31-	\$ -	\$ 828.30 X
14	OVAL-HEAD SCREW	4	PWHT-003-954- -	\$ -	\$ 3.20 X
TOTAL PARTS				\$ 2,596.00	\$ 3,801.20
LESS 10%				\$ 259.60	\$ 380.12
TOTAL PARTS COST				\$ 2,336.40	\$ 3,421.08
SUPPLEMENTARY PARTS NO DISCOUNT					
1	HEADLAMP CONNECTOR HOUSING	2	L3C0-973-737- -	\$ 53.46	\$ 53.46
TOTAL PARTS COST				\$ 2,389.86	
Labour Description					
1	TO REPLACE FRONT BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 1,560.00	\$ 2,340.00
2	TO RESPRAY FRONT BUMPER.			\$ 1,300.00	\$ 1,500.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 200.00	\$ 200.00
4	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 600.00	\$ 600.00
5	SUNDRIES.			\$ 30.00	\$ 50.00
TOTAL LABOUR				\$ 3,690.00	\$ 4,690.00

TOTAL PARTS	\$ 2,389.86	\$ 3,421.08
TOTAL	\$ 6,079.86	\$ 8,111.08
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ 6,079.86	
GST 7%	\$ 425.59	\$ -
GRAND TOTAL	\$ 6,505.45	\$ -

Number of days: 3 Working days (Exclude waiting for survey, authorization, parts, sat, sun & ph)

Like Auto Collision must notify the Resurveyor of the following:

- To resurvey before after body painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No second modification(s) is allowed
- Inventory items must be resurveyed and subject to final approval from Insurance Company

acknowledged by Reparer

Signature:

Date:



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

MS FIRST CAPITAL INSURANCE LTD 6 Raffles Quay #21-00 Singapore 048580		NAME : Mr Teo Ho Soon	WIP : 53834
ATTN : MOTOR CLAIMS		ADDRESS : 533 Bedok Reservoir Road #05-114 Singapore 479283	EXCESS : DATE: 13-Dec-19
FAX :		TEL :	
VEH NO :	SFD8383A	DATE IN :	CONTACT PERSON : EVA 63310683
CHASSIS NO :	WP1ZZZ92ZHK89911	MILEAGE :	TYPE OF CLAIM : TP
MODEL :	Cayenne	DATE REG.:	POLICY NO. :

NATURE OF WORKS

S/NO	Parts Description					
		QTY			REVISED	PRICES
1	FRONT BUMPER / DD	1		P958-505-217-07-G2X		\$ 1,557.20
2	BUMPER GRILLE FRAME RH * ?	1		P958-505-682-40-989		\$ 129.20
3	AIR DUCT OUTER RH / CUT	1		P958-505-946-00-		\$ 233.00
4	GRILLE FRAME COVER RH ?	1		P958-505-484-50-		\$ 218.60
5	CLIP / MSC	2		P999-507-836-09-		\$ 2.60
6	GRILLE GARNISH UPPER RH X	1		P958-505-686-40-989		\$ 60.50
7	GRILLE GARNISH LOWER RH X	1		P958-505-686-45-989		\$ 60.50
8	SENSOR ?	1		P5Q0-919-275-B -G2X		\$ 238.50
9	GASKET X	1		P5Q0-919-133- -989		\$ 2.60
10	NUT X	2		PN -902-184-03-		\$ 9.00
11	FOG LAMP COVER RH ?	1		P958-505-824-00-989		\$ 49.20
12	WHEEL ARCH COVER RH / CUT	1		P958-559-728-20-989		\$ 408.80
13	ADDITIONAL HEADLAMP RH X	1		P958-631-182-31-		\$ 828.30
14	OVAL-HEAD SCREW X	4		PWHT-003-954- -		\$ 3.20
TOTAL PARTS						\$ 3,801.20
TOTAL PARTS COST						\$ 3,801.20
Labour Description						
1	TO REPLACE FRONT BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. 1560 x 1				1560	\$ 2,340.00
2	TO RESPRAY FRONT BUMPER. X 1300				1300	\$ 1,500.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				NETT	\$ 200.00
4	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				NETT	\$ 600.00
5	SUNDRIES.				NETT	\$ 50.00
				TOTAL LABOUR	\$ -	\$ 4,690.00
				TOTAL PARTS	\$ -	\$ 3,801.20

TOTAL	\$ -	\$ 8,491.20
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

***DISCLAIMER**

- 1 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.
- 2 TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.
- 3 THIS IS ONLY AN ESTIMATE BASED ON PARTS AVAILABILITIES AT CURRENT LOCAL SINGAPORE WAREHOUSE. IF THERE IS A NEED TO INCLUDE AIRFREIGHT PARTS, WE WILL INFORM DULY.

Store (LKK) WPL Rm
18/12/19, 2.30pm
3 days
Ry BrL Spj
P/P


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	801C

Vehicle Details

Vehicle No.:	SFD8383A
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Dec 2019
Vehicle Make:	PORSCHE
Vehicle Model:	CAYENNE V6 (E2-II) TIP E5
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	032151
Chassis No.:	WP1ZZZ92ZHKA89911
Maximum Power Output:	220.0 kW (295 bhp)
Open Market Value:	\$83,405.00
Original Registration Date:	14 Jul 2017
First Registration Date:	14 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$122,129.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jul 2027
PARF Rebate Amount:	\$91,596.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jul 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,802.00
COE Rebate Amount:	\$37,691.00
Total Rebate Amount:	\$129,287.00

The information contained herein is correct as at 18 Dec 2019

OK

MOTOR SURVEY ASSIGNMENT

Date	12-12-2019	Our Ref No. D19007859MFSH
Accident Date	10-12-2019	Claim Type. Third Party
Insured Vehicle	SHA3007L	Third Party Vehicle. SFD8383A
Survey Location	27A TANJONG PENJURU	
Contact Person.	EVA KOK	
Contact No.	63310680/ 0	Fax No. 63310690
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	STUTTGART AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

P: EVA
 T: 16.12.19 3.41p.m
 R: MT
 G.V



PORSCHE

DISCHARGE VOUCHER

I/ We hereby acknowledge having received from the under-mentioned
Repairers my/our vehicle No: USD 8383A which has been
repaired to my satisfaction and I/we admit that the payment for such repairs
by **Stuttgart Auto Pte Ltd** is in full and final discharge of my claim under
policy number: _____ In respect of damage
caused to the said vehicle as a result of an accident that occurred on
10/10/2019 at Westmatt Road



Witnessed by Repairers

16/01/2020

Date:



Signature by Insured

16/01/2020

Date:

Porsche Centre Singapore
Stuttgart Auto Pte Ltd
Excluded Group of Companies
Company Reg. No. 199403745N

Corporate Head Office & Passenger
Services Centre
12 Selegie Road, Singapore 229468
Tel: 651 6363 0911 Fax: 651 6363 3911
Website: www.porsche.com.sg

City Centre
29 Long Road, Singapore 139095
Tel: 651 6472 4433 Fax: 651 6472 3101



PORSCHE

Date: 04 March 2020

Aftersales Centre

27A Tanjong Pagar
Singapore 609042
Telephone: (65) 6331 0700

FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road
#16-01 City House
Singapore 068877
Attn : Motor Claims Department

Claim No : **D19007859MFSH**

Our Ref : **SFD8383A**

Re: Accident involving SFD8383A & SHA3007L on 10/12/2019

Enclosed is the duly signed Discharge voucher for your perusal.

Please pay **Stuttgart Auto Pte Ltd** the sum of **\$6,962.90** as
and mail your cheque to **12 Sungei Kadut Avenue Singapore 729648.**

Yours faithfully,

Stephanie Loke
Manager – Service & Development
DID: 63310686
FAX: 63310690
e-mail: Stephanie.loke@eurokars.com.sg



PORSCHE

INSURANCE INVOICE

GST Reg No: M90364005A

CODE: F0020 FIRST
CUSTOMER: First Capital Insurance Limited
ADDRESS: 36 Robinson Road
#14-01 City House
Singapore 068877

PAGE NO: 1
DOCUMENT NO: 13205634
JOB NO: 53834
DATE IN: 13/01/2019
DATE PRINTED: 05/02/2020
CSO/OP CODE: Janice Syn
SVC MNT EXP: 13/07/2022

MODEL: Porsche Cayenne Tiptronic
CHASSIS NO: WP1ZZZ922HKA89911
ENGINE NO: 032151
DESCRIPTION: LTA Search Fee

REGN NO: SFD8363A
REGN DATE: 14/07/2017
MILEAGE: 50497

Item	Description	Unit	U/Price	Disc%	Con%	Amount
SUP	LTA SEARCH FEE			0.00		6.96

Parts 0.00
Sundries 0.00
Labour 6.96
Menus 0.00

Net 6.96
G.S.T. 7% 0.19
Total 7.45
Paid 0.00
Amount Due 7.45

All major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handling. Replaced parts that are removed from cars are to be collected within 5 working days failing which STUTTGART AUTO PTE LTD reserved the rights to dispose of these parts without further notice. Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

CASH / NETS / AMEX / VISA / MASTER
NO:

Customer Signature

STUTTGART AUTO PTE LTD

Authorised Signature

ORIGINAL COPY

Stuttgart Auto Pte Ltd
Company Reg. No. 198403740N

Porsche Centre Singapore
29 Leng Kee Road, Singapore 159099
Tel: (65) 6472 4433
www.porsche.com.sg

Aftersales Centre
27A Tanjong Pagar Road, Singapore 069042
Tel: (65) 6331 0700

Corporate Head Office
12 Dunger Kadut Avenue, Singapore 729048
Tel: (65) 6363 0911 Fax: (65) 6363 3911

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI19022191/Eea3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-03-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3007L	Veh. Inspected	SFD 8383A
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D19007859MFSH	Excess (\$)	0.00
Assign From	JOANNEY	Assign Date	17/12/2019

2. Vehicle Particulars & Condition

Make & Model	PORSCHE CAYENNE	c.c	3598
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WP1ZZZ92ZHKA89911	Colour	GREY
Odometer	49207	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	265/50 R19	MICHELIN	5 mm
L/H Front Tyre	265/50 R19	MICHELIN	5 mm
R/H Rear Tyre	265/50 R19	MICHELIN	5 mm
L/H Rear Tyre	265/50 R19	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/12/2019	Inspection Date	18/12/2019
Survey held at	27A TANJONG PENJURU		
Repairer	STUTTGART AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFD 8383A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DENTED	1,557.20	1,557.20
1	BUMPER GRILLE FRAME RH	BROKEN	129.20	129.20
1	AIR DUCT OUTER RH	CUT	233.00	233.00
1	GRILLE FRAME COVER RH	BROKEN	218.60	218.60
2	CLIP	NOT NECESSARY	2.60	-
1	GRILLE GARNISH UPPER RH	NOT NECESSARY	60.50	-
1	GRILLE GARNISH LOWER RH	NOT NECESSARY	60.50	-
1	SENSOR	NOT NECESSARY	238.50	-
1	GASKET	NOT NECESSARY	2.60	-
2	NUT	NOT NECESSARY	9.00	-
1	FOG LAMP COVER RH	BROKEN	49.20	49.20
1	WHEEL ARCH COVER RH	CUT	408.80	408.80
1	ADDITIONAL HEADLAMP RH	NOT NECESSARY	828.30	-
4	OVAL-HEAD SCREW	NOT NECESSARY	3.20	-
	LESS 10% DISCOUNT		-	-259.60
			3,801.20	2,336.40
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
2	HEADLAMP CONNECTOR HOUSING (ADDITIONAL) (SN)	BROKEN	53.46	53.46
			103.46	83.46
LABOUR				
	TO REPLACE FRONT BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		2,340.00	1,560.00
	TO RESPRAY FRONT BUMPER .		1,500.00	1,300.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		200.00	200.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		600.00	600.00
			4,640.00	3,660.00
GRAND TOTAL			8,544.66	6,079.86

Report Ref No. CC4/FCI19022191/Eea3q2

**RECOMMENDED COST OF REPAIRS****6,079.86**

Report Ref No. CC4/FCI19022191/Eea3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.