



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

MS FIRST CAPITAL INSURANCE LTD 6 Raffles Quay #21-00 Singapore 048580		NAME : Mr Teo Ho Soon		WIP : 53834	
ATTN. : MOTOR CLAIMS		ADDRESS : 533 Bedok Reservoir Road #05-114 Singapore 479283		EXCESS :	
FAX :		TEL :		DATE: 13-Dec-19	
VEH NO :	SFD8383A	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP1ZZZ92ZHKA89911	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Cayenne	DATE REG.:	14.07.2017	POLICY NO. :	

NATURE OF WORKS					
S/NO	Parts Description			REVISED	PRICES
		QTY			
1	FRONT BUMPER / DD	1	P958-505-217-07-G2X		\$ 1,557.20
2	BUMPER GRILLE FRAME RH * ?	1	P958-505-682-40-9B9		\$ 129.20
3	AIR DUCT OUTER RH / CUT	1	P958-505-946-00-		\$ 233.00
4	GRILLE FRAME COVER RH ?	1	P958-505-484-50-		\$ 218.60
5	CLIP / MC	2	P999-507-836-09-		\$ 2.60
6	GRILLE GARNISH UPPER RH X	1	P958-505-686-40-9B9		\$ 60.50
7	GRILLE GARNISH LOWER RH X	1	P958-505-686-45-9B9		\$ 60.50
8	SENSOR ?	1	P5Q0-919-275-B -G2X		\$ 238.50
9	GASKET X	1	P5Q0-919-133- -9B9		\$ 2.60
10	NUT X	2	PN -902-184-03-		\$ 9.00
11	FOG LAMP COVER RH ?	1	P958-505-824-00-9B9		\$ 49.20
12	WHEEL ARCH COVER RH / CUT	1	P958-559-728-20-9B9		\$ 408.80
13	ADDITIONAL HEADLAMP RH X	1	P958-631-182-31-		\$ 828.30
14	OVAL-HEAD SCREW X	4	PWHT-003-954- -		\$ 3.20
TOTAL PARTS					\$ 3,801.20
TOTAL PARTS COST					\$ 3,801.20
Labour Description					
1	TO REPLACE FRONT BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. 1560 x 1			1560	\$ 2,340.00
2	TO RESPRAY FRONT BUMPER. 1 x 1300			1300	\$ 1,500.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			NETT	\$ 200.00
4	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			NETT	\$ 600.00
5	SUNDRIES.			NETT	\$ 50.00
TOTAL LABOUR				\$ -	\$ 4,690.00
TOTAL PARTS				\$ -	\$ 3,801.20

TOTAL	\$ -	\$ 8,491.20
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

***DISCLAIMER**

- 1 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.
- 2 TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.
- 3 THIS IS ONLY AN ESTIMATE BASED ON PARTS AVAILABILITIES AT CURRENT LOCAL SINGAPORE WAREHOUSE. IF THERE IS A NEED TO INCLUDE AIRFREIGHT PARTS , WE WILL INFORM DULY.

Steve (LKK) WML Perle
 18/12/19, 2.30pm
 3 days
 Rg Bel Sy
 P/P

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
