

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 661R

AAD1912-054

*Not Authored
11/12/19 & 22/5/20*

Vehicle No.:
 Chassis No.:
 Vehicle Make: 16 DEC 2019
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

SHF 661R
 VF1ABL15AUC278742
 RENAULT
 LATITUDE
 7.12.19
FCIL
 30/6/2014

	PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu</i> 747.20	✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 344.70	X
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68	X
1	BUMPER RETAINER FRT RH	\$	<i>Dis</i> 101.40	✓
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 10.70	X
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 292.50	X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 147.00	X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21	X
1	BUMPER BEAM FRT	\$	<i>N</i> 663.70	X
1	HEADLAMP RH	\$	<i>Lot</i> 743.60	✓
1	HEADLAMP PANEL FRT RH	\$	<i>N</i> 128.30	X
1	FENDER PANEL FRT RH	\$	<i>R</i> 437.10	✓
1	WHEELARCH FRT RH	\$	<i>Sn</i> 191.40	} X
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 11.80	
1	FENDER BRACKET FRT RH	\$	<i>Sn</i> 106.40	
1	FENDER INSULATOR RH	\$	<i>Sn</i> 66.30	
1	TOW COVER FRT	\$	<i>Sn</i> 60.90	
1	FRONT BRACE PANEL	\$	<i>N</i> 177.22	
1	RADIATOR GRILLE	\$	<i>Sn</i> 969.90	
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36	
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 686.00	
1	FRAME FULL SUPPORT PANEL	\$	<i>N</i> 592.70	
1	FRAME FULL SUPPORT BRACKET	\$	<i>N</i> 41.60	
1	BONNET	\$	<i>N</i> 1,312.70	
1	BONNET INSULATOR	\$	<i>Sn</i> 294.30	
1	BONNET STRUT RH	\$	<i>Sn</i> 53.30	
1	BONNET HINGE RH	\$	<i>Sn</i> 237.40	

Trans-cab Auto Services Pte Ltd

AAD1912-054

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 661R

1	BONNET LOCK	\$	<i>N</i>	152.80	}	X
1	BONNET CABLE	\$	<i>Sm</i>	55.20		
1	BONNET CABLE COVER	\$	<i>Sm</i>	80.60		
1	BONNET SEAL OUTER	\$	<i>Sm</i>	83.20		
1	BONNET SEAL INNER	\$	<i>Sm</i>	70.10		
1	LOWER ARM RH L70Y	\$	<i>Sm</i>	192.70		
1	KNUCKLE ARM RH L70Y	\$	<i>Sm</i>	481.50		
1	ABSORBER FRT RH L70Y	\$	<i>Sm</i>	203.50		
1	DRIVESHAFT RH	\$	<i>N</i>	1,355.70		
1	STABILIZER BAR FRT	\$	<i>Sm</i>	427.90		
1	WIPER RESERVOIR MOTOR	\$	<i>Sm</i>	82.60		
1	WIPER RESERVOIR	\$	<i>Sm</i>	179.60		
1	WIPER RESERVOIR NECK	\$	<i>Sm</i>	29.30		
1	DOOR PANEL FRT RH	\$	<i>N</i>	2,844.66		
1	DOOR MIRROR RH ASSY	\$	<i>Sm</i>	1,483.40		
1	DOOR HARNESS WIRE RH	\$	<i>Sm</i>	2,670.00		
1	ROCKER PANEL INNER GARNISH RH	\$	<i>Sm</i>	466.51		
1	ROCKER PANEL INNER RH	\$	<i>N</i>	1,024.79		
1	ROCKER PANEL OUTER RH	\$	<i>N</i>	1,184.99		
1	ROCKER PANEL CENTER RH	\$	<i>N</i>	990.25		
TOTAL		\$		23,304.67		
10%		\$		2,330.47		
		\$		20,974.20		

Special Nett

1	BUMPER CLIP FRT	\$	<i>N</i>	66.00	}	X
1	BUMPER BRACKET CLIP FRT RH	\$	<i>N</i>	12.00		
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>N</i>	10.50		
1	BUMPER GRILLE LOWER CLIP	\$	<i>N</i>	69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>N</i>	70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>N</i>	20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>N</i>	30.00		
1	WHEELARCH CLIP FRT RH	\$	<i>N</i>	30.50		
1	FRONT RIGHT TYRE	\$	<i>Sm</i>	300.00		
1	FRONT RIGHT TYRE RIM	\$	<i>Sm</i>	380.00		
1SET	Front licence plate with holder	\$	<i>Sm</i>	80.00		

Trans-cab Auto Services Pte Ltd

AAD1912-054

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 661R

1SET	RADIATOR GRILLE SCREW	\$	<i>nn</i> 16.00	}
1SET	RADIATOR GRILLE FRAME CLIP	\$	<i>nn</i> 52.00	
6	BONNET INSULATOR CLIP L70Y	\$	<i>nn</i> 7.30	
2	BONNET CABLE COVER SCREW L70Y	\$	<i>nn</i> 10.85	
2	BONNET CABLE CLIP L70Y	\$	<i>nn</i> 6.31	
1	FRONT DOOR STICKER 'Trans-Cab'	\$	<i>nn</i> 80.00	
1	FRONT DOOR STICKER 'Classic'	\$	<i>nn</i> 80.00	
TOTAL		\$	1,320.47	
TOTAL PARTS		\$	22,294.67	

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00	<i>4401</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	<i>4001</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
To rust-proofing of the affected areas.	\$	170.00	<i>301</i>
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	<i>X</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>4</i> 380.00	<i>X</i>
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1912-054

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 661R

To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i>	380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X
To check ABS and brake efficiency, final checking and testing.	\$	<i>nn</i>	380.00	X
TOTAL	\$		14,930.00	
Over All Total	\$		37,224.67	

LUMP SUM (REPAIR DAY)

~~20 DAYS~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: