

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X**AAD1912-095***Not Authorized
L1Smp & 280d*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

16 DEC 2019

SHC 5991X

VF1ABL15AUC280996

RENAULT

LATITUDE

11.12.19

FCIL

18/12/2014

		PART
1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	OUTER PANEL REAR (End Panel)
14	1	OUTER PANEL REAR (End Panel) TRIM
15	1	TAILLAMP RH
16	1	TAILLAMP PANEL RH
17	1	TAILLAMP LH
18	1	TAILLAMP PANEL LH
19	1	BOOT REAR
20	1	BOOT FINISHER
21	1	BOOT WHEATERSTRIP
22	1	BOOT REFLECTOR LAMP LH
23	1	BOOT REFLECTOR LAMP RH
24	1	BOOT BADGE 'RENAULT'
25	1	BOOT BADGE
26	1	BOOT STRUT LH

		LIST
\$	Buc	561.70 ✓
\$	ndi wt	411.90 ✓
\$	Sn	98.10 x
\$	Sn	82.10 x
\$	Sn	59.80 x
\$	Sn	16.60 x
\$	Sn	80.80 x
\$	Sn	54.20 x
\$	Sn	16.60 x
\$	Bz	547.80 ✓
\$	K	114.50 x
\$	ndi	100.90 ✓
\$	Bz	745.80 ✓
\$	Sn	404.56
\$	Sn	313.10
\$	K	401.40
\$	Sn	401.40
\$	K	401.40
\$	K	1,677.20 } x
\$	Sn	344.70
\$	Sn	178.20
\$	Sn	277.70
\$	Sn	277.70
\$	nn	82.40
\$	nn	95.80
\$	Sn	145.10

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X**AAD1912-095**

27	1	BOOT STRUT RH	\$	145.10	}
28	1	BOOT HINGE LH	\$	254.20	
29	1	BOOT HINGE RH	\$	253.80	
30	2	BOOT RUBBER PLUG	\$	139.90	
31	2	BOOT BUFFER	\$	26.80	
32	1	BOOT LOCK LINKAGE	\$	20.60	
33	1	BOOT LOCK LINKAGE HOLDER	\$	99.50	
34	1	BOOT INNER TRIM BOARD	\$	611.00	
35	1	BOOT SWITCH	\$	113.00	
36	1	BOOT LOCK	\$	246.60	
37	1	BOOT LOCK CATCH	\$	41.70	}
38	1	EXHAUST CAP REAR	\$	125.40	
39	1	EXHAUST REAR	\$	5,263.60	
40	1	SPARE WHEEL PANEL	\$	1,229.40	
41	1	SPARE TYRE BOARD	\$	680.90	
42	1	SPARE WHEEL PANEL TRIM	\$	612.21	
TOTAL			\$	17,755.17	
10%			\$	1,775.52	
			\$	15,979.65	

Special Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	30.00	X
11	1	BOOT STICKER "6555-3333"	\$	30.00	X
12	2	REAR WINDSCREEN SEALANT	\$	80.00	X
13	1	WINDSCREEN MOULDING	\$	100.00	X
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	X

Trans-cab Auto Services Pte Ltd**AAD1912-095**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X

15	1	BOOT INNER TRIM CLIP	\$	nn	45.00	}	X
16	1SET	BOOT FINISHER CLIP	\$	nn	24.20		
17	1	TAILLAMP CLIP LH	\$	nn	5.00		
18	1	TAILLAMP CLIP RH	\$	nn	5.00		
19	1	Rear Bumper Protector	\$	nn	100.00		
20	1	EXHAUST MOUNTING REAR	\$	nn	16.00		
21	1	EXHAUST BRACKET REAR	\$	nn	24.80		
22	1SET	Rear licence plate with holder	\$	sn	80.00		
TOTAL			\$		1,587.00		
TOTAL PARTS			\$		17,566.65		

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To Rust-Proofing Of The Affected Areas.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	15/
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	60/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00	600/
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$		170.00	60/

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X**AAD1912-095**

To transfer of rear windscreen glass to facilitate bodywork repair.	\$	na	170.00	X
To check steering geometry and computer wheel alignment	\$	↳	220.00	X
To repair and realign rear exhaust pipe.	\$	↳	170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	↳	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	↳	380.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	↳	170.00	X
Putty and spray painting of the affected portion.	\$		6,000.00	44%
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	↳	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	↳	380.00	X

TOTAL \$ 15,230.00**Over All Total \$ 32,796.65****LUMP SUM (REPAIR DAY)****20 DAYS****4 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: