

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS F	IRST CAPITAL IN	ISURANCE LTD	Ref : CC4/FCI19022200/Aea3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 22-04-2020 Code: FCI2			
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHC 2080U	Veh. Inspected	SKF 9399D	
	Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
	Claim No.	D19007905MFSH	Excess (\$)	0.00	
	Assign From	MAY CHUA	Assign Date	17/12/2019	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA CIVIC	c.c	1498	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	MRHFC1660JT000129	Colour	BLACK	
	Odometer	25283	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/50 R17	YOKOHAMA	6 mm	
	L/H Front Tyre	215/50 R17	YOKOHAMA	6 mm	
	R/H Rear Tyre	215/50 R17	YOKOHAMA	6 mm	
	L/H Rear Tyre	215/50 R17	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	13/12/2019	Inspection Date	18/12/2019	
	Survey held at	eld at KAH MOTOR CO SDN BERHAD			
		15 UBI ROAD 4 SINGAPORE 408610			
5a.					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				