

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: W000550000

Company Ref. No.: S80FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SKF9399D
Chassis No : MRHFC1660JT000129
Model : CIVIC 1.5 TURBO VTIS YM2018
Owner's Name : TAN POH NGOH
Ins Policy No. :
Date of Accident : 13/12/2019

Document No. : SQT19005451
Date : 14. Dec 2019
Customer No. : WZF002
Svc Advisor : YOU PO SOON
Engine No : L15B73623883
Date | Time : 14. Dec 2019 4:38:25 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CYNTHIA TAN POH NGOH OWNER INSURER: AVIVA LTD ACC DATE: 13/12/2019 SURVEYED BY: DATE: REF NO: TP INSURER: MS FIRST CAPITAL TP VEH: SHC2080U						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER <i>De band</i>	1	617.20	25	✓ 462.90	32.40	495.30
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER <i>Not Nee</i>	1	180.00	25	X 135.00	9.45	144.45
91505-TM8-003	CLIP,BUMPER <i>her</i>	8	2.30	25	✓ 13.80	0.97	14.77
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER <i>De d.</i>	1	39.80	25	✓ 29.85	2.09	31.94
71593-TEA-T01	SPACERR.RR.BUMPER SIDE <i>her</i>	1	11.50	25	X 8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE <i>her</i>	1	11.50	25	X 8.62	0.60	9.22
Sum Item					658.79	46.11	704.90
BOSUN	SUNDRIES	1	50.00		20 50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		X 180.00	12.60	192.60
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	180.00		130 180.00	12.60	192.60
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	1000.00		560 1000.00	70.00	1070.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1100.00		450 1100.00	77.00	1177.00
Sum Labor					2510.00	175.70	2,685.70

Survey By _____

Date & Time _____

Total Amount 3,168.79 221.81 3,390.60

Printed on 14/12/2019 4:50:04 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE LIMITED	Document No.	: SQT19005451	Page	2
	36 ROBINSON ROAD	Date	: 14. Dec 2019		
	#16-01 CITY HOUSE	Customer No.	: WZF002		
	SINGAPORE 068877	Svc Advisor	: YOU PO SOON		
Registration No	: SKF9399D	Engine No	: L15B73623883		
Chassis No	: MRHFC1660JT000129	Date Time	: 14. Dec 2019 4:38:25 PM		
Model	: CIVIC 1.5 TURBO VTIS YM2018	Surveyor Name	:		
Owner's Name	: TAN POH NGOH	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 13/12/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
Excess							
					Total (Inclusive of GST)		3,390.60
Status							
Signature							

Adrian Lim,
P/P 18/12/19.
All Authorised
03 Days.
96893735.

Printed on 14/12/2019 4:50:04 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co, Sdn. Bhd, it will be refunded.

**HONDA**

Attn: Adrian

SERVICE PRE-INVOICE**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

WD: 3 Day

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer: CU0034095 / MS FIRST CAPITAL
 Chassis No: MRHFC1660JT000129
 License No: SKF9399D
 Mileage: 25592
 Engine No: L15B73623883

Document No: SVO19082652
 Printed By: ARYCHUA
 Order Date: 23. December 2019
 Order Time: 9:34:25 AM
 Service Advisor: YOU PO SOON

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incld GST
	TP DIRECT SETTLEMENT (J/NO: 74004) OWNER: CYNTHIA TAN POH NGOH OWNER INSURER: AVIVA LTD ACC DATE: 13/12/2019@09.10AM ACC: ALEXANDRA RD TO QUEENSWAY SURVEYED BY: ADRIAN LING 18/12/2019@12.12PM REF NO: D19007905MFSH TP INSURER: MS FIRST CAPITAL TP VEH: SHC2080U						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	39.80	25	29.85	2.09	31.94
	SUM PARTS:				506.55	35.46	542.01
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BA02R	EXT-YJ	1	130.00		130.00	9.10	139.10
	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)						
BKRP02S	EXT-YJ	1	560.00		560.00	39.20	599.20
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.						
BP02R	EXT-YBH	1	450.00		450.00	31.50	481.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P)						
	SUM LABOUR:				1,160.00	81.20	1,241.20
	TOTAL SGD				1,666.55	116.66	1,783.21

Total Payable (SGD)**1,783.21**

GST Amount is calculated from individual line(s)