

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Registration No : SKF9399D

Chassis No : MRHFC1660JT000129

Model : CIVIC 1.5 TURBO VTIS YM2018

Owner's Name : TAN POH NGOH

Ins Policy No. :

Date of Accident : 13/12/2019

Document No. : SQT19005451

Date : 14. Dec 2019

Customer No. : WZF002

Svc Advisor : YOU PO SOON

Engine No : L15B73623883

Date | Time : 14. Dec 2019 4:38:25 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CYNTHIA TAN POH NGOH OWNER INSURER: AVIVA LTD ACC DATE: 13/12/2019 SURVEYED BY: DATE: REF NO: TP INSURER: MS FIRST CAPITAL TP VEH: SHC2080U						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER <i>Reband</i>	1	617.20	25	✓ 462.90	32.40	495.30
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	180.00	25	? 135.00	9.45	144.45
91505-TM8-003	CLIP,BUMPER <i>han</i>	8	2.30	25	✓ 13.80	0.97	14.77
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER <i>del</i>	1	39.80	25	✓ 29.85	2.09	31.94
71593-TEA-T01	SPACERR.RR.BUMPER SIDE <i>3 new</i>	1	11.50	25	+ 8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	+ 8.62	0.60	9.22
Sum Item					658.79	46.11	704.90
BOSUN	SUNDRIES	1	50.00		<i>20</i> 50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		<i>x</i> 180.00	12.60	192.60
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	180.00		<i>130</i> 180.00	12.60	192.60
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	1000.00		<i>560</i> 1000.00	70.00	1070.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1100.00		<i>450</i> 1100.00	77.00	1177.00
Sum Labor					2510.00	175.70	2,685.70

Survey By

Date & Time

Total Amount 3,168.79 221.81 3,390.60

Printed on 14/12/2019 4:50:04 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SKF9399D
Chassis No : MRHFC1660JT000129
Model : CIVIC 1.5 TURBO VTIS YM2018
Owner's Name : TAN POH NGOH
Ins Policy No. :
Date of Accident : 13/12/2019

Document No. : SQT19005451 **Page** 2
Date : 14. Dec 2019
Customer No. : WZF002
Svc Advisor : YOU PO SOON
Engine No : L15B73623883
Date | Time : 14. Dec 2019 4:38:25 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Excess							
Status							
Signature							

Total (Inclusive of GST)**3,390.60**

Adrian Ling,
P/P 18/12/19.

AKL Authorised

03 Days.
96893735.

Printed on 14/12/2019 4:50:04 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.