

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

16 DEC 2019

E S T I M A T E

Estimate No. : b1 53795
Date Estimated : 16/12/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lau Hong Peng
940, Tampines Avenue 5,
#06-213

Singapore 520940

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL9005J	WBAJA12010BT82710	27/09/2019	520i	0

DESCRIPTION

Replace rear bumper include remove attachment etc and
knock on accident dent area

850 1,275.00

Spray painting rear bumper

934 1,038.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

To replace rear exhaust silencer including alignment
system and conduct checks for leak.

X 531.00

Sundries.

80 ✓ 150.00

Total Labour 1: 3,171.00

DESCRIPTION

TAILPIPE TRIM BLACK CHROME D=80MM ~~--- CMT~~ X NN

QTY	PRIC	VALUE
1	154.55	154.55

REAR SILENCER X NN

1	1,281.95	1,281.95
---	----------	----------

LEFT PROTECTION FOIL ~~--- AK~~ NN X

1	13.45	13.45
---	-------	-------

RIGHT PROTEC ~~--- AK~~ X NN

1	13.45	13.45
---	-------	-------

Carrier, bum ~~--- AK~~ X NN

1	632.45	632.45
---	--------	--------

REAR BUMPER BOTTOM REINFORCEMENT ~~--- AK~~ ✓ BR

1	88.15	88.15
---	-------	-------

REAR BUMPER CENTRE GUIDE ~~--- AK~~ ✓ BR

1	67.45	67.45
---	-------	-------

REAR BUMPER TRIM STRIP ~~--- AK~~ BR ✓

1	116.60	116.60
---	--------	--------

REAR BUMPER TOWING EYE FLAP PRIMED ~~--- CMT~~ X NN

1	52.60	52.60
---	-------	-------

REAR BUMPER PANEL PRIMED (PDC/PMA) ~~--- AK~~ 00

1	1,619.15	1,619.15
---	----------	----------

SET MOUNTING PMA SENSOR ~~--- AK~~ X NN

1	69.35	69.35
---	-------	-------

UNDERBODY PANELLING REAR ~~--- AK~~ ✓ BR

1	41.30	41.30
---	-------	-------

REAR RH REAR REFLECTOR ~~--- AK~~ X NN

1	38.85	38.85
---	-------	-------

DECOUPING RING PDC TORQUE CONVERTER ~~--- AK~~ NN X

4	5.10	20.40
---	------	-------

ULTRASONIC SENSOR IMPERIALBLAU(WA89 ~~--- AK~~ X NN

4	370.00	1,480.00
---	--------	----------

Total Parts : 5,689.70

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 53795
Date Estimated : 16/12/2019
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL9005J	WBAJA12010BT82710	27/09/2019	520i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 13/1/20, 10:30am Excess S\$ _____Surveyor's Name Steve (LKK) Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend _____

ML Am
Ar 3 days
P/P
By P/L Sy

Labour 1	:	3,171.00
Parts	:	5,689.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	620.25
Grand Total	:	9,480.95

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 53795**
Date Estimated : **16/12/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -

Lau Hong Peng
940, Tampines Avenue 5,
#06-213

Singapore 520940

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL9005J	WBAJA12010BT82710	27/09/2019	520i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments, rear bumper carrier including remove attachments to facilitate repairs.	850.00		850.00
To respray rear bumper.	934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
# To replace bootlid smart opener top sensor wire, control unit including program and checks bottom sensor wire for proper function.	562.00		562.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR BUMPER CARRIER	862.10	1.00		862.10
REAR BUMPER BOTTOM REINFORCEMENT	88.15	1.00		88.15
REAR BUMPER CENTRE GUIDE	67.45	1.00		67.45
REAR BUMPER TRIM STRIP	116.60	1.00		116.60
REAR BUMPER PANEL PRIMED (PDC/PMA)	1,619.15	1.00		1,619.15
UNDERBODY PANELLING REAR	41.30	1.00		41.30
# SENSOR WIRE FOR SMART OPENER TOP	46.30	1.00		46.30
# CONTROL UNIT SMART OPENER	497.05	1.00		497.05

SUPPLEMENTARY ITEMS

Total Labour :	2,576.00
Total Parts :	3,338.10
Total Labour & Parts :	5,914.10
Deduction for Excess :	0.00
Total Repair Costs less Excess:	5,914.10
GST @7%:	413.99
Grand Total :	6,328.09

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 53795**
Date Estimated : **16/12/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -

Lau Hong Peng
940, Tampines Avenue 5,
#06-213

Singapore 520940

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL9005J	WBAJA12010BT82710	27/09/2019	520i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To replace bootlid smart opener top sensor wire, control unit including program and checks bottom sensor wire for proper function.	562.00		562.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR BUMPER CARRIER ✓ DD	862.10	1.00		862.10
# SENSOR WIRE FOR SMART OPENER TOP ✓ CUT	46.30	1.00		46.30
# CONTROL UNIT SMART OPENER ✓ BR	497.05	1.00		497.05

SUPPLEMENTARY ITEMS

Total Labour :	562.00
Total Parts :	1,405.45
Total Labour & Parts :	1,967.45