

Date: 14.12.2019
Vehicle No: SLB2457A
Model: NISSAN QASHQAI 1.2 DIG-T
Chassis: SJNFEAJ11U1588915 - 2015
Reg.Year: 2016

Third Party Insurer: III
Third Party Veh No: SHD3354T
Date of Accident: 13.12.2019

Not Authorized
11 Sep @ 7
Resurvey After Paint 5-6 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Pr</i> \$2,867.50
2	REAR TAILGATE INNER LOCK	1		<i>Pr</i> \$203.28
3	REAR TAILGATE "QASHQAI" EMBLEM	1		<i>Pr</i> \$105.75
4	REAR WINDSCREEN MOULDING	1		<i>Pr</i> \$128.60
5	REAR TAILGATE INNER TRIM CLIPS	8	\$6.50	\$52.00
6	REAR END PANEL	1		<i>Pr</i> \$703.50
7	REAR END PANEL UPPER TRIM COVERING	1		<i>Pr</i> \$129.25
8	REAR END PANEL UPPER TRIM COVERING CLIPS	6	\$6.50	<i>Pr</i> \$39.00
9	REAR BUMPER	1		<i>Pr</i> \$1,240.50
10	REAR BUMPER CLIPS	10	\$5.80	<i>Pr</i> \$58.00
11	REAR BUMPER REFLECTOR LH	1		<i>Pr</i> \$87.50
12	REAR BUMPER SIDE BRACKET LH	1		<i>Pr</i> \$48.80
13	REAR SPARE TYRE PANEL			REPAIR
SUB TOTAL				\$5,663.68
LESS 30%				-\$1,699.10
PARTS TOTAL				\$3,964.58

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>Pr</i> \$80.00
2	REAR WINDSCREEN STOPPER	2	\$15.00	<i>Pr</i> \$30.00
3	REAR BUMPER REVERSE SENSOR	1		<i>Pr</i> \$350.00
S/N TOTAL				\$460.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 14.12.2019
Vehicle No: SLB2457A
Model: NISSAN QASHQAI 1.2 DIG-T
Chassis: SJNFEAJ11U1588915 - 2015
Reg.Year: 2016

Third Party Insurer: III
Third Party Veh No: SHD3354T
Date of Accident: 13.12.2019

ESTIMATE**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST REAR ACCIDENT
AREAS & ETC

759 600
\$800.00

LABOUR CHARGES TO REMOVE & REFIX, REPLACE REAR WINDSCREEN GLASS, REAR
WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING & ETC

\$150.00 1200

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM
& ETC

\$150.00 600

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS
AT REAR TAILGATE, REAR END PANEL, REAR BUMPER & ETC

\$900.00 800

LABOUR CHARGES TO DISCONNECT & RECONNECT REAR WIRING SYSTEMS & ETC

\$120.00 200

TO TUFF KOTE & UNDERSEAL MATERIALS

\$200.00 600

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC

\$100.00 600

LABOUR TOTAL \$2,420.00

ONG **TOTAL** **\$6,844.58**