

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
Email: kentsengcarservices@gmail.com

M/s NTUC Income Insurance Co-operative Ltd

DATE

17.12.2019

73 Bras Basah Road, #05-01

CAR NO

SJR 1643 A


NTUC Trade Union House S189556

MAKE

Mitsubishi Lancer

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.

YOUR INSURED : FBK 5001 H

Pc	Pcs	JMYSRCY2A9U004283	UNIT PRICE	AMOUNT
1	pc	Rear bumper ✓ PD 7 X SVC		\$877.20
1	pc	Rear bumper reflector (left) 7 X SVC		\$38.00
1	pc	Rear bumper side retainer (left) ✓ BR		\$30.00
1	pc	Rear bumper bracket (left) 7 X SVC		\$34.80
1	pc	Rear bumper lower lip ✓ CRU. - M+H		\$650.00
1	pc	Rear bumper reverse sensor X SVC		\$300.00
1	set	Rear bumper reinforcement 7 X SVC		\$289.00
1	pc	Rear bumper reinforcement 7 X SVC		\$599.30
1	pc	Rear end panel X R		
		To check rear lightings and electrical wiring system include performing water leakage test.		\$80.00X
		To provide labour, workmanship to re-align, cutting Rear end panel, dismantle & replace the above mentioned parts.		\$900.00
		Labour for respray rear end panel, rear boot lid cover, rear bumper and rear bumper lower lip.		\$1,000.00
		To spray anti-rust coating on new & affected panel		\$200.00X
		To remove and reinstall rear reverse sensor.		\$80.00X
		Repair day - 3 days Lump Sum After part photo.		
		 26/12/19		
				R = 942 - 10% 847.8 L = 590 1,437.8 - 20% 1,150.24
				682 724 280 480 250 280 300 400
				Total \$5,078.30

Page 1 of 1

KENT SENG CAR SERVICES.

Sun Pin (LKK)

19/12/2019.

TP without prejudice.

Sunpin @ lkkauto.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: