Lion City Rentals Pte Ltd CARROS CENTER 60 JALAN LAM HUAT #04-01 S(737869) Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 17/12/2019

Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLE6131Y CHASSIS NO: RU31208507

MAKE / MODEL: Honda Vezel Hybrid 1.5X CVT

DATE OF ACCIDENT: 14/12/2019

YOUR INSURED VEHICLE NUMBER :SJS60H

MILEAGE: 243500 km

PARTS DESCRIPTION Rear tailgate Rear tailgate Vezel emblem Rear tailgate Honda emblem Rear tailgate Hybrid emblem Rear tailgate windscreen moulding Rear tailgate weatherstrip Rear tailgate lock Rear tailgate lock Rear tailgate lock Rear tailgate lock catch Rear RH tail lamp Rear RH taillamp Rear LH taillamp	QTY	\$1,450.00	\$1,450.00
	1PC	\$86.80	\$86.80
	1PC	\$81.30	\$81.30
	1PC	\$84.00	\$84.00
	1PC	\$195.00	\$195.00
	1PC	\$155.00	\$155.00
	1PC	\$550.00	\$550.00
	1PC	\$180.00	\$180.00
	1PC	\$780.00	\$780.00
	1PC	\$780.00	\$480.00
	1PC	\$480.00	\$480.00
12 Rear LH taillamp 13 Rear LH taillamp refelector 7. X SVC 14 Rear end panel 15 Rear end panel top garnish 7. X SVC 16 Rear bumper / M CRU. 17 Rear bumper RH reflector X SVC 18 Rear bumper LH reflector 7. X SVC 19 Rear spare tyre tool box 7. X SVC	1PC 1PC 1PC 1PC 1PC 1PC 1PC	4	

CD		1 4 1	. NE	тт
22	FL.	141	INF	

1	Rear bumper clips / Nec	1 SET	\$180.00 30
	End panel top garnish clips ? 🗴 5 🗸	1 SET	\$80.00
	Reverse sensor / Short	1PC	\$250.00 200
	Body sealant 7 X SVC	1set	\$300.00
	Windscreen sealant / № C	1PC	\$200.00
	Rear number plate X X5VC		\$60.00
	/	Special Nett Total S\$:	\$1,070.00

LABOUR CHARGES

	LABOUR CHARGES	1 ~1
1	To labour charge for removing rear tailgate, rear end panel, rear bumper out to facilitate repairs and replacement of damaged parts. Also include cuting out and welding of replacement spare tyre panel	\$900.00 460 566 700
2	To respray rear tailgate, end panel and spare typre panel	\$800.00 400
3	To remove and install rear tailgate glass	\$160.00 120
4	To apply rustproofing on all damaged parts	\$180.00 30
6	To check wiring system	\$100.00 3 0
7	To conduct a standard of opearing procedures post repairs scan test as a requirements upon 7. X completion of collision repairs	\$300.00
8	To deactivate and active high voltage hybrid 7	\$300.00

Repair day - 3 days. L/S After paint photo

battery as a safety precautions

LKK Auto Consultants hence notify

the Repairer of the following: To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LABOUR TOTAL S\$: \$2,740.00 TOTAL S\$: \$10,275.68 **7% GST** \$719.30 GRAND TOTAL S\$: \$10,994.98

Sun pin (LICK) 17/12/2014.
TP withou prejudice.