

14, 321.98

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5262L

AAD1912-088

*Not Authorized
Resuming B4paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 5262L

JTDKB3FU103077327

TOYOTA

PRIUS

11.12.19

AIG

12/12/2018

13 DEC 2019

		PART			LIST
1	1	REAR BUMPER	\$	Ry	442.60 —
2	1	REAR BUMPER RE-INFORCEMENT	\$	Ry	332.70 —
3	1	REAR BUMPER TOWING COVER	\$	nd	15.40 —
4	1	REAR BUMPER UNDER COVER (BLACK)	\$	Ry	576.30 ✓
5	1	ANTENNA, ELECTRICAL KEY	\$	Sm	72.00 X
6	1	REAR BUMPER SIDE RETAINER LH	\$	Sm	116.50 X
7	1	REAR BUMPER SIDE RETAINER RH	\$	CM	117.70 ✓
8	1	REAR BUMPER SIDE RH	\$	CM	123.70 —
9	1	REAR BUMPER SIDE LH	\$	Sm	123.70 X
10	1	REAR TAILGATE	\$	Ry	1,147.80 —
11	1	REAR TAILGATE OUTER GARNISH	\$	CM	925.60 —
12	1	COVER, REAR COMBINATION LAMP, RH	\$	Sm	64.50 X
13	1	BOARD ASSY, BACK DOOR TRIM	\$	Sm	259.20 X
14	1	REAR TAILGATE WEATHERSTRIP	\$	Sm	372.30 X
15	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	Sm	56.50 X
16	1	BOARD, BACK DOOR TRIM	\$	Sm	225.20 X
17	1	PANEL SUB-ASSY, BODY LOWER BACK	\$	Ry	650.30 ✓
18	1	TAILLAMP LOWER RH	\$	CM	502.00 ✓
19	1	TAILLAMP UPPER RH	\$	CM	451.80 X NN
20	1	TAILLAMP LOWER LH	\$	Sm	502.00 X
21	1	TAILLAMP UPPER LH	\$	Sm	443.30 X
22	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	Sm	355.90 X
23	1	BOX, DECK FLOOR, RH	\$	Sm	313.60 X
24	1	BOX, DECK FLOOR, LH	\$	Sm	313.00 X
25	1	BOARD, REAR FLOOR, NO.1	\$	R	519.00 X
26	1	BOX, DECK FLOOR, REAR	\$	Sm	105.80 X
27	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	R	355.90 X

Trans-cab Auto Services Pte Ltd**AAD1912-088**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5262L

28	1	PANEL SUB ASSY, QUARTER, RH	\$	R	854.80	2 X
29	1	LINER, REAR WHEEL HOUSE, RH	\$	R	139.80	X
30	1	SEAL, REAR BUMPER SIDE, RH	\$	Sn	88.50	X
31	1	DUCT ASSY, QUARTER VENT, RH	\$	DU	67.00	✓
32	1	COVER, FLOOR UNDER, NO.1	\$	Sn	175.10	X
33	1	COVER, FLOOR UNDER, NO.2	\$	Sn	241.90	X
34	1	COVER, REAR FLOOR	\$	SVC	229.90	X
35	1	COVER, DECK TRIM, REAR	\$	Sn	126.70	X
36	1	PIPE ASSY, EXHAUST, TAIL	\$	R	1,655.40	} X
37	1	SUPPORT, EXHAUST PIPE, NO.4	\$	Sn	49.10	
38	1	SUPPORT, EXHAUST PIPE, NO.5	\$	Sn	49.10	
39	1	GASKET, EXHAUST PIPE	\$	Sn	53.50	
40	1	PAN, REAR FLOOR	\$	R	583.40	
41	1	EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	R	78.30	
42	1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	R	196.50	
43	1	TROUGH, BACK DOOR OPENING, RH	\$	Sn	103.40	
44	1	ARM ASSY, TRAILING, REAR RH	\$	Sn	370.40	
45	1	ARM ASSY, UPPER CONTROL, REAR RH	\$	Sn	420.80	
46	1	ARM ASSY, REAR SUSPENSION, NO.1 RH	\$	Sn	239.20	
47	1	ARM ASSY, REAR SUSPENSION, NO.2 RH	\$	Sn	497.50	
48	1	WIRE, SKID CONTROL SENSOR, RH	\$	Sn	94.70	
49	1	CARRIER SUB ASSY, REAR AXLE, RH	\$	Sn	953.60	
50	1	HUB & BEARING ASSY, REAR AXLE, RH	\$	Sn	725.60	
51	1	DISC, REAR	\$	Sn	450.70	
52	1	CYLINDER ASSY, DISC BRAKE, REAR RH	\$	Sn	1,001.90	} X
53	1	ABSORBER ASSY, SHOCK, REAR RH	\$	Sn	127.00	
54	1	SUPPORT ASSY, REAR SUSPENSION, RH	\$	Sn	149.30	
55	1	WIRE, BACK DOOR, NO.2	\$	Sn	294.40	
56	1	WIRE, LUGGAGE ROOM, NO.3	\$	Sn	170.70	
57	1	WIRE, ENGINE ROOM MAIN	\$	SVC	7,323.90	X
58	1	WIRE, ENGINE	\$	Sn	2,577.20	X
59	1	PANEL SUB ASSY, FRONT DOOR, RH	\$	R	1,287.40	X
60	1	MIRROR ASSY, OUTER REAR VIEW, RH	\$	Sn	1,436.60	X
61	1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	R	97.50	X
62	1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	R	110.60	X
63	1	CHECK ASSY, FRONT DOOR	\$	Sn	183.80	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5262L**AAD1912-088**

64	1	WEATHERSTRIP, FRONT DOOR, RH	\$	Sh	231.30	
65	1	RUN, FRONT DOOR GLASS, RH	\$	Sh	153.60	
66	1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	Sh	321.10	
67	1	MOULDING ASSY, FRONT DOOR BELT, RH	\$	Sh	92.00	
68	1	TAPE, BLACK OUT, NO.1 RH	\$	va	13.30	X
69	1	TAPE, BLACK OUT, NO.2 RH	\$	va	43.50	
70	1	TAPE, BLACK OUT, NO.3 RH	\$	va	26.30	
71	1	WIRE, FRONT DOOR, RH	\$	Sh	532.80	
72	1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	Sh	594.80	
73	1	FRONT BUMPER	\$	Bu	516.00	
74	1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	Sh	103.40	X
75	1	REINFORCEMENT, FRONT BUMPER	\$	SV	716.60	X
76	1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	SV	246.10	X
77	1	ABSORBER, FRONT BUMPER, LOWER	\$	SV	132.70	X
78	1	ABSORBER, FRONT BUMPER ENERGY	\$	SV	79.60	X
79	1	FRONT BUMPER SIDE RETAINER RH	\$	Diy	80.10	
80	1	FRONT BUMPER SIDE RETAINER LH	\$	Sh	82.30	X
81	1	COVER SUB-ASSY, ENGINE, NO.1	\$	Sh	472.40	X
82	1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	Sh	241.90	X
83	1	EXTENSION, FRONT BUMPER, RH	\$	H	120.10	X
84	1	EXTENSION, FRONT BUMPER, LH	\$	H	120.10	X
85	1	COVER, FRONT BUMPER HOLE, LH	\$	Sh	29.30	X
86	1	COVER, FRONT BUMPER HOLE, RH	\$	Sh	29.30	X
87	1	FRONT LED LAMP (LOWER) ^B RH	Sh \$	GMA Sh	951.40	X
88	1	FRONT HEADLAMP ^B RH	Sh \$	GMA	2,637.60	X
89	1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	Sh	960.50	X
90	1	MOTOR, HEADLAMP LEVELING, LH	\$	Sh	487.50	X
91	1	FRONT LED LAMP (LOWER) RH	\$	CM	951.40	
92	1	FRONT HEADLAMP RH	\$	CM	2,637.60	
93	1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	SV	960.50	X
94	1	MOTOR, HEADLAMP LEVELING, RH	\$	SV	487.50	X
95	1	GRILLE SUB-ASSY, RADIATOR	\$	NU	346.00	
96	1	GRILLE, RADIATOR, LOWER NO.1	\$	NU	170.10	X
97	1	EMBLEM ASSY, RADIATOR GRILLE	\$	NU	90.80	
98	1	FRONT FENDER RH	\$	Bu	977.80	
99	1	LINER, FRONT FENDER, RH	\$	Diy	206.70	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5262L**AAD1912-088**

100	1	PROTECTOR, FRONT FENDER SIDE PANEL, RH	\$	N	93.90	X
101	1	SEAL, FENDER APRON MUDGUARD, RH	\$	Sn	51.90	X
102	1	EMBLEM, SIDE PANEL RH	\$	Sn	54.60	✓
103	1	COVER SUB ASSY, FRONT PILLAR, UPR RH	\$	Sn	100.40	}
104	1	BRACE SUB ASSY, FENDER APRON, RH	\$	Sn	292.10	
105	1	MEMBER, FRONT APRON TO COWL SIDE, LOWER FRONT RH	\$	N	62.80	
106	1	MEMBER, FRONT APRON TO COWL SIDE, UPPER RH	\$	N	110.00	
107	1	APRON ASSY, FRONT FENDER, RH	\$	N	176.80	
108	1	SUPPORT SUB ASSY, RADIATOR, RH	\$	N	245.10	
109	1	SUPPORT SUB ASSY, RADIATOR, LH	\$	N	245.10	
110	1	SUPPORT SUB ASSY, RADIATOR, UPPER	\$	N	377.10	
111	1	SUPPORT SUB ASSY, RADIATOR, LOWER	\$	N	409.90	}
112	1	SUPPORT, RADIATOR, UPPER RH	\$	Sn	78.90	
113	1	SUPPORT, RADIATOR, UPPER LH	\$	N	78.90	X
114	1	FRONT FENDER LH	\$	N	977.80	X
115	1	LINER, FRONT FENDER, LH	\$	Sn	202.50	X
116	1	EMBLEM, SIDE PANEL LH	\$	Sn	54.60	X
117	1	COVER SUB ASSY, FRONT PILLAR, UPR LH	\$	Sn	100.40	X
118	1	COVER, RADIATOR SUPPORT OPENING	\$	Sn	235.30	X
119	1	FRONT BONNET	\$	R	983.10	✓
120	1	HINGE ASSY, HOOD, LH	\$	N	58.90	X
121	1	HINGE ASSY, HOOD, RH	\$	Dist	58.90	✓
122	1	INSULATOR, HOOD	\$	Sn	410.90	}
123	1	LOCK ASSY, HOOD	\$	N	135.00	
124	1	CABLE ASSY, HOOD LOCK CONTROL	\$	Sn	54.90	
125	1	SEAL, HOOD TO FRONT END PANEL	\$	Sn	51.60	
126	1	BRACE, HOOD LOCK SUPPORT	\$	N	78.30	
127	1	GUIDE, RADIATOR AIR, NO.3	\$	Sn	112.70	
128	1	SHAFT ASSY, FRONT DRIVE, RH	\$	N	1,352.50	
129	1	ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$	Sn	760.10	
130	1	KNUCKLE, STEERING, RH	\$	Sn	663.40	}
131	1	LINK ASSY, FRONT STABILIZER, RH	\$	Sn	237.10	
132	1	BAR, STABILIZER, FRONT	\$	Sn	367.30	
133	1	FRONT SHOCK ABSORBER	\$	Sn	438.30	
134	1	SUPPORT SUB-ASSY, FRONT SUSPENSION, RH	\$	Sn	236.40	
135	1	GEAR ASSY, STEERING	\$	Sn	1,955.40	

Trans-cab Auto Services Pte Ltd**AAD1912-088**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5262L

136	1	SENSOR, SPEED, FRONT RH	\$	543.90	}	Sir,
137	1	SOCKET & WIRE SUB-ASSY, REAR COMBINATION LAMP, LH	\$	63.30		
138	1	SOCKET & WIRE SUB-ASSY, REAR COMBINATION LAMP, RH	\$	63.30		
139	1	SEAL, RADIATOR TO SUPPORT, NO. 3	\$	29.60		
140	1	GUIDE, RADIATOR AIR, NO.1 LH	\$	69.90		
141	1	SEAL, RADIATOR TO SUPPORT, NO.2	\$	29.60		
142	1	GUIDE, RADIATOR AIR, NO.1 RH	\$	65.30		
143	1	GUIDE, RADIATOR AIR, NO.2	\$	53.40		
144	1	FAN, RH	\$	281.30		
145	1	FAN, LH	\$	219.10		
146	1	SHROUD, FAN	\$	264.70		
147	1	MOTOR, COOLING FAN, LH	\$	655.10		
148	1	MOTOR, COOLING FAN, RH	\$	535.50		
149	1	CONDENSER ASSY, COOLER	\$	1,783.20		
150	1	HOSE SUB ASSY, SUCTION	\$	646.80		
151	1	HOSE SUB ASSY, DISCHARGE	\$	402.90		
152	1	PIPE SUB ASSY, SUCTION	\$	465.80		
153	1	TUBE & ACCESSORY ASSY, AIR CONDITIONER	\$	691.00		
154	1	RADIATOR ASSY	\$	2,218.00		
155	1	HOSE, WATER BY PASS, NO.1	\$	45.20		
156	1	HOSE, WATER BY PASS, NO.2	\$	45.20		
157	1	HOSE, WATER BY PASS, NO.3	\$	24.40		
158	1	HOSE, WATER BY PASS, NO.4	\$	15.90		
159	1	HOSE, WATER BY PASS, NO.8	\$	45.20		
160	1	PIPE, WATER BY PASS, NO.1	\$	13.20		
161	1	HOSE, RADIATOR, NO.2	\$	48.60		
162	1	HOSE, RADIATOR, NO.1	\$	51.60		
163	1	JAR ASSY, WINDSHIELD WASHER	\$	219.10	}	Sir,
164	1	INLET SUB ASSY, WASHER	\$	67.00		
165	1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$	292.40		
166	1	HORN ASSY, HIGH PITCHED	\$	134.80		
167	1	HORN ASSY, LOW PITCHED	\$	134.80		
168	1	MOULDING, WINDSHIELD, OUTSIDE RH	\$	85.50		
169	1	INLET, AIR CLEANER, NO.3	\$	42.10		
170	1	INLET, AIR CLEANER, NO.2	\$	112.70		
171	1	INLET, AIR CLEANER, NO.1	\$	155.60		

Trans-cab Auto Services Pte Ltd**AAD1912-088**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5262L

172 1 CROSSMEMBER SUB ASSY, FRONT SUSPENSION

	\$	<i>Sm</i> 2,585.50 <i>X</i>
TOTAL	\$	74,636.90
25%	\$	18,659.23
	\$	55,977.68

Special Nett

1	1SET PARKING AID	\$	<i>Shay</i> 700.00 <i>250sm</i>
2	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00 <i>—</i>
3	2 REAR WINDSCREEN SEALANT	\$	<i>na</i> 80.00 <i>40sm</i>
4	1 WINDSCREEN MOULDING	\$	<i>na</i> 100.00 <i>X</i>
5	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00 <i>30sm</i>
6	1 REAR TAILGATE TOYOTA LOGO	\$	<i>na</i> 47.00 <i>—</i>
7	1 REAR TAILGATE WORDING 'PRIUS'	\$	<i>na</i> 52.90 <i>—</i>
8	1 REAR TAILGATE WORDING 'HYBRID'	\$	<i>na</i> 53.50 <i>—</i>
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>na</i> 80.00 <i>30sm</i>
10	1 REAR TAILGATE STICKER '6555-3333'	\$	<i>na</i> 80.00 <i>30sm</i>
11	1 REAR BUMPER PROTECTOR	\$	<i>Sm</i> 100.00 <i>X</i>
12	1SET BUMPER CLIP FRT	\$	<i>na</i> 66.00 <i>—</i>
13	1 FRONT NUMBER PLATE WITH MOULDING	\$	<i>Sm</i> 200.00 <i>X</i>
14	1 CLIP, FRONT FENDER LINER RH	\$	<i>na</i> 25.00 <i>—</i>
15	1 REAR BUMPER PROTECTOR	\$	<i>na</i> 100.00 <i>X</i>
16	1 SPARE WHEEL RIM	\$	<i>Sm</i> 1,570.55 <i>X</i>
17	1 SPARE WHEEL RIM COVER	\$	<i>Sm</i> 175.80 <i>X</i>
18	1 SPARE TYRE 195/65/15	\$	<i>Sm</i> 350.00 <i>X</i>
19	1SET REAR RH FENDER LINER CLIP	\$	<i>na</i> 35.00 <i>—</i>
20	1SET FRNT RH BUMPER RETAINER CLIP	\$	<i>na</i> 25.00 <i>—</i>
21	1SET REAR RH BUMPER RETAINER CLIP	\$	<i>na</i> 25.00 <i>—</i>
22	1 FRONT WHEEL RIM	\$	<i>Sm</i> 1,570.55 <i>—</i>
23	1 FRONT WHEEL RIM COVER	\$	<i>Sm</i> 175.80 <i>—</i>
24	1 FRONT TYRE 195/65/15	\$	<i>Sm</i> 350.00 <i>—</i>
25	1 REAR WHEEL RIM	\$	<i>Sm</i> 1,570.55 <i>—</i>
26	1 REAR WHEEL RIM COVER	\$	<i>Sm</i> 175.80 <i>—</i>
27	1 REAR TYRE 195/65/15	\$	<i>Sm</i> 350.00 <i>—</i>
28	1 REAR NUMBER PLATE WITH MOULDING	\$	<i>Sm</i> 200.00 <i>—</i>
29	1 WINDSCREEN SEALANT	\$	<i>Sm</i> 253.80 <i>—</i>
30	1 FRONT WINDSCREEN MOULDING	\$	<i>na</i> 120.00 <i>—</i>

Trans-cab Auto Services Pte Ltd**AAD1912-088**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5262L

31	1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	X
32	1	FRONT DOOR STICKER "TRANS-CAB"	\$	<i>nn</i>	100.00	Λ
TOTAL			\$		8,998.25	

TOTAL PARTS \$ 64,975.93**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	9,000.00	<i>1380</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	9,000.00	<i>2000</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>120</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>50</i>
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	<i>60</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of Bonnet fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$	170.00	<i>100</i>
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
Towing Fees	\$	170.00	<i>50</i>

Trans-cab Auto Services Pte Ltd**AAD1912-088**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5262L

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	~ 170.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	120
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	40
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00	X
To transfer of Front Fender fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To drop petrol tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	~ 380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	~ 380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	~ 380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5262L**AAD1912-088**

To repair and realign rear exhaust pipe.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	X
To dismantle and refit rear axle assy, remove and renewal of parts, final checking and testing.	\$	380.00	X
To transfer of Front Door fittings, attachments and perform water seepage test.	\$	170.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	X
To dismantle and refit engine cross-member and engine mounting.	\$	380.00	X
TOTAL	\$	25,080.00	
Over All Total	\$	90,055.93	

(PART-BY-PART) Repair Days**30 DAYS***11 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: