

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19022229/FKA3Q2**Date:** 27/07/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SHA2616K **Insured Vehicle No :** SLX2108S

Date of Loss: 11/12/2019 Nature of Claim: TP Claim No: 7076657729SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2616K	Engine No:	G4LEKU210491
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVKU146151
Reg. Date:	30/04/2019 (Man. Year: 2019)	Odometer:	94536 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R16	Rear Tyre Size:	195/65 R16
Front Left Side:	Davanti 8 mm	Rear Left Side:	Davanti 9 mm
Front Right Side:	Davanti 8 mm	Rear Right Side:	Davanti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,989.14	1,272.02	717.12	36.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	600.00	430.00	41.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,019.14	1,872.02	1,147.12	37.99
+ GST 7.00/7.00% (S\$)	211.34	131.04	80.30	38.00
Nett Amount (S\$)	3,230.48	2,003.06	1,227.42	37.99
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (2.5 x S\$125.19/day) (S\$)		312.98		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,448.53		
Global Sum Settlement (S\$)		2,400.00		

INSPECTION

Date of Assignment: 12/12/2019

Date Inspected: 12/12/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: PARASURAM SHANMUGAM**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID H EMBLEM	Not Necessary	28.00 FL	*- FL
2	1		*EMBLEM -HYBRID	Not Necessary	24.30 FL	*- FL
3	1		*EMBLEM -IONIQ	Not Necessary	31.30 FL	*- FL
4	1		*REAR BUMPER	Cut	459.40 FL	*459.40 FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	294.80 FL	*- FL
6	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	276.20 FL	*- FL
7	1		*REAR BUMPER CENTRE MOULDING ASSY	Scratched	451.25 FL	*451.25 FL
8	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Cracked	155.00 FL	*155.00 FL
9	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
10	2		*REAR BUMPER SIDE BRACKET (LH/RH)	Not Necessary	66.20 FL	*- FL
11	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
12	1		*BOOT LID COMFORT LOGO & TEL NO.STICKER	Not Necessary	30.00 FS	*- FS
13	1		*REAR NO PLATE }	Cracked	25.00 FS	*55.00 FS
14	1		*REAR NO PLATE TRIM COVER }	Broken	30.00 FS	*- FS
15	1		*REAR BUMPER REVERSE SENSOR	Scratched	135.70 FS	*135.70 FS
16	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
17	1		*IONIQ LAMP ASSY -REAR FOG	Cracked	201.50 FL	*201.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,418.75	1,529.85
- List Item Discount on L Items 20.00/20.00% (\$\$)	429.61	257.83
Total Parts (\$\$)	1,989.14	1,272.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	350.00	320.00
2	SPRAY PAINTING CHARGE	New	500.00	200.00
3	WIRING CHARGE	New	50.00	0.00
4	TUFF KOTE	New	50.00	30.00
5	REMOVE/REFIX REVERSE SENSOR	New	80.00	50.00
			Gross Labour Cost (\$)	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >