

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 2616K

DATE 11/12/2019 16:50

Ala

MAKE :

MODEL : HYUNDAI IONIQ

Olmar

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid 'H' Emblem <i>xnn</i>			\$ 28.00
	Emblem -Hybrid <i>xm</i>			\$ 24.30
	Emblem -Ioniq <i>xnn</i>			\$ 31.30
	Rear Bumper <i>cut</i>			\$ 459.40
	Rear Bumper Reinforcement ?			\$ 294.80
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 138.10	\$ 276.20
	Rear Bumper Centre Moulding Assy <i>scr</i>			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy <i>xnn</i>			\$ 155.00
	Rear Bumper Stay <i>xnn</i>			\$ 138.10
	Rear Bumper Side Bracket (LH/RH) <i>xnn</i>		\$ 33.10	\$ 66.20
	Rear Bumper Cover Clips <i>rec</i>			\$ 22.00
	SUB TOTAL			\$ 1,946.55
	LESS 20%			\$ 389.31
	DISCOUNTED TOTAL			\$ 1,557.24
	Boot Lid Comfort Logo & Tel No. Sticker <i>rec</i>			\$ 30.00 Nett
	Rear No. Plate <i>cr</i>			\$ 25.00 Nett
	Rear No. Plate Trim Cover <i>br</i>			\$ 30.00 Nett
	Rear Bumper Reverse Sensor <i>xnn</i>			\$ 135.70 Nett
	Rear Bumper Rubber Mat <i>rec</i>			\$ 50.00 Nett
				\$ 270.70
	Labour Charge			
	Panel Beating			\$ 350.00 <i>\$240</i>
	Spray Painting Charge			\$ 500.00 <i>\$320</i>
	Wiring Charge			\$ 50.00 <i>\$200</i>
	Tuff Kote			\$ 50.00 <i>\$30</i>
	Remove/Refix Reverse Sensor			\$ 80.00 <i>\$50</i>
	TOTAL LABOUR			\$ 1,030.00
	ESTIMATE TOTAL			\$ 2,857.94

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ram (LKK)
12/12/19 1300 hrs
Ram@lkk.com.sg
85622784
(2) repair days
8/10
Ref paint photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.