

K&T CARS

K&T Cars
53 Ubi Avenue 1 #01-23 Spore 408934
Tel : 6844 5938
E-mail : kntcars@gmail.com
ROC number : 53208965X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AIG INSURANCE

REPAIR PERFORMANCE INVOICE

Vehicle number SJJ7806A
Make / Model TOYOTA VIOS
Chassis number MR053HY9305078549 / 2008
Accident date 13/12/19
Reference T1912-22

Unit Price - SGD \$

Qty Particulars

PARTS REPLACEMENT - LIST ITEMS

- | Qty | Particulars | Unit Price - SGD \$ |
|-----|-------------------------------------|---------------------|
| 1 | FRONT BUMPER 2004.75 ✓ | 614.53 485 |
| 1 | FRONT BUMPER RETAINER free ✓ | 162.50 52 |
| 1 | FRONT RH FOG LAMP X sue | 380.31 X |
| 1 | FRONT RH FOG LAMP COVER X sue | 155.83 X |
| 1 | FRONT RH HEADLAMP ? cr ✓ | 512.51 427 |
| 1 | FRONT BONNET X sue | 702.75 X |
| 1 | FRONT BONNET HINGE X sue | 115.00 X |
| 1 | FRONT FENDER bu ✓ | 642.85 447 |
| 1 | FRONT FENDER EMBLEM ne ✓ | 193.20 76 |
| 1 | FRONT FENDER INNER SHIELD ne ✓ | 51.75 ✓ |
| 1 | FRONT CROSS MEMBER X sue | 2070.00 X |
| 1 | FRONT RH KNUCKLE ARM ? bt ✓ | 569.25 335 |
| 1 | FRONT RH KNUCKLE ARM BEARING ? ne ✓ | 166.75 131 |
| 1 | FRONT RH LOWER ARM X sue | 1144.25 X |

2004.75
25%
1503.56

614.53 485
162.50 52
380.31 X
155.83 X
512.51 427
702.75 X
115.00 X
642.85 447
193.20 76
51.75 ✓
2070.00 X
569.25 335
166.75 131
1144.25 X

1503.56

360.00

1210.00

3073.56

20%

2458.84

4/5-2, 450

5 days

Less 25%

7481.48
1870.37
5611.11

PARTS REPLACEMENT - SPECIAL NETT ITEMS

- | | | |
|-------|-------------------------------------|--|
| 1 | RM ct ✓ | |
| 1 | TYRE NN | |
| 1 SET | FRONT BUMPER CLIP ne ✓ | |
| 1 SET | FRONT FENDER INNER SHIELD CLIP ne ✓ | |

360 { 800.00 300
500.00 X
50.00 30
50.00 30

Subtotal

1400.00

Balance C/F

7011.11

LABOUR AND MISCELLANEOUS CHARGES

Balance B/F

7011.11

- | | | |
|---|--|--|
| 1 | CHECK WIRING AND LIGHTNING SYSTEM | |
| 2 | REMOVE, RENEW & REFIT OLD BONNET TO NEW | |
| 2 | COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT | |
| 3 | REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS | |
| 4 | PANEL BEATING ON AFFECTED AREAS | |
| 5 | SPRAY PAINTING ON AFFECTED AREAS | |
| 6 | APPLY ANTI RUST ON AFFECTED AREAS | |

1210 { 60.00 30
150.00 X nn
150.00 60
200.00 80 ?
900.00 400
1200.00 400 600
150.00 60 40

Subtotal

2810.00

Grand total

9821.11

Rasul

Hp 90010068

5 days

4/5

17/12/19 @ 1625

Repair after repair