

K&T CARS

K&T Cars

53 Ubi Avenue 1 #01-23 Spore 408934

Tel : 6844 5938

E-mail : kntcars@gmail.com

ROC number : 53208965X

AIG INSURANCE

REPAIR PERFORMA INVOICE

Vehicle number	SJJ7806A
Make / Model	TOYOTA VIOS
Chassis number	MR053HY9305078549
Accident date	13/12/19
Reference	T1912-22

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER Repair cut ✓	614.53
1	FRONT BUMPER RETAINER ?	162.50
1	FRONT RH FOG LAMP X	380.31
1	FRONT RH FOG LAMP COVER X	155.83
1	FRONT RH HEADLAMP ?	512.51
1	FRONT BONNET X	702.75
1	FRONT BONNET HINGE X	115.00
1	FRONT FENDER bum ✓	642.85
1	FRONT FENDER EMBLEM new ✓	193.20
1	FRONT FENDER INNER SHIELD new ✓	51.75
1	FRONT CROSS MEMBER X ?	2070.00
1	FRONT RH KNUCKLE ARM ?	569.25
1	FRONT RH KNUCKLE ARM BEARING ?	166.75
1	FRONT RH LOWER ARM X	1144.25
		7481.48
	Less 25%	1870.37
		5611.11
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	RIM cut ✓	800.00 300
1	TYRE	500.00 X
1 SET	FRONT BUMPER CLIP new ✓	50.00 30
1 SET	FRONT FENDER INNER SHIELD CLIP new ✓	50.00 30
	Subtotal	1400.00
	Balance C/F	7011.11
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	7011.11
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 30
2	REMOVE, RENEW & REFIT OLD BONNET TO NEW	150.00 X
2	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT	150.00 60
3	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	200.00 80?
4	PANEL BEATING ON AFFECTED AREAS	900.00 400
5	SPRAY PAINTING ON AFFECTED AREAS	1200.00 400 600
6	APPLY ANTI RUST ON AFFECTED AREAS	150.00 60 40
	Subtotal	2810.00
	Grand total	9821.11

Rasul
 Hp 90010068
 5 days
 4/5
 17/12/19 @ 1625
 Repair after repair