

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

17-Dec-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6418 D

1 pc	Rear bumper o/s side bracket XNV	\$	29.00
1 pc	Rear bumper X(R)	\$	696.00
1 pc	Rear o/s wheel cover SCX ✓	\$	116.00
		\$	841.00
	Less 10%	\$	84.10
		\$	756.90

S/NETT

1 pc	Rear o/s fender sticker rec ✓	\$	60.00
	Sundry	\$	50.00 \$30
	To check for rear o/s wheel alignment	\$	80.00 XNV
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same etc	\$	550.00 \$360
	To putty and spray painting on rear o/s fender, rear bumper	\$	400.00 \$360
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 \$50
		\$	2,016.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram (LKK)

19/12/19 10:10 hrs

Parasuram@lkkauto.com

886227284

3 repair days

45

att repair photo