

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 23064

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1482/2019/NS
Date : 16-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr See Soon Keong
Address : 79 West Coast Crescent
#31-05
Singapore 126793
Telephone : (HP)+65 98383533
Type of Claim : Own Damage Claims
Policy No. : 1700009492-02
Vehicle No. : **SDV 3533 X**
Model Code : Audi Q7 2.0 TFSI QU
Model / Year : 25/5/2017
Engine No. : CYR 027551
Chassis No. : WAUZZZ4M8HD029004
Mileage : 35807
Date In : 16-Dec-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Dec-19
Place of Accident : Clementi Ave 2 Towards AYE Junction

premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDV 3533 X

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To tow vehicle from accident scene.	S/N 280.00	X.
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
3	To remove and renew aircond condenser, additional radiator and charge air cooler. To install radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,600.00	X. ✓ <i>88.5</i>
4	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$ 300.00	✓

SUB TOTAL LABOUR CHARGES

: \$ 2,660.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDV 3533 X

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
5	To dismantle and renew front bumper, bonnet, lhs front fender, and lhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 6,750.00	3800 2100 3900 - 3600
6	To respray front bumper, lhs front bumper spoiler, bonnet, lhs front fender, both front wheel arch trims and lhs front door.	\$ 5,600.00	2900 4 x 600 = 2400 2 x 150 = 300 wheel cover spoiler 200
7	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00	???
8	To carry out diagnostic check.	S/N \$ 192.00	✓

TOTAL LABOUR CHARGES

: \$ 15,482.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDV 3533 X

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted</i>	\$ 2,242.00	✓ 1793.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 403.00	+ X
3	FRONT BUMPER AIR GUIDE - LH <i>Not Nec</i>	\$ 60.00	? X
4	FRONT BUMPER END CAP - LH <i>Not Nec</i>	\$ 32.00	? X
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>included.</i>	\$ 252.00	+ ✓ 201.20
6	FRONT BUMPER GRILLE - LOWER CENTRE <i>Not Nec</i>	\$ 187.00	X
7	FRONT UNDERRUN BAR <i>reld</i>	\$ 735.00	— 588
8	FRONT BUMPER CLOSING ELEMENT <i>included.</i>	\$ 191.00	? ✓ 152.40
9	FRONT BUMPER SPOILER - LH <i>Damaged</i>	\$ 192.00	✓ 153.60
10	FRONT BUMPER SPOILER - LH OUTER	\$ 40.00	✓ 31.52
11	FRONT BUMPER COVER CAP - LH <i>Ryir</i>	\$ 52.00	X
12	RADIATOR GRILLE <i>cut</i>	\$ 2,269.00	✓ 1815.20
13	RADIATOR GRILLE COVER <i>Green</i>	\$ 62.00	+
14	RADIATOR GRILLE INNER COVER	\$ 56.00	+
15	FRONT BUMPER AIR GUIDE GRILLE - LH <i>missing</i>	\$ 271.00	— 216.40
16	FRONT BUMPER END CAP - LH <i>Not Nec</i>	\$ 30.00	? X
17	RADIATOR GRILLE SPOILER - LH <i>Not Nec</i>	\$ 55.00	X
18	FRONT BUMPER CARRIER <i>Bent.</i>	\$ 791.00	? ✓ 632.40
19	FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>	\$ 156.00	✓ 124.40
20	FRONTBUMPER GUIDE SECTION - LH <i>Damaged</i>	\$ 40.00	✓ 31.52

SUB-TOTAL SPARE PARTS

: \$ 8,116.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDV 3533 X

S/N	Parts Description			Damaged Parts & Prices	
				S/Nett	Remark
21	FRONT BUMPER SUPPORT - LH / RH	RH dented	2	\$ 66.00	✓ 25.84
22	FRONT BUMPER COVER	Neu		\$ 119.00	+
23	CAUTION SIGN STICKER	Neu	NEC	\$ 13.00	+
24	FRONT PARKING AID SENSOR - INNER / OUTER	outer missing	2	\$ 462.00	231.184.80
25	FRONT PARKING AID SEAL RING	Neu	4	\$ 12.00	- 10.24
26	FRONT BUMPER WIRING SET	Neu		\$ 582.00	+
27	FANFARE BRACKET - LH LOW TONE	Best.		\$ 206.00	✓ 164.80
28	FRONT FENDER - LH	Distorted		\$ 1,481.00	1184.80
29	FRONT FENDER ATTACHMENT PARTS	Not Nec		\$ 69.00	? X
30	FRONT FENDER BRACE - LH FRONT	Best. Best.		\$ 93.00	✓ 74.08
31	FRONT FENDER BRACKET - LH	Not Nec		\$ 59.00	? X
32	FRONT FENDER CLOSING ELEMENT - LH	Neu		\$ 30.00	? X
33	FRONT FENDER BRACKET - LH	Not Nec		\$ 56.00	? X
34	FRONT WHEEL HOUSING LINER - LH	Dented		\$ 223.00	178.40
35	REAR WHEEL HOUSING LINER - LH	Neu		\$ 223.00	+
36	WHEEL HOUSING LINER ATTACHMENT PARTS	Not Nec		\$ 50.00	? X
37	BONNET	Dented		\$ 4,511.00	✓ 3608.80
38	BONNET ATTACHMENT PARTS	Neu		\$ 89.00	? X
39	BONNET LID HINGE - LH / RH	Neu	2	\$ 152.00	+
40	BONNET IMPACT PROTECTION - FRONT	torn		\$ 97.00	- 77.04

SUB TOTAL SPARE PARTS

: \$ 8,593.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDV 3533 X

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	FRONT FENDER SEAL - LH <i>Not nec</i>	\$	56.00 ? X
42	HEADLAMPS COVER - LH <i>ple n</i>	\$	93.00 +
43	BONNET STRIKER - LH <i>nec n</i>	\$	109.00 +
44	BONNET BOWDEN CABLE - CENTRE <i>nec n</i>	\$	53.00 +
45	BONNET LID LOCK	\$	201.00 ✓
46	BONNET LID LOCK CABLE	\$	81.00 +
47	BONNET RELEASE LEVER	\$	13.00 +
48	BONNET LID LOCK CABLE	\$	106.00 +
49	HEADLIGHT MOUNTING - LH <i>cracked</i>	\$	107.00 - 85.20
50	LED HEADLIGHT <i>cracked</i>	\$	9,074.00 - 7259.20
51	MAIN LIGHT ELECTRONICS POWER MODULE <i>nec n</i>	\$	716.00 +
52	LIGHT CONTROL SYSTEM CONTROL UNIT - LH	\$	685.00 +
53	HEADLIGHT HOSE - LH <i>nec n</i>	\$	35.00 +
54	HEADLAMP FANS <i>Not nec</i>	\$	363.00 ? X
55	LIFT CYLINDER - LH <i>Not nec</i>	\$	181.00 ? X
56	HEADLIGHT HOSE - LH <i>nec n</i>	\$	88.00 +
57	FRONT WHEEL COVER - LH / RH <i>nec</i>	2 \$	1,044.00 - 834.40
58	LOCK CARRIER <i>cracked</i>	\$	1,100.00 ? ✓ 880.00
59	RADIATOR AIR GUIDE - LH OUTER <i>near Deformed</i>	\$	41.00 + ✓ 32.24
60	ADDITIONAL RADIATOR <i>not in Deformed</i>	\$	613.00 ✓ 506.40

SUB TOTAL SPARE PARTS

: \$ 14,759.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDV 3533 X

S/N	Parts Description		S/Nett	Damaged Parts & Prices	
				S/Nett	Remark
61	ADDITIONAL RADIATOR BRACKET	Bent	\$	121.00	✓ 96.80
62	ADDITIONAL RADIATOR BRACKET LH REAR		\$	23.00	✓ 18.96
* 63	REFRIGERANT LINE	Bent	\$	204.00	✓ 163.20
* 64	REFRIGERANT LINE		\$	234.00	✓ 186.80
65	PRESSURE HOSE - LH		\$	246.00	X
66	CHARGE AIR COOLER	Not in	\$	855.00	X
67	READY MIX COOLANT	Nec	4 \$	84.00	X ✓ 67.20
68	AIRCON CONDENSER	Not Nec	\$	878.00	X
69	RADIATOR AIR GUIDE - UPPER / LOWER	could	2 \$	74.00	✓ 59.04
70	RADIATOR AIR GUIDE - LH	Behind	\$	25.00	✓ 20.00
71	FRONT ALUMINIUM RIM - LH	Not Nec	\$	1,116.00	✓ ? X
72	ALUMINIUM RIM RUBBER VALVE	Not in	4 \$	13.00	X
73	AIRCON STICKER	Nec	NEC \$	7.00	✓ 5.12
74	FRONT NO PLATE	Nec	S/N \$	40.00	✓
75	SUNDRIES	Nec	\$	400.00	✓ 136.16

TOTAL SPARE PARTS

TOTAL LABOUR CHARGES

GRAND TOTAL

: \$ 35,788.00
: \$ 15,482.00
: \$ 51,270.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 17/12/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/1482/2019/NS

20-Dec-19

Glory Tan

1 of 1

SDV 3533 X

Audi Q7 2.0 TFSI QU

Quantity Description

Parts

1

Refrigerant pipe

2

Refrigerant line

Unit Price Amount

\$ 494.00 ~~394.80~~
\$ 204.00 ~~163.20~~

TOTAL

\$ 698.00

For Premium Automobiles Pte Ltd

Authorised Signature

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: