

ASS. REC. BY:

Steve

REF:

AIG CC3/AIG 19022239/ETf3

ASSIGNMENT

From:

Date:

17-12-2019

Veh No:

SKC 95306

Yr Regn:

20/9/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKC 95306

at Workshop m/s

Premium

of

281 Alexandra Road

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

1pm onmr wshy

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV

REP. / 24 HRS

sup

Vehicle: IN / OUT

Date:

Person Contacted:

Truck / Trailer or

Make:

Audi Q7

C.C.

1984

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

2063

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAU2224M7K0940471

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

255/55R19

R:

n

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

10/2/19

D.O.I.

17/12/19

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or *

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-246K

SKC 95306 - CS/MSG 16021128/ATbm2 Rat-31/190016

18/12-

Mandate Request

19/12-

Authorise repair by Kok chong

19/12-

Inform authorise repair excess 1000 via email to premium
before paint front bumper required.

Part by part \$8,306.96 (Red: 23,229.04 : 73%)

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

5

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

Lump Sum / LB: 8306.96

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 22949

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1476/2019/GW
Date : 16-Dec-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Qing GuangMei
Address : Blk 186 Depot
#22-13
Singapore 109687
Telephone : (HP)+65 98583416
Type of Claim : Own Damage Claims
Policy No. : 1900163652
Vehicle No : **SKC 9530 G**
Model Code : Audi Q7 2.0 TFSI QU
Model / Year : 20-09-19
Engine No : CYR 096543
Chassis No : WAUZZZ4M7KD040471
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Dec-19
Place of Accident : Demspy Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKC 9350 G

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 /	✓
3	To dismantle and renew front bumper, bonnet and rhs headlight. Re-organize front crash management components. Reinstall all parts removed. <i>500</i>	\$ 3,150.00 <i>500</i>	<i>600</i>
4	To respray front bumper, rhs front bumper spoiler, bonnet and both front wheel arch covers. <i>550 x 1.8 2.5</i>	\$ 3,800.00	<i>1375 2100</i>
5	To carry out diagnostic check.	S/N \$ 192.00 /	✓
TOTAL LABOUR CHARGES		: \$ 7,622.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKC 9350 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER ✓	\$ 2,242.00	1793.60
2	FRONT BUMPER FIXING PARTS ?	\$ 403.00	X
3	FRONT TOW EYE COVER-RH X	\$ 32.00	
4	FRONT BUMPER AIR GUIDE - RH ?	\$ 60.00	X
5	FRONT BUMPER CLOSING ELEMENT ?	\$ 252.00	X
6	FRONT BUMPER GRILLE-LOWER CENTRE X	\$ 187.00	
7	FRONT UNDERRUN BAR X	\$ 735.00	
8	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE ?	\$ 191.00	X
9	FRONT BUMPER SPOILER-RH ✓ BR	\$ 192.00	153.60
10	FRONT BUMPER SPOILER-RH OUTER ?	\$ 40.00	
11	RADIATOR GRILLE ✓ CAT	\$ 2,269.00	1815.20
12	RADIATOR GRILLE COVER ?	\$ 62.00	
13	AUDI EMBLEM BRACKET ✓ nec	\$ 56.00	44.72
14	FRONT AIR GUIDE GRILLE-RH ✓ CAT	\$ 271.00	216.40
15	FRONT END CAP-RH X	\$ 31.00	
16	FRONT BUMPER SPOILER-RH INNER ?	\$ 55.00	
17	BONNET X R	\$ 4,511.00	
18	BONNET IMPACTPROTECTION ✓ nec	\$ 97.00	77.04
19	BONNET ATTACHMENT PARTS X	\$ 89.00	
20	HEADLIGHT COVER-RH X	\$ 93.00	
SUB-TOTAL SPARE PARTS		\$ 11,868.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

4

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKC 9350 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT FENDER COVER-LH X	\$ 40.00	
22	HEADLIGHT MOUNTING-RH ?	\$ 107.00 X	
23	LED HEADLIGHT-RH ?	\$ 9,074.00 X	
24	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM-RH ?	\$ 181.00 X	
25	HOSE FOR HEADLIGHT WASHER SYSTEM-RH ?	\$ 88.00 X	
26	AIR CONDITIONER STICKER X	\$ 7.00	
27	SIGN " CAUTION " STICKER X	\$ 13.00	
28	FOAM FILLER PIECE X	\$ 156.00	
29	FRONT BUMPER REINFORCEMENT BAR ?	\$ 791.00 X	
30	FRONT REINFORCEMENT BAR SUPPORT-LH/RH ? 2	\$ 66.00 X	
31	FRONT BUMPER GUIDE SECTION-RH ?	\$ 40.00 X	
32	RADIATOR AIR GUIDE-RH ?	\$ 25.00 X	
33	RADIATOR AIR GUIDE-RH UPPER ?	\$ 37.00 X	
34	RADIATOR AIR GUIDE-RH LOWER ?	\$ 37.00 X	
35	FRONT WHEEL COVER-LH/RH / 1pc 2	\$ 1,044.00 834.40	
36	FRONT NO. PLATE X	S/N \$ 40.00	
37	SUNDRIES ?	\$ 300.00 X	
TOTAL SPARE PARTS :		\$ 23,914.00	
TOTAL LABOUR CHARGES		\$ 7,622.00	
GRAND TOTAL		\$ 31,536.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

5

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

[Handwritten signature]
19/12/19

Telefax

Name : Steve (LKK) 90 - Not Author (Remy)
Surveyed Date : 17/12/19, 1-15pm
Authorised Date : Excess - ?
Excess Cost : 5 days
Liability : P/P
Remarks : Rg ReL 5m

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant