

REPAIR DETAILS

SUPPLEMENTARY

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Jun 2020)

Parts: 143 OPEL INSIGNIA GRANDSPORT B16DTH 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SMG9846B/16/06/2020 10:15

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/Values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Steering rack end RH	0.00	0.00	By *254.00 F ✓
2	1		*Steering tie rod RH	0.00	0.00	By *261.00 F ✓
3	1		*Front bumper beam RH	0.00	0.00	By *14.00 F ✓
4	3		*Front bumper rivets (Original)	0.00	0.00	K *3.00 F ✓
5	1		*Pedestrian safety sensor	0.00	0.00	short *257.00 F ✓
Sub Total (S\$)						789.00
+ Margin on L,N Items 10.00% (S\$)						78.90
Total Parts (S\$)						867.90

P=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SMG9846B/16/06/2020 10:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To spray paint (front bumper) <i>in foreman</i>	New	80.00 ✓
<u>Labour Items</u>			
2	To check/erase fault codes	New	100.00 ✓
3	To dismantle + renew steering rack + tie rod	New	120.00 ✓
4	To knock dents on front bumper reinforcement	New	120.00 ✓
Gross Labour Cost (S\$)			420.00

Lai Huat (Meng Kee) Motor Pte Ltd/SMG9846B/16/06/2020 10:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >