

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Dec 2019		18 Dec 2019 09:48 Edit Adj Rpt	S\$2,490.52 Edit Estimates	S\$2,490.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: HADEMALM BO GORAN , ID: S2644121H									
Vehicle Reg. No.: SCR7100T		Date of Loss: 13/12/2019 18:00 - :59 [47 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D205991C02		Policy/Cover Note No.: DMCVSN19086019000							
Vehicle Reg. No. (Insured): YN5936Y		Policy No. (Claimant): 2100443847-04							
		Excess: S\$500.00							
Repairer: TC AutoClinic Pte Ltd (Leng Kee) 25 Leng Kee Road, 159097 Leng Kee - Tel: 67038511									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 30/12/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SCR7100T (SNM19D205991C02)
[YN5936Y]
TP
HADEMALM BO GORAN
Dec 13 2019 6:00PM
[-]
TC AutoClinic Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

No	Finalized On	TC AutoClinic Pte Ltd (Leng Kee)		Thumbnail	Print
1	16/12/19 10:15	Video - Accident [Linked Accident Report Documents]		Load MP4	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/12/19 17:15	General View		Load JPG	☒
2	30/12/19 17:15	General View		Load JPG	☒
3	30/12/19 17:15	General View		Load JPG	☒
4	30/12/19 17:15	General View		Load JPG	☒
5	30/12/19 17:15	General View		Load JPG	☒
6	30/12/19 17:15	General View		Load JPG	☒
7	30/12/19 17:15	General View		Load JPG	☒
8	30/12/19 17:15	General View		Load JPG	☒
9	30/12/19 17:15	General View		Load JPG	☒
10	30/12/19 17:15	General View		Load JPG	☒
11	30/12/19 17:15	General View		Load JPG	☒
12	30/12/19 17:15	General View		Load JPG	☒
13	30/12/19 17:15	General View		Load JPG	☒
14	30/12/19 17:15	Odometer Reading		Load JPG	☒
15	30/12/19 17:15	Chassis Number		Load JPG	☒
16	30/12/19 17:15	General View		Load JPG	☒
17	30/12/19 17:15	General View		Load JPG	☒
18	30/12/19 17:15	General View		Load JPG	☒
19	30/12/19 17:15	General View		Load JPG	☒
20	30/12/19 17:15	General View		Load JPG	☒
21	17/03/20 08:59	Photographs of Damaged Items		Load JPG	☒
22	17/03/20 08:59	Photographs of Damaged Items		Load JPG	☒
23	17/03/20 08:59	Photographs of Damaged Items		Load JPG	☒
24	17/03/20 08:59	Reinspection Photo		Load JPG	☒
25	17/03/20 08:59	Reinspection Photo		Load JPG	☒
26	17/03/20 08:59	Reinspection Photo		Load JPG	☒

Linked Accident Report Documents

			View View in Browser	
Video			1 per page	☒
No	Finalized On	TC AutoClinic Pte Ltd (Leng Kee)	Thumbnail	Print
1	16/12/19 10:15	Video - Accident	Load MP4	

Video			1 per page	☒
No	Finalized On	TC AutoClinic Pte Ltd (Leng Kee)	Thumbnail	Print
Assessment Reports				
			1 per page	☒
No	Finalized On	TC AutoClinic Pte Ltd (Leng Kee)	Thumbnail	Print
1	16/12/19 10:18	Accident Statement	 Load HTM	
Photos/Images				
			3 per page	☒
No	Finalized On	TC AutoClinic Pte Ltd (Leng Kee)	Thumbnail	Print
1	16/12/19 10:16	COI	 Load JPG	☒
2	16/12/19 10:16	Driving License	 Load JPG	☒
3	16/12/19 10:16	Accident Photo	 Load JPG	☒
4	16/12/19 10:16	Accident Photo	 Load JPG	☒
5	16/12/19 10:16	Accident Photo	 Load JPG	☒
6	16/12/19 10:16	Accident Photo	 Load JPG	☒
7	16/12/19 10:16	Accident Photo	 Load JPG	☒
8	16/12/19 10:16	Accident Photo	 Load JPG	☒
9	16/12/19 10:16	Accident Photo	 Load JPG	☒
10	16/12/19 10:16	Accident Photo	 Load JPG	☒
11	16/12/19 10:16	Accident Photo	 Load JPG	☒
12	16/12/19 10:16	Accident Photo	 Load JPG	☒
13	16/12/19 10:16	Accident Photo	 Load JPG	☒
14	16/12/19 10:16	Driving License	 Load JPG	☒
15	16/12/19 10:16	Driving License	 Load JPG	☒
16	16/12/19 10:16	Accident Photo	 Load JPG	☒
17	16/12/19 10:16	Accident Photo	 Load JPG	☒
18	16/12/19 10:16	Accident Photo	 Load JPG	☒
19	16/12/19 10:16	Accident Photo	 Load JPG	☒
Documentation				
			1 per page	☒
No	Finalized On	TC AutoClinic Pte Ltd (Leng Kee)	Thumbnail	Print
1	16/12/19 10:15	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119022260/ETF3E2

Date: 30/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN19086019000

Claimant Vehicle
No : SCR7100TInsured Vehicle
No : YN5936Y

Date of Loss: 13/12/2019

Nature of Claim: TP

Claim
No: SNM19D205991C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCR7100T

Make & Model: NISSAN X-TRAIL, 2.0 CVT (A)

Engine No: MR20790525B

Reg. Date: 17/12/2015 (Man. Year: 2015)

Chassis No: JN1JANT32Z0001232

Colour: Red

Odometer: 64302 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,527.80	725.52	7,802.28	91.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,352.00	1,765.00	2,587.00	59.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,879.80	2,490.52	10,389.28	80.66
+ GST 7.00/7.00% (S\$)	901.59	174.34	727.25	80.66
Nett Amount (S\$)	13,781.39	2,664.86	11,116.53	80.66

INSPECTION

Date of Assignment: 18/12/2019

Date Inspected: 30/12/2019 Inspected At:

TC AutoClinic Pte Ltd (Leng Kee)
25 Leng Kee Road
Singapore 159097

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Mar 2020)	
Parts:	N/A	NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCR7100T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER BODYKIT	Not Necessary	484.20 FS	*- FS
2	1		*X-TRAIL EMBLEM	Necessary	110.00 FN	*110.00 FN
3	1		*NISSAN EMBLEM	Necessary	64.90 FN	*64.90 FN
4	1		*REAR RIGHT QUARTER GLASS	Not Necessary	400.00 FS	*- FS
5	1		*REAR RIGHT FENDER	Repair	1,155.20 FN	*- FN
6	1		*TAILGATE CENTRE FINISHER	Not Necessary	145.20 FN	*- FN
7	1		*TAILGATE GLASS	Not Necessary	1,386.00 FN	*- FN
8	1		*TAILGATE	Repair	4,380.00 FN	*- FN
9	1		*RIGHT REINFORCEMENT STAY	Not Necessary	195.60 FN	*- FN
10	1		*REINFORCEMENT	Not Necessary	596.20 FN	*- FN
11	1		*RIGHT BUMPER BRACKET	Broken	38.90 FN	*38.90 FN
12	1		*BUMPER CENTRE FINISHER	Not Necessary	117.50 FN	*- FN
13	1		*REAR BUMPER	Dented	693.10 FN	*693.10 FN
14	1		*REAR UPPER PANEL	Not Necessary	447.50 FN	*- FN
15	1		*REAR RIGHT FENDER TRIM	Not Necessary	162.50 FN	*- FN
16	1		*RIGHT REFLECTOR	Not Necessary	61.90 FN	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	10,438.70	906.90
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	1,910.90	181.38
Total Parts (\$\$)	8,527.80	725.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	**COMPLETE WAXING OF VEHICLE	New	71.00	0.00
2	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	New	120.00	0.00
3	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	120.00	120.00
4	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	New	55.00	55.00
5	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	300.00	0.00
6	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN / SHORT CIRCUIT, REPAIR WHEN NECESSARY	New	240.00	0.00
7	REPLACE REAR BUMPER, BODYKIT, TAILGATE, REAR RIGHT FENDER & TRIM, REFLECTOR ETC. REPAIR PANELS	New	1,400.00	840.00
8	REPLACE TAILGATE GLASS TO FACILITATE REPAIR	New	250.00	0.00
9	INSTALL SOLAR FILM ON TAILGATE GLASS	New	144.00	0.00
10	REPLACE REAR RIGHT QUARTER GLASS TO FACILITATE REPAIR	New	250.00	0.00
11	INSTALL SOLAR FILM ON REAR RIGHT QUARTER GLASS	New	32.00	0.00
12	REMOVE & INSTALL HEADLINER, SEATS, CARPETING, PANELS TO FACILITATE REPAIR	New	120.00	0.00
13	RESPRAY REAR BUMPER, BODYKIT, TAILGATE, REAR RIGHT FENDER ETC	New	1,250.00	750.00
14	QC, RETUNE & CONSULT CHECK (NPA)	New	0.00	0.00
15	COMPLIMENTARY WASH & VACUUM (NPA)	New	0.00	0.00
Gross Labour Cost (S\$)			4,352.00	1,765.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >