

ASS. REC. BY:

REF: CS/CT119022169/T19f322

Special Instructions:

WMMW

Toufex

ASSIGNMENT (Office)

From (Person): Mr. Xing Hui Ping

of CT1

Date/Time: 18.12.19 14.46pm

Estimated Cost:

Bill No:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 58164

Insured: YL 7304T

at Workshop n/s: N-51 Automotive

Tel: 68420051

of Blk 2 Kaki Bukit #01-17/18

Policy No: DMKRSN30243367000

Claim No: SNM19D20598402

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 16.12.2019

CA / REV / REP. / REV 24 HRS

"up"

Date/Time: 18.12.19

Person Contacted: Zi Ting

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time Action/Instruction ( ☒ ) Estimate

SLT 58164 - X

YL 7304T - NA/CT119022114/24 DON - 16/12/2019



## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins. Auth'd	Status
Main	18 Dec 2019		18 Dec 2019 14:46 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:			
Main Claimant:	DARWIN-51 CAR RENTAL PTE LTD		
Vehicle Reg. No.:	SLT5816H	Date of Loss:	16/12/2019 11:00 - :59
Claim Type:	TP / SNM19D205984C02	Policy/Cover Note No.:	DMCVSN30433619000
Vehicle Reg. No. (Insured):	YL7304T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/12/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Summer Lee (LKK Auto)

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Wednesday, 18 December, 2019 2:22 PM  
**To:** ziting@n51.com.sg  
**Cc:** Asher Sng (LKK Auto); assignments  
**Subject:** FW: OUR REF: SNM19D205984/YL7304T/IRENE - SLT5816H & YL7304T - NOTICE TO INSURER TO CONDUCT PRI WITHIN 2 WORKING DAYS  
**Attachments:** 16122019154026-0001.pdf

Dear Sir (LKK),

We refer to the above matter.

Please get your surveyor to liaise with LKK to conduct survey.

Regards,

**Irene Tay**

Executive

Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 62247478/62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Claims Dept of CTI

**Sent:** Tuesday, December 17, 2019 10:00 AM

**To:** Irene Tay <irene.tay@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; ziting@n51.com.sg

**Subject:** OUR REF: SNM19D205984/YL7304T/IRENE - SLT5816H & YL7304T - NOTICE TO INSURER TO CONDUCT PRI WITHIN 2 WORKING DAYS

Dear Irene,

Please conduct PRS for SLT5816H.

Note : officer in charge – Irene Tay 63896192.

**\*\*\* Kindly quote our reference number when replying.**

Thank You.

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Ziting [<mailto:ziting@n51.com.sg>]

**Sent:** Monday, December 16, 2019 3:43 PM

**To:** Claims Dept of CTI

**Subject:** SLT5816H & YL7304T - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer to attachment and:-

Kindly propose / provide your 10 surveyors

Thank you.

Regards,

Zi Ting

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

[www.n51.com.sg](http://www.n51.com.sg)



---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/12/2019 13:55
Date Of Accident	16/12/2019 11:30
Exact Location Of Accident	WOODLANDS ROAD BEFORE STAGMONT RING
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT5816H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	DARWIN-51 CAR RENTAL PTE LTD
Co Reg No	201407909C
Email Address	SALES@N51.COM.SG
Mobile Phone No	(LOCAL) +65-88215151
Alternative Phone No	OFFICE-88215151

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS ALPHA HYBRID 1.8S A
Exact Purpose for which vehicle was being used at time of accident	CHAUFFEUR
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD19V08678/VPZ/R02
Cover Note Number	

### Driver

Name of Driver	MOHAMED RIDZWAN BIN MOHAMID IBRAHIM
NRIC No	S7934754Z
Date Of Birth	19/11/1979
Occupation	OUTDOOR
Date Of Driving Pass	17/10/2002
Driving Experience	17 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-93380696
Fax Number	
Contact Number	OTHERS-93380696
Email Address	MDRIDZWAN@GMAIL.COM

Address	APT BLK 769 CHOA CHU KANG STREET 54 #02-13 SINGAPORE
Postcode	680769
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YL7304T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLT9939K
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

#### DETAILS OF INJURED PERSON 1

Name

MOHAMED RIDZWAN BIN MOHAMID IBRAHIM

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLT5816H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

APT BLK 769 CHOA CHU KANG STREET 54 #02-13  
SINGAPORE

Postcode

680769



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/2/19 at @ 1130 hrs. I was travelling in my vehicle (SLT 58164) along Woodlands Road before Stoppage Ring on the extreme left lane. I slow down and stopped due to the vehicle ahead stopped. Suddenly, I felt a great impact from the rear. I got down from my vehicle and found it was a chain collision involving 3 vehicles.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

**DARWIN-51 CAR RENTAL PTE LTD**  
 2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT  
 AUTOHUB  
 SINGAPORE 417921

Contact : 88215151 93380696

## ESTIMATE

Repair Code : CLM15865

Date in : 16/12/2019

Vehicle Num. : SLT5816H

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S A

Chassis/Eng# : ZVW400026293/2ZR1995003

88235151

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER	1	523.90 <i>de✓</i>	523.90
REAR BUMPER REFLECTOR L/R	2	58.00 <i>X AN</i>	116.00
REAR BUMPER SIDE RETAINER L/R	12 <i>RH X AN</i>	98.00 <i>LH-CR✓</i>	196.00 <i>98</i>
REAR END PANEL	1	630 781.45 <i>bt✓</i>	781.45
REAR END PANEL ANTENNA SENSOR	1	385 485.00 <i>CR✓</i>	485.00
REAR END PANEL INNER TOP GARNISH	1	287.90 <i>de✓</i>	287.90
REAR SPONGE COMPARTMENT TRAY	1	396.70 459.70 <i>de✓</i>	459.70
REAR SPONGE COMPARTMENT TRAY TOP COVER	1	655.00 <i>X AN</i>	655.00
REAR TAILGATE	1	929.60 <i>bt✓</i>	929.60
REAR TAILGATE 'HYBRID' EMBLEM	1	50.00 <i>ne✓</i>	50.00
REAR TAILGATE 'PRIUS' EMBLEM	1	52.30 <i>ne✓</i>	52.30
REAR TAILGATE INNER PULL GARNISH	1	38.50 <i>X AN</i>	38.50
REAR TAILGATE INNER TRIM BOARD	1	578.00 <i>CR✓</i>	578.00
REAR TAILGATE MECHANISM LOCK	1	374 425.00 <i>bt✓</i>	425.00
REAR TAILGATE OUTER GARNISH	1	428.30 <i>de✓</i>	428.30
REAR TAILGATE OUTER GARNISH 'LOGO' EMBLEM	1	87.10 <i>ne✓</i>	87.10
REAR TAILGATE RUBBER GUIDE STOPPER L/R	2	29.00 <i>X AN</i>	58.00
REAR TAILGATE WEATHER STRIP	1	360.70 <i>twi✓</i>	360.70

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD  
2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT  
AUTOHUB  
SINGAPORE 417921

Contact : 88215151 93380696

## ESTIMATE

Repair Code : CLM15865

Date in : 16/12/2019

Vehicle Num. : SLT5816H

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S A

Chassis/Eng# : ZVW400026293/2ZR1995003

REAR TAILGATE WINDSCREEN LOWER SEAL	1	42.00	nei ✓	42.00
REAR TAILGATE WINDSCREEN MOULDING L/R	2	65.00	nei ✓	130.00
REAR TAILGATE WINDSCREEN UPPER SEAL	1	38.00	nei ✓	38.00
REAR TAILLAMP L/R	1/2 n n R H X	630.00	LH n ✓	1,260.00 <sup>630</sup>
REAR TAILLAMP LOWER BRACKET L/R	1/2 n n R H X	68.00	LH n ✓	136.00 <sup>68</sup>
Subtotal before discount				5879.50 8,118.45
Percentage discount 25%				4409.62 2,029.61
Sub-total 1				6,088.84
REAR BUMPER CLIPS - SET	1	80.00	3one ✓	80.00
REAR BUMPER REVERSE SENSOR	1	350.00	200 n n ✓	350.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	20.00	nei ✓	20.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	50.00	2one ✓	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	1	20.00	n n X	20.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	4one ✓	80.00
REAR TAILLAMP CLIPS L/R - SET	2	30.00	n n X	60.00
Subtotal before discount				660.00
Percentage discount 0%				310 0.00
Sub-total 2				660.00
Parts-total				6,748.84

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD  
2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT  
AUTOHUB  
SINGAPORE 417921

Contact : 88215151 93380696

## ESTIMATE

Repair Code : CLM15865

Date in : 16/12/2019

Vehicle Num. : SLT5816H

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S A

Chassis/Eng# : ZVW400026293/2ZR1995003

## LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	30	100.00
To remove, reinstall tailgate windscreen	120	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60	140.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	600	1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	600	1,000.00
To apply anti-rust chemical on repaired and replaced panel.	30	120.00
To remove, reinstall tailgate mechanism and check for function	60	80.00
<b>Labour Total</b>		<b>2,590.00</b>
<b>Parts &amp; Labour Total</b>	1500	<b>9,338.84</b>

\*\*\* This is a computer-generated document which requires no signature. \*\*\*

page 3

LKIC Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah  
97495749  
w/ 18/12/19  
lumpsum  
Being after repair.

4409.62  
310  
1500  
6219.62  
4/5 \$49.510 #  
5 days

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2019		18 Dec 2019 14:46 <a href="#">Edit Adj Rpt</a>	<b>S\$4,950.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,950.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	- Co. Reg. No.: -		
Main Claimant:	<b>DARWIN-51 CAR RENTAL PTE LTD</b>		
Vehicle Reg. No.:	<b>SLT5816H</b>	Date of Loss:	16/12/2019 11:00 - :59 [25 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / SNM19D205984C02</b>	Policy/Cover Note No.:	DMCVSN30433619000
Vehicle Reg. No. (Insured):	<b>YL7304T</b>	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	<b>N-51 Automotive Pte Ltd (HQ)</b> BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 30/12/2019]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)






































There are no mail for this case.





































**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLT5816H (SNM19D205984C02)  
[YL7304T]  
TP  
DARWIN-51 CAR RENTAL PTE LTD  
Dec 16 2019 11:00AM  
[-]  
N-51 Automotive Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View <span>View in Browser</span>	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/03/20 17:33	Odometer Reading		 Load JPG	<input checked="" type="checkbox"/>
2	05/03/20 17:33	Chassis Number		 Load JPG	<input checked="" type="checkbox"/>
3	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
4	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
5	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
6	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
7	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
8	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
9	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
10	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
11	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
12	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
13	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
14	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
15	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
16	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
17	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
18	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
19	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
20	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
21	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
22	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
23	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
24	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
25	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
26	05/03/20 17:33	General View		 Load JPG	<input checked="" type="checkbox"/>
27	05/03/20 17:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
28	05/03/20 17:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
29	05/03/20 17:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
30	05/03/20 17:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
31	05/03/20 17:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
32	05/03/20 17:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
33	05/03/20 17:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
34	05/03/20 17:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
35	05/03/20 17:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
36	05/03/20 17:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
37	05/03/20 17:34	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	05/03/20 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	05/03/20 17:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
72	05/03/20 17:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
73	05/03/20 17:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			





# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119022269/T1QF3E2

Date: 16/03/2020

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN30433619000

Claimant Vehicle  
No: SLT5816HInsured Vehicle  
No: YL7304T

Date of Loss: 16/12/2019

Nature of Claim: TP

Claim  
No: SNM19D205984C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT5816H

Make &amp; Model: TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A)

Engine No: 2ZR1995003

Reg. Date: 01/11/2017 (Man. Year: 2017)

Chassis No: ZVW400026293

Colour: Silver

Odometer: 192442 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,748.84	4,877.12	1,871.72	27.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,590.00	1,500.00	1,090.00	42.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,338.84</b>	<b>6,377.12</b>	<b>2,961.72</b>	<b>31.71</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,950.00</b>		
<b>(S\$)</b>	9,338.84	4,950.00	4,388.84	47.00
<b>+ GST 7.00/7.00% (S\$)</b>	653.72	346.50	307.22	47.00
<b>Nett Amount (S\$)</b>	<b>9,992.56</b>	<b>5,296.50</b>	<b>4,696.06</b>	<b>47.00</b>

### INSPECTION

Date of Assignment: 18/12/2019

Date Inspected: 18/12/2019 Inspected At:

N-51 Automotive Pte Ltd (HQ)  
BLK 2 KAKI BUKIT, #01-17/18 KAKI  
BUKIT AUTOHUB  
Singapore 417921

Estimated Period of Repair: 5.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2020)	
<b>Parts:</b> 144	TOYOTA PRIUS ALPHA HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SLT5816H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	523.90 FL	*523.90 FL
2	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	116.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER L/R	N/S Cracked / O/S NotNecessary	196.00 FL	*98.00 FL
4	1		*REAR END PANEL	Bent	781.45 FL	*630.00 FL
5	1		*REAR END PANEL ANTENNA SENSOR	Cracked	485.00 FL	*385.00 FL
6	1		*REAR END PANEL INNER TOP GARNISH	Deformed	287.90 FL	*287.90 FL
7	1		*REAR SPONGE COMPARTMENT TRAY TOP COVER	Not Necessary	655.00 FL	*- FL
8	1		*REAR TAILGATE	Bent	929.60 FL	*929.60 FL
9	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	50.00 FL	*50.00 FL
10	1		*REAR TAILGATE PRIUS EMBLEM	Necessary	52.30 FL	*52.30 FL
11	1		*REAR TAILGATE INNER PULL GARNISH	Not Necessary	38.50 FL	*- FL
12	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	578.00 FL	*578.00 FL
13	1		*REAR TAILGATE MECHANISM LOCK	Bent	425.00 FL	*374.00 FL
14	1		*REAR TAILGATE OUTER GARNISH	Deformed	428.30 FL	*428.30 FL
15	1		*REAR TAILGATE OUTER GARNISH LOGO EMBLEM	Necessary	87.10 FL	*87.10 FL
16	2		*REAR TAILGATE RUBBER GUIDE STOPPER L/R	Not Necessary	58.00 FL	*- FL
17	1		*REAR TAILGATE WEATHER STRIP	Twisted	360.70 FL	*360.70 FL
18	1		*REAR TAILGATE WINDSCREEN LOWER SEAL	Necessary	42.00 FL	*42.00 FL
19	2		*REAR TAILGATE WINDSCREEN MOULDING L/R	Necessary	130.00 FL	*130.00 FL
20	1		*REAR TAILGATE WINDSCREEN UPPER SEAL	Necessary	38.00 FL	*38.00 FL
21	1		*REAR TAILLAMP L/R	N/S Cracked / O/S NotNecessary	1,260.00 FL	*630.00 FL
22	1		*REAR TAILLAMP LOWER BRACKET L/R	N/S Necessary/ O/SNotNecessary	136.00 FL	*68.00 FL
23	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
24	1		*REAR BUMPER REVERSE SENSOR	Not Working	350.00 FS	*200.00 FS
25	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
26	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*20.00 FS
27	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
28	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
29	2		*SET REAR TAILLAMP CLIPS L/R	Not Necessary	60.00 FS	*. FS
30	1		*REAR SPONGE COMPARTMENT TRAY	Deformed	459.70 FL	*396.70 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					8,778.45	6,399.50
- List Item Discount on L Items 25.00/25.00% (S\$)					2,029.61	1,522.38
Total Parts (S\$)					6,748.84	4,877.12

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR	New	100.00	30.00
2	TO REMOVE, REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	140.00	60.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	30.00
7	TO REMOVE, REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,590.00</b>	<b>1,500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >