



HKL LIM
TEAM MOTORSPORT

Blk 100B #01-24, Bukit Merah Lane 3, Singapore 159722
Email: support@hklimmotorsport.com.sg

Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Website: www.hklimmotorsport.com.sg

FBM8059L

- 1 FRONT FORK ASSY LH/RH ? bt -
- 2 FRONT FORK UNDER BRACKET ? bt -
- 3 STEERING CONE BEARING ? new
- 4 FRONT FENDER X suc
- 5 REAR FENDER X suc
- 6 FRONT WHEEL RIM X repair R+
- 7 FRONT WHEEL SHALF X bt
- 8 FRONT WHEEL BEARING 2PCS ? X suc
- 9 FRONT WHEEL BEARING OIL SEAL 7 X suc
- 10 FRONT BRAKE DISC ? bt
- 11 HEAD COWLING X suc
- 12 FRONT SIGNALS LH cm
- 13 HANDLE BAR ? bt
- 14 HANDLE BAR GRIP X suc
- 15 HANDLE BAR BALANCER suc
- 16 CLUTCH LEVER suc
- 17 SIDE MIRROR suc
- 18 HEAD PANEL X suc
- 19 GEAR PEDAL bt
- 20 BRAKE PEDAL X suc
- 21 TAIL BOARD LH/RH X suc
- 22 SIDE STAND X suc
- 23 MAIN STAND X suc
- 24 COVER SET STICKET X nn
- 25 LABOUR

\$	300.00	
\$	180.00	
\$	60.00	
\$	55.00	X
\$	150.00	
\$	280.00	X R
\$	45.00	
\$	40.00	X
\$	10.00	X
\$	120.00	
\$	150.00	X
\$	60.00	
\$	80.00	
\$	20.00	X
\$	20.00	
\$	25.00	
\$	45.00	
\$	60.00	X
\$	55.00	
\$	60.00	X
\$	180.00	X
\$	45.00	X
\$	80.00	X
\$	120.00	X
\$	680.00	300 - Labour
\$	2,920.00	3040.00

1140
1096
1026

TOTAL

Side fending Un- \$ 120 X suc Resu

1026
300
1326
20%

1060.80

4/5 - 1,050

3 days

Resu
Resu
22/07/2020

3 days
4/5
19/12/19 @ 1540
Resu after repair