

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT119022270/R1VF3E2**Date:** 27/07/2020**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSN19304719000

Claimant Vehicle No : FBM8059L**Insured Vehicle No :** SLX815Y

Date of Loss: 14/12/2019

Nature of Claim: TP

Claim No: SNM19D205992C02

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBM8059L**

Make & Model: YAMAHA SNIPER T150, 150cc

Engine No: G3E6E0359203

Reg. Date: 06/04/2018 (Man. Year: 2018)

Chassis No: MH3UG0740J0085833

Colour: Multi-colour

Odometer: 50415 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:**CONDITION OF TYRES**

Front Tyre Size: 80/90-17

Rear Tyre Size: 110/70-17

Front Left Side: Corsa 3 mm

Rear Left Side: Corsa 3 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,360.00	1,026.00	1,334.00	56.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	300.00	380.00	55.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,040.00	1,326.00	1,714.00	56.38
Approved Total (Overridden) (S\$)		1,050.00		
Nett Amount (S\$)	3,040.00	1,050.00	1,990.00	65.46

INSPECTION

Date of Assignment: 18/12/2019

Date Inspected: 19/12/2019 Inspected At:

Hkl Lim Team Motorsport (HQ)
BLK 1008 #01-24 BUKIT MERAH LANE 3
Singapore 159722

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Jul 2020)	
Parts:	N/A	YAMAHA SNIPER T150 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBM8059L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK ASSY LH / RH	Bent	300.00 F	*300.00 FL
2	1		*FRONT FORK UNDER BRACKET	Bent	180.00 F	*180.00 FL
3	1		*STEERING CONE BEARING	Necessary	60.00 F	*60.00 FL
4	1		*FRONT FENDER	Serviceable	55.00 F	*- FL
5	1		*REAR FENDER	Broken	150.00 F	*150.00 FL
6	1		*FRONT WHEEL RIM	Repair	280.00 F	*- FL
7	1		*FRONT WHEEL SHALF	Bent	45.00 F	*45.00 FL
8	2		*FRONT WHEEL BEARING	Serviceable	40.00 F	*- FL
9	1		*FRONT WHEEL BEARING OIL SEAL	Serviceable	10.00 F	*- FL
10	1		*FRONT BRAKE DISC	Bent	120.00 F	*120.00 FL
11	1		*HEAD COWLING	Serviceable	150.00 F	*- FL
12	1		*FRONT SIGNALS LH	Cracked	60.00 F	*60.00 FL
13	1		*HANDLE BAR	Bent	80.00 F	*80.00 FL
14	1		*HANDLE BAR GRIP	Serviceable	20.00 F	*- FL
15	1		*HANDLE BAR BALANCER	Scratched	20.00 F	*20.00 FL
16	1		*CLUTCH LEVER	Scratched	25.00 F	*25.00 FL
17	1		*SIDE MIRROR	Scratched	45.00 F	*45.00 FL
18	1		*HEAD PANEL	Serviceable	60.00 F	*- FL
19	1		*GEAR PEDAL	Bent	55.00 F	*55.00 FL
20	1		*BRAKE PEDAL	Serviceable	60.00 F	*- FL
21	2		*TAIL BOARD LH / RH	Serviceable	180.00 F	*- FL
22	1		*SIDE STAND	Serviceable	45.00 F	*- FL
23	1		*MAIN STAND	Serviceable	80.00 F	*- FL
24	1		*COVER SET STICKER	Not Necessary	120.00 F	*- FL
25	1		*SIDE FAIRING LH	Serviceable	120.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,360.00	1,140.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	114.00
Total Parts (\$\$)	2,360.00	1,026.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	680.00	300.00
Gross Labour Cost (S\$)			680.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >