

13032009

ASS. REC. BY:

REF:

CS/CT19022272/Ks f3/12

Special Instructions:

CIVILIAN

Kenneth

ASSIGNMENT (Office)

From (Person):

Ben Tang

of

(11)

Date/Time:

16.12.19 11.16 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 8715T

Insured:

YN 4032L

at Workshop m/s:

S Thru Automotive

Tel:

62841542

of

BIC 8 Sinming Industrial Estate #01-64/66

Policy No:

Claim No:

SNMMD705943

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time:

18.12.19 12.30 p.m

Person Contacted:

yan

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) (Signature)

YN 4032L X

GBE 8715T X

28/1 11.12.19 8.41 a.m. email & confirmed
(\$ 10,246.01 Red - 71%)

ASS. REC. BY:

REF: 0721

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Soon:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBE 87157

Yr Regn:

04.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Dyno

c.c

2982

Colour:

h. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

217657

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

K04231

8023123

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

"

195R14X8

R/Falken

155R12X80D1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal:

3

mm

R/Bal:

55

mm

L/Bal:

3

mm

L/Bal:

55

mm

D.O.A.

12/12/19

D.O.I.

18/12/19

Survey held at

Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or

O/S R

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

RECEIVED 28 JAN 2020

Date/Time, File Pass to?

28/01/20

1) Type of

Date/Time, File Return to?



: Prelim. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) \$ - RS. \$

) Fuel

) Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

TOTAL

220

Report Format:

Lump Sum / L.B.I. (\$

4,100/- 451

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Wednesday, 18 December 2019 11:26 AM
To: assignments
Subject: FW: OUR REF: SNM19D205943; ACCIDENT INVOLVING YN4032L & GBE8715T ON 12/12/2019 ; Your Ref: JEQ/191278/1219/S3

Dear Sir

We refer to above matter.

Please assist to arrange for PRS of TP vehicle GBE8715T.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Sim Teo Koon <tk_sim@juseq.com.sg>
Sent: Wednesday, December 18, 2019 10:45 AM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; 'S Three Automotive' <admin@sthreeautomotive.com.sg>
Subject: FW: OUR REF: SNM19D205943; ACCIDENT INVOLVING YN4032L & GBE8715T ON 12/12/2019 ; Your Ref: JEQ/191278/1219/S3

URGENT

Dear Sir,

We refer to our email below.

Our client's repairer informed that till date, the surveyor had not conducted the pre-repair inspection.

Please arrange the pre-repair inspection on an URGENT BASIS.

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)

JusEquity Law Corporation.
Tel: 6506 6065, Fax: 6536 9339
E-mail: tk_sim@juseq.com.sg

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]
Sent: 13 December 2019 15:22
To: 'Ben.Tang@sg.cntaiping.com' <Ben.Tang@sg.cntaiping.com>
Cc: 'S Three Automotive' <admin@sthreeautomotive.com.sg>
Subject: FW: OUR REF: SNM19D205943; ACCIDENT INVOLVING YN4032L & GBE8715T ON 12/12/2019 ; Your Ref: JEQ/191278/1219/S3

Dear Sirs,

We refer to your email.

Our client is agreeable to appoint **KENNETH KONG (LKK Auto Consultants Pte Ltd)** as a single joint expert.

Please be informed that our client's motor vehicle is available for inspection at the under-stated workshop: -

S THREE AUTOMOTIVE RECOVERY PTE LTD
Blk 8 Sin Ming Industrial Estate #01-64/66,
Singapore 575643
Tel: 6284 1542; Fax: 6487 5315

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)
JusEquity Law Corporation.
Tel: 6506 6065, Fax: 6536 9339
E-mail: tk_sim@juseq.com.sg

From: Ben Tang [<mailto:Ben.Tang@sg.cntaiping.com>]
Sent: Friday, December 13, 2019 2:29 PM
To: claims@juseq.com.sg
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D205943; ACCIDENT INVOLVING YN4032L & GBE8715T ON 12/12/2019 ; Your Ref: JEQ/191278/1219/S3

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG

MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
GBE8715T

Make / Model
TOYOTA / DYNA 3.0 M

Vehicle Type :
B31 - Goods (Open) Lorry (Metal Body)/Pickup

Vehicle Attachment 1 :
With Hood

Vehicle Scheme :
Normal

Chassis No. :
KDY2318023123

Propellant :
Diesel

Engine No. :
1KD2580773

Motor No. :
-

Engine Capacity :
2982 cc

Power Rating :
-

Maximum Power Output :
-

Maximum Laden Weight :

3425 kg

Unladen Weight :

1800 kg

Year Of Manufacture :

2015

Original Registration Date :

08 Apr 2016

Lifespan Expiry Date :

07 Apr 2036

COE Category :

C - Goods Vehicle & Bus

PQP Paid :

\$43,094.00

COE Expiry Date :

07 Apr 2026

Road Tax Expiry Date :

07 Apr 2020

PARF Eligibility Expiry Date :

-

Inspection Due Date :

07 Apr 2020

Intended Transfer Date :

30 Jan 2020

CO2 Emission :

174.00 (g/km)

CEV/VES Rebate Utilised Amount :

-

CO Emission :

-

HC Emission :

-

NOx Emission :

-

PM Emission :

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
Road Tax Renewal - 6 months (08 Apr 2020 to 07 Oct 2020)	\$0.00
Road Tax Renewal - 12 months (08 Apr 2020 to 07 Apr 2021)	\$0.00

Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees. Any road tax that has been paid for the vehicle will be transferred to the next owner.

This vehicle has a road tax Over Payment of \$183.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

Print

OK →

Save as PDF

Copy as Text

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 12/12/2019 17:17
 Date Of Accident 12/12/2019 07:00
 Exact Location Of Accident ALONG 60 BOUNDARY CLOSE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBE8715T
Insured/Policyholder
 Name Of Registered Owner XIANGAN CONSTRUCTION PTE LTD
 Co Reg No - 399W company
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-83426668
 Alternative Phone No OFFICE-83426668

Vehicle Particulars

Manufacturer TOYOTA
 Model -

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company GREAT EASTERN GENERAL INSURANCE LIMITED
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 2019-V0100421-VCV-R002
 Cover Note Number

Driver

Name of Driver YU JIANFEI
 Work Permit No G6974835Q
 Date Of Birth 07/09/1978
 Occupation OUTDOOR
 Date Of Driving Pass 06/05/2013
 Driving Experience 6 YEARS AND 7 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-83426668
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address	-
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) Involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer attached report.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN4032L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the members of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder Signature
Date & Time:


Driver Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

— refer to attachment —

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While stationary awaiting for Inhibit vehicles to
before turning
clear A suddenly vehicle B inhibit reverse without
signaling. I noticed the lung, but still collided into
the front RH portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Police Officer's Signature
Date & Time:

Driver's Signature
(If driver is not the police officer)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PA No.:

Along to boundary (use

reversed



VEHICLE A: 6BE 871ST
VEHICLE B: 7N 4032L

REZ



Toyota : Dyna : KDY/LY(220,230,250,260) Independent Front Suspension Models : 2006.9- : KDY231R-TLMKY
Thrust Line Alignment

Front : Left

Actual	Before	Specified Range
-0°54'	-0°54'	-0°15' 1°15'
3°28'	3°28'	2°25' 3°55'
-0°01'	-0°01'	0°07' 0°12'
13°27'	13°27'	
12°34'	12°34'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-3°05'	-3°05'	-0°15' 1°15'
2°50'	2°50'	2°25' 3°55'
-0°24'	-0°23'	0°07' 0°12'
15°13'	15°13'	
12°08'	12°08'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
2°11'	2°11'	-0°30' 0°30'
0°38'	0°38'	-0°30' 0°30'
-1°45'	-1°45'	-0°30' 0°30'
-0°25'	-0°24'	0°14' 0°24'

Rear : Left

Actual	Before	Specified Range
-0°16'	-0°16'	
-0°14'	-0°14'	

Camber
Toe

Rear : Right

Actual	Before	Specified Range
0°08'	0°08'	
0°08'	0°08'	

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°25'	-0°25'	
-0°06'	-0°06'	
-0°11'	-0°11'	



GBE8715T

Toyota : Dyna KDY231R-TLMKY
Thrust Line Alignment



Front : Left

Actual	Before	Specified Range
-0°52'	-0°05'	-0°15' 1°15'
3°08'	3°08'	2°25' 3°55'
0°00'	0°10'	0°07' 0°12'
13°20'	12°33'	
12°28'	12°28'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°20'	0°29'	-0°15' 1°15'
3°23'	3°23'	2°25' 3°55'
-0°02'	-0°06'	0°07' 0°12'
12°41'	11°51'	
12°21'	12°21'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°32'	-0°34'	-0°30' 0°30'
-0°16'	-0°16'	-0°30' 0°30'
0°39'	0°41'	-0°30' 0°30'
-0°02'	0°04'	0°14' 0°24'

Rear : Left

Actual	Before	Specified Range
-0°10'	-0°12'	
0°26'	0°25'	

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-0°05'	-0°04'	
-0°30'	-0°30'	

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°06'	-0°09'	
-0°04'	-0°05'	
0°28'	0°28'	

*Not Notified
21 Sep @ 4100h
Presumy After Paint
4 days*

TO :
ATTN : **MOTOR CLAIM DEPT.**

T/P VEH. NO. : **YN4032L**

ESTIMATE REPORT 1st QUOTATION

JOB NO. : _____

OWNER'S PARTICULAR

NAME : **XIANGAN CONSTRUCTION PTE LTD**

CONTACT : _____

ADDRESS : _____

LICENSE NO. : **GBE8715T** TRANS. _____

CHASSIS NO. : **KDY2318023123**

MAKE / MODEL : **TOYOTA DYNA**

ENGINE NO. : _____

OWNER'S INSURER : **GREAT EASTERN**

JOB-CODE : **TP** S/A : **MICHELLE**

ACCIDENT DATE : **12-Dec-19**

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR. DISP	REV. PRICE
1 FRONT DOOR RH <i>1380</i>	1.00	<i>Ry</i> 1699.70	25.00	1274.78	Y	✓
2 FRONT DOOR OUTER MOULDING RH	1.00	<i>Sm</i> 121.28	25.00	90.96	Y	X
3 FRONT DOOR HANDLE RH	1.00	<i>Sm</i> 170.25	25.00	127.69	Y	X
4 FRONT DOOR INNER LOCK RH	1.00	<i>R</i> 282.90	25.00	212.18	Y	X
5 FRONT DOOR TRIMBOARD RH	1.00	<i>Sm</i> 495.60	25.00	371.70	Y	X
6 FRONT DOOR RUBBER BEADING	1.00	<i>Rad/Lst</i> 175.80	25.00	131.85	Y	<i>506sm</i>
7 FRONT WHEEL PANEL RH	1.00	<i>R</i> 402.30	25.00	301.73	Y	X
8 FRONT UPPER ARM RH	1.00	<i>Sm</i> 1430.50	25.00	1072.88	Y	X
9 FRONT LOWER ARM RH <i>348</i>	1.00	<i>Ort</i> 557.48	25.00	418.11	Y	<i>R</i>
10 FRONT KNUCKLE ARM RH	1.00	<i>Ry</i> 469.43	25.00	352.07	Y	<i>R</i>
11 FRONT KNUCKLE ARM BEARING RH	1.00	<i>Me</i> 110.48	25.00	82.86	Y	<i>R</i>
12 FRONT SHOCK ABSORBER RH	1.00	<i>Sm</i> 118.95	25.00	89.21	Y	X
13 REAR SIDE PANEL RH <i>R</i>	1.00	856.28	25.00	642.21	Y	X
14 REAR SIDE PANEL EMBLEM	1.00	<i>rm</i> 42.53	25.00	31.90	Y	X
15 FRONT MUFFLER GUARD RH	1.00	<i>Sm</i> 160.95	25.00	120.71	Y	X
16 HEADLAMP RH	1.00	<i>Gr</i> 921.40	25.00	691.05	Y	✓
17 FRONT BUMPER	1.00	<i>Bul/Gr</i> 720.88	25.00	540.66	Y	✓
18 FRONT BUMPER BRACKET	1.00	<i>R</i> 285.00	25.00	213.75	Y	X
19 STEP GARNISH RH <i>276.</i>	1.00	<i>Gr</i> 328.70	25.00	246.53	Y	—
20 FRONT WHEEL AREA PANEL RUBBER SEAL RH	1.00	<i>Dis</i> 72.70	25.00	54.53	Y	✓
21 FRONT FOG LAMP COVER RH	1.00	<i>Sm</i> 96.71	25.00	72.53	Y	X
22 FRONT FOG LAMP COVER LH	1.00	<i>Sm</i> 96.71	25.00	72.53	Y	X

23	FRONT DOOR GLASS CHANNEL RH	1.00	<i>fn</i>	211.60	25.00	158.70	Y	<u>X</u>
24	FRONT DOOR GLASS LOWER OUTER RH	1.00	<i>fn</i>	525.10	25.00	393.83	Y	<u>X</u>
25	FRONT DOOR TOP HINGE RH	1.00	<i>fn</i>	78.30	25.00	58.73	Y	<u>X</u>
26	FRONT DOOR BOTTOM HINGE RH	1.00	<i>fn</i>	99.30	25.00	74.48	Y	<u>X</u>
27	FRONT DOOR GLASS RH	1.00	<i>fn</i>	330.00	25.00	247.50	Y	<u>✓</u>
28	FRONT DOOR GLASS REGULATOR	1.00	<i>fn</i>	198.55	25.00	148.91	Y	<u>X</u>
29	FRONT DOOR GLASS MOTOR RH	1.00	<i>fn</i>	545.71	25.00	409.28	Y	<u>X</u>
30	FRONT DOOR PILLAR RUBBER RH	1.00	<i>fn</i>	65.71	25.00	49.28	Y	<u>X</u>
31	FRONT PANEL SIDE COVER RH	1.00	<i>fn</i>	189.61	25.00	142.21	Y	<u>X</u>
32	FRONT GRILLE	1.00	<i>fn</i>	475.70	25.00	356.78	Y	<u>X</u>
33	FRONT GRILLE LOGO	1.00	<i>fn</i>	69.71	25.00	52.28	Y	<u>X</u>
34	FRONT WHEEL INNER GARNISH RH	1.00	<i>fn</i>	195.80	25.00	146.85	Y	<u>X</u>
35	FRONT WHEEL INNER PROTECTOR RH	1.00	<i>fn</i>	65.91	25.00	49.43	Y	<u>X</u>
36	WING MIRROR RH	1.00	<i>fn</i>	313.81	25.00	235.36	Y	<u>✓</u>

TOTAL (PARTS) :

12981.34

9736.01

SPECIAL NETT ITEM

1	FRONT DOOR CO. STICKER	1.00	<i>fn</i>	40.00	0.00	40.00	Y	<u>25.00</u>
2	COOLANT	1.00	<i>fn</i>	80.00	0.00	80.00	Y	<u>X</u>
3	FRONT NO. PLATE	1.00	<i>fn</i>	50.00	0.00	50.00	Y	<u>X</u>
4	FRONT GRILLE CLIPS 1SET	1.00	<i>fn</i>	80.00	0.00	80.00	Y	<u>✓</u>
5	FRONT DOOR TRIM BOARD CLIPS	1.00	<i>fn</i>	80.00	0.00	80.00	Y	<u>X</u>
6	FRONT RIM RH	1.00	<i>fn</i>	480.00	0.00	480.00	Y	<u>X</u>
7	FRONT TYRE RH	1.00	<i>fn</i>	280.00	0.00	280.00	Y	<u>X</u>

TOTAL (PARTS) :

1090.00

1090.00

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA	1200.00	0.00	1200.00	Y	<u>500</u>
2	SPRAY PAINTING ON ACCIDENT AREA	1200.00	0.00	1200.00	Y	<u>500</u>
3	CHECK AND REPAIR WIRING SYSTEM	120.00	0.00	120.00	Y	<u>200</u>
4	R&R FRONT DOOR COMPONENT	120.00	0.00	120.00	Y	<u>600</u>
5	R&R FRONT SUSPENSION	380.00	0.00	380.00	Y	<u>7800</u>
6	CONDUCT FULL WHEEL ALIGNMENT	120.00	0.00	120.00	Y	<u>600</u>
7	R&R SEATS, CARPET & TRIM TO ASSIST REPAIR	<i>fn</i> 120.00	0.00	120.00	Y	<u>X</u>

8	BALANCE RIM	80.00	0.00	80.00	Y	X
9	R&R AIRCON COOLING COIL & TOP UP GAS	180.00	0.00	180.00	Y	X

TOTAL (LABOUR): 3520.00 3520.00

TOTAL PARTS & LABOUR 17591.34 14346.01

EXCESS : : S\$

NO. OF DAY :

RE-SURVEY : BEFORE / AFTER PAINTING

~~PART BY PART~~ OR LUMP-SUM : S\$

DATE OF SURVEY : 18/12/19

SURVEY BY : Kannerh

CONTACT NO : 96910663

FAX NO : 62564315

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No (legal modification) is allowed
- Supplementary work(s) must be authorised and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119022272/KSF3N2
Date: 30/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DM
Claimant Vehicle No: GBE8715T Insured Vehicle No: YN4032L
Date of Loss: 12/12/2019 Nature of Claim: TP Claim No: SNM19D205943

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE8715T
Make & Model: TOYOTA DYNA, 3.0 D (M) Engine No: 1KD2580773
Reg. Date: 08/04/2016 (Man. Year: 2015) Chassis No: KDY2318023123
Colour: Metallic Silver Odometer: 217657 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R14X8 Rear Tyre Size: 155R12X8 (D)
Front Left Side: Falken 3 mm Rear Left Side: Falken 5/5 mm
Front Right Side: Falken 3 mm Rear Right Side: Falken 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,826.00	3,819.92	7,006.08	64.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,520.00	1,320.00	2,200.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,346.00	5,139.92	9,206.08	64.17
Approved Total (Overridden) (S\$)		4,100.00		
(S\$)	14,346.00	4,100.00	10,246.00	71.42
+ GST 7.00/7.00% (S\$)	1,004.22	287.00	717.22	71.42
Nett Amount (S\$)	15,350.22	4,387.00	10,963.22	71.42

INSPECTION

Date of Assignment: 26/12/2019
Date Inspected: 18/12/2019 Inspected At: S Three Automotive & Recovery Pte Ltd - Sin Ming (HQ)
BLK 8 SIN MING IND EST #01-64/66
Singapore 575643
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Jan 2020)	
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE8715T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Bent	1,699.70 FL	*1,380.00 FL
2	1		*FRONT DOOR OUTER MOULDING RH	Serviceable	121.28 FL	*- FL
3	1		*FRONT DOOR HANDLE RH	Serviceable	170.25 FL	*- FL
4	1		*FRONT DOOR INNER LOCK RH	Repair	282.90 FL	*- FL
5	1		*FRONT DOOR TRIMBOARD RH	Serviceable	495.60 FL	*- FL
6	1		*FRONT WHEEL PANEL RH	Repair	402.30 FL	*- FL
7	1		*FRONT UPPER ARM RH	Serviceable	1,430.50 FL	*- FL
8	1		*FRONT LOWER ARM RH	Distorted	557.48 FL	*348.00 FL
9	1		*FRONT KNUCKLE ARM RH	Bent	469.43 FL	*469.43 FL
10	1		*FRONT KNUCKLE ARM BEARING RH	Necessary	110.48 FL	*110.48 FL
11	1		*FRONT SHOCK ABSORBER RH	Serviceable	118.95 FL	*- FL
12	1		*REAR SIDE PANEL RH	Repair	856.28 FL	*- FL
13	1		*REAR SIDE PANEL EMBLEM	Not Necessary	42.53 FL	*- FL
14	1		*FRONT MUFFLER GUARD RH	Serviceable	160.95 FL	*- FL
15	1		*HEADLAMP RH	Cut	921.40 FL	*921.40 FL
16	1		*FRONT BUMPER	Buckled/Cut	720.88 FL	*720.88 FL
17	1		*FRONT BUMPER BRACKET	Repair	285.00 FL	*- FL
18	1		*STEP GARNISH RH	Cut	328.70 FL	*276.00 FL
19	1		*FRONT WHEEL AREA PANEL RUBBER SEAL RH	Distorted	72.70 FL	*72.70 FL
20	1		*FRONT FOG LAMP COVER RH	Serviceable	96.71 FL	*- FL
21	1		*FRONT FOG LAMP COVER LH	Serviceable	96.71 FL	*- FL
22	1		*FRONT DOOR GLASS CHANNEL RH	Serviceable	211.60 FL	*- FL
23	1		*FRONT DOOR GLASS LOWER OUTER RH	Serviceable	525.10 FL	*- FL
24	1		*FRONT DOOR TOP HINGE RH	Repair	78.30 FL	*- FL
25	1		*FRONT DOOR BOTTOM HINGE RH	Repair	99.30 FL	*- FL
26	1		*FRONT DOOR GLASS RH	Cut	330.00 FL	*330.00 FL
27	1		*FRONT DOOR GLASS REGULATOR	Serviceable	198.55 FL	*- FL
28	1		*FRONT DOOR GLASS MOTOR RH	Serviceable	545.71 FL	*- FL
29	1		*FRONT DOOR PILLAR RUBBER RH	Serviceable	65.71 FL	*- FL
30	1		*FRONT PANEL SIDE COVER RH	Serviceable	189.61 FL	*- FL
31	1		*FRONT GRILLE	Serviceable	475.70 FL	*- FL
32	1		*FRONT GRILLE LOGO	Serviceable	69.71 FL	*- FL
33	1		*FRONT WHEEL INNER GARNISH RH	Serviceable	195.80 FL	*- FL
34	1		*FRONT WHEEL INNER PROTECTOR RH	Serviceable	65.91 FL	*- FL
35	1		*WING MIRROR RH	Dented	313.81 FL	*313.81 FL
36	1		*FRONT DOOR CO.STICKER	Necessary	40.00 FS	*25.00 FS
37	1		*COOLANT	Not Necessary	80.00 FS	*- FS
38	1		*FRONT NO PLATE	Serviceable	50.00 FS	*- FS
39	1		*SET FRONT GRILLE CLIPS	Not Necessary	80.00 FS	*- FS
40	1		*FRONT DOOR TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS
41	1		*FRONT RIM RH	Serviceable	480.00 FS	*- FS
42	1		*FRONT TYRE RH	Serviceable	280.00 FS	*- FS
43	1		*FRONT DOOR RUBBER BEADING (50%)	Dented/Cut	131.85 FS	*87.90 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **14,027.39** **5,055.60**
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,201.39 1,235.68

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	10,826.00	3,819.92
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA	New	1,200.00	500.00
2	SPRAY PAINTING ON ACCIDENT AREA	New	1,200.00	500.00
3	CHECK AND REPAIR WIRING SYSTEM	New	120.00	20.00
4	R&R FRONT DOOR COMPONENT	New	120.00	60.00
5	R&R FRONT SUSPENSION	New	380.00	180.00
6	CONDUCT FULL WHEEL ALIGNMENT	New	120.00	60.00
7	R&R SEATS,CARPET & TRIM TO ASSIST REPAIR	New	120.00	0.00
8	BALANCE RIM	New	80.00	0.00
9	R&R AIRCON COOLING COIL & TOP UP GAS	New	180.00	0.00
Gross Labour Cost (\$\$)			3,520.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >