



**TRANS EUROKARS PTE LTD**



finalised COST OF REPAIRS

<b>CHINA TAIPING INSURANCE P/L</b> 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 <b>ATTN. :</b> MOTOR CLAIMS <b>FAX :</b>		<b>NAME :</b> Mr Hee Yong Chong <b>ADDRESS :</b> No. 32 Fernvale Link #09-08 Singapore 797531 <b>TEL :</b> 96711538	<b>WIP :</b> 17108 <b>EXCESS :</b> <b>DATE:</b> 17-Dec-19
<b>VEH NO :</b>	<b>SMA2008G</b>	<b>DATE IN :</b>	<b>CONTACT PERSON :</b> Vion 63957877
<b>CHASSIS NO :</b>	JM6BN22A8J0208406	<b>MILEAGE :</b>	<b>TYPE OF CLAIM :</b> THIRD PARTY CLAIM
<b>MODEL :</b>	MAZDA3	<b>DATE REG.:</b> 30-May-18	<b>POLICY NO. :</b>

**NATURE OF WORKS**

**Parts Description**

NO	QTY		REVISED	PRICES
1	1	REAR BUMPER	\$ 1,128.60	\$ 1,128.60
2	1	BRACKET CENTER	\$ 5.40	\$ 5.40
3	1	TOWING COVER LHS	\$ 16.50	\$ 16.50
4	1	TOWING COVER RHS	\$ 17.10	\$ 17.10
5	1	REFLECTOR LHS		\$ 53.00
6	1	REFLECTOR RHS		\$ 53.00
7	1	REAR REINFORCEMENT	\$ 564.20	\$ 564.20
8	2	RETAINER CENTER, SENSOR	\$ 36.40	\$ 36.40
9	1	SENSOR CENTER, ULTRASONIC	\$ 180.90	\$ 361.80
10	1	CORD SHORT, SENSOR		\$ 152.80
11	3	TAPE PROTECTOR, SENSOR	\$ 25.80	\$ 25.80
12	2	GROMMET, REAR BUMPER	\$ 6.00	\$ 6.00
13	4	GROMMET, REAR BUMPER	\$ 10.80	\$ 10.80
14	4	RIVET, REAR BUMPER	\$ 18.00	\$ 18.00
15	2	CLIP, REAR BUMPER	\$ 6.80	\$ 6.80
16	4	FASTENER, REAR BUMPER	\$ 12.00	\$ 12.00
17	1	RETAINER LHS		\$ 33.60
18	1	RETAINER RHS		\$ 33.60
19	1	BRACKET LHS		\$ 47.90
20	1	BRACKET RHS		\$ 47.90
21	1	REAR END PANEL	\$ 530.40	\$ 530.40
22	1	TRIM, END PANEL		\$ 89.40
23	1	BEZEL, LOCK		\$ 11.40
24	6	FASTENER, TRIM		\$ 18.00
25	1	BOOTLID	\$ 1,005.30	\$ 1,005.30
26	1	WEATHERSTRIP, BOOTLID		\$ 113.10
27	1	LOCK, BOOTLID		\$ 160.70
28	1	STRIKER, BOOTLID		\$ 35.10
29	1	ORNAMENT, MAZDA	\$ 56.10	\$ 56.10
30	1	MASCOT, REAR	\$ 78.20	\$ 78.20

31	ORNAMENT, SKYACTIVE	1	MBHN1-51-771	\$ 66.80	\$ 66.80
32	FASTENER, BOOTLID	2	MEG21-51-146	\$ 12.40	\$ 12.40
33	GROMMET, BOOTLID	2	MGA7B-51-146	\$ 6.60	\$ 6.60
34	GASKET LHS, BOOTLID	1	MB45A-51-3J8	\$ 22.00	\$ 22.00
35	GASKET RHS, BOOTLID	1	MB45A-51-3H8	\$ 22.00	\$ 22.00
36	GASKET LHS, TAILLAMP	1	MBHN1-51-163	\$ 22.00	\$ 22.00
37	GASKET RHS, TAILLAMP	1	MBHN1-51-153	\$ 22.00	\$ 22.00
38	GUARD STONE LHS	1	MBHS2-50-4R2	\$ 17.40	\$ 17.40
39	GUARD STONE RHS	1	MBHS2-50-4P2	\$ 18.20	\$ 18.20
40	ANTENNA, KEYLESS	1	MKD47-67-6NXA		\$ 111.10
41	CLIP, ANTENNA	1	MKD45-67-6NYA		\$ 2.70
<b>TOTAL PARTS</b>				<b>\$ 3,907.90</b>	<b>\$ 5,052.10</b>
<b>TOTAL PARTS COST</b>				<b>\$ 3,907.90</b>	<b>\$ 5,052.10</b>

**Labour Description**

1	MZ-BR-REAR05	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID. TO REPAIR REAR FENDER LH, REAR FENDER RH, REAR FLOOR PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 2,910.00	\$ 4,290.00
2	MZ-SP-SREAR7	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL, BOOT LID, REAR FENDER LH AND REAR FENDER RH.	\$ 3,350.00	\$ 4,410.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	\$ 330.00	\$ 660.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	\$ 330.00	\$ 330.00
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.		\$ 70.00
6	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	\$ 330.00	\$ 990.00
7	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	\$ 120.00	\$ 350.00
8	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 120.00	\$ 250.00
9	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
11	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.		\$ 120.00
12	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00

TOTAL LABOUR	\$ 7,840.00	\$ 12,170.00
TOTAL PARTS	\$ 3,907.90	\$ 5,052.10
TOTAL	\$ 11,747.90	\$ 17,222.10
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ 11,747.90	
GST 7%	\$ 822.35	\$ -
<b>GRAND TOTAL</b>	<b>\$ 12,570.25</b>	<b>\$ -</b>

REMARKS:

**11 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)**