Surveyor	: Kamaliah	Kanala	ASS	IGNMON SPE	T (Omco)		Date/Time:	21/11/20
		Kanag	_ 01	1	3ill to:			
Estubated Cos	TTP RES / O	D RES / RV	AINV	IMY ICS				
ODTITINO	hicle No:	FBH	640 L					
To Inspect ve	m/s	1 7 13				Tel:		
					The state of the state of			1 = 10
of	MHASPF	160000 284	H2/1		Claim No:	79/11	159355	3 2019
					Hxcoss:			
							D.O.A	19/09/
A Carlotte and Market								
Make of Veh:		3.						
(Client's Recervi	REP. / REV	24 HRS						
CA / REV	REP. / REV	24 HRS	erson Co	ontacted:		v		
CA / REV	REP. / REV					v		
CA / REV	REP. / REV	24 HRS		ontacted:		v		
CA / REV	REP. / REV	24 HRS				v		OUT
CA / REV	REP. / REV	24 HRS				v		
CA / REV	REP. / REV	24 HRS				v		
CA / REV	REP. / REV	24 HRS				v		
CA / REV	REP. / REV	24 HRS				, /T		
CA / REV	REP. / REV	24 HRS				······································		
CA / REV	REP. / REV	24 HRS				· S		
CA / REV	REP. / REV	24 HRS				Y S		
CA / REV	REP. / REV	24 HRS				4		

Vehicles to be inspected: SHB8692U - Driver (Involved party)

IO In-Charge: SIO Saleha

## h) Case IAFP-IB-20191115 - Mechanical Inspection of Motorcycle, FBH640L (TP/IP/59353/2019)

On 19 September 2019 (Thursday) at about 5.09 pm, motor cycle was travelling along Buangkok East Drive towards Buangkok Dr, on the right of 3 lanes, when the deceased's motor cycle lost control and collided onto the right kerb at a gradual left bend. As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene at 5.26pm by Paramedic Nabila.

Vehicles to be inspected: FBH640L - Rider (Deceased) - 3865/19 611 6 K

IO In-Charge: SIO Saleha

## i) Case IAFP-IB-20191115 - Mechanical Inspection of Motorcycle, FBE735M (TP/IP/59379/2019)

On 20 September 2019, at about 2.14 a.m., the Deceased (Rider of motor cycle) was believed to be travelling on Lane 1 of 4-lanes along SLE towards CTE (10km), when she collided onto a portable directional sign, collided onto a few cones and skidded. Due to the impact, Deceased's motorcycle landed on Lane 2. There were ongoing road works at that time but there was no contact with the stationary LTA TMA truck. As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene at 2.34 am by Paramedic Christine.

Vehicles to be inspected: FBE735M - Rider (Deceased) - 377) /19 GK

IO In-Charge: SIO Saleha

## j) Case IAFP-IB-20191115 - Mechanical Inspection of Motor Car, SMA1288X (TP/IP/60507/2019)

On 26 September 2019 at about 1.10 a.m., the Deceased (pedestrian) was walking on the left lane of the 3 lanes of Jalan Bukit Merah and suddenly knelt down on the road facing oncoming traffic. The Witness, who was travelling on the left lane of the 3 lanes of Jalan Bukit Merah towards Queensway, saw the Deceased walking onto the left lane and kneel on the road. He immediately came to a stop before the Deceased and switched on the hazard lights and called for the Police. The defendant (motor car) who was travelling on the centre of the 3 lanes of Jalan Bukit Merah towards Queensway, then made left turn into the carpark entrance of Blk 110 Jalan Bukit Merah and ran over the Deceased. Due to the accident, the Deceased was conveyed to the Singapore General Hospital (SGH) however, he succumbed to his injuries and was pronounced dead on the same day at 2.33 a.m.

Vehicles to be inspected: SMA1288X - Driver (Potential defendant)

IO In-Charge: SIO Saleha

## k) Case IAFP-IB-20191115 - Mechanical Inspection of Motor Car, SMJ1564B (TP/IP/69597/2019) 4671/16 Case IAFP-IB-20191115 - Mechanical Inspection of Motorcycle, JRR7688 (TP/IP/69597/2019) 6140 61

On 9 November 2019 (Saturday) at about 4.33 a.m., the Involved Party (SMJ1564B) was driving his motor car on the extreme right lane of the 4 lanes of BKE towards Woodlands checkpoint. Somewhere after KJE, he suddenly felt an impact from the rear right portion and saw the Deceased's motorcycle (without any rider), approaching from the right side of his motor car. The motorcycle continued to veer to the left