

1-01-2002

ASS. REC. BY:

REF:

CS3/MSG19017025/Gqf302-1

Special Instruction:

SUBJECT: GQ

ASSIGNMENT (Office)

(8/12/2019

From (Person): Ng Chen How

of MSIH

Date/Time: 26.4.19 16-26P.m

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 64025

Insured:

SLJ 6138 C

at Workshop m/s Onon Autodinic

Tel:

91444476

of NO 25 K BT Rd 4 #03-31

Policy No: 29114756

Claim No:

606507

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20.9.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 27/9/19 10.14A.m

Person Contacted:

Janice

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time

Action/Instruction

X

Estimate

#03-32

After repair: 2/10/2019

RECEIVED 31 JAN 2020

\$1900, 3 Days.  
used \$640, 75%.

30/1/2020

Surveyor PRR

REF: MSG

ASSIGNMENT

From \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s Orion Auto  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: 3 Consistent? : Yes or No  
Est. Repairs: 3 days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLS6402S Yr Regn: Sep, 17  
Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Volkswagen Golf C.C. 1390  
Colour: Red A/C: Insured / Std / NI / NA  
Sp Reading: 35896 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: WVWZZZAUZH W/13844  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In Order / Jammed / Leaked / Burnt or  
Brake: In Order / Jammed / Leaked / Burnt or  
Modi: Nil / S Rim / STD A/Rim or  
Tyre Size: F: 225/45R17  
R: 11  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front  
R/Bal: 6 mm R/Bal: 6 mm  
L/Bal: 6 mm L/Bal: 6 mm  
D.O.A. \_\_\_\_\_ D.O.I. 01-10-19  
Survey held at w/s 3:20pm  
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
o/s rear  
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
\$1000 - \$2000

RECEIVED 2019

Date/Time, File Pass to? ☐ : Preli. Report  
1) ☐ : Final Report  
Date/Time, File Return to?

Days Of Repair: 3  
Resurvey No. of Trip: 1

Survey Fee:	120
Transportation:	
Photos	
Others	11
TOTAL	131

Report Format : PRR  
Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_) ☐ : S + RS (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_) ☐ : Photos  
☐ : Tech. Invs (\$ \_\_\_\_\_) ☐ : Others  
☐ : Weekend (\$ \_\_\_\_\_)

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	727B
<b>Vehicle Details</b>	
Vehicle No.:	SL564025
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.4 TSI AT 5G13HZ
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	CZC159323
Chassis No.:	WVWZZZAUZHW113844
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$20,325.00
Original Registration Date:	29 Sep 2017
First Registration Date:	29 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$10,455.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Sep 2027
PARF Rebate Amount:	\$7,841.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	28 Sep 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,902.00
COE Rebate Amount:	\$34,250.00
<b>Total Rebate Amount:</b>	<b>\$42,091.00</b>

The information contained herein is correct as at 04 Oct 2019

OK



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

## VEHICLE INSPECTION REPORT

Report No. : PAS/IP/0021019

Date of Report : 22/11/2019

To : Ms Tan Hua Geok Jennifer  
C/o. 25 Kaki Bukit Road 4  
Synergy@KB #03-31  
Singapore 417800

Date of Assignment : 01/10/2019  
Report requested by : Ms Tan Hua Geok Jennifer  
Date of Accident : 20/09/2019  
Date of Inspection : 01/10/2019  
Claim No. : Third Party Claim  
Policy No. : -

### PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SI.S6402S  
Make & Model : Volkswagen Golf  
Date of Registration : 29/09/2017  
Colour : Red

Engine Capacity (cc) : 1395cc  
Mileage (km) : 35896km  
Chassis / Frame No. : WVVZZZAUZHW113844  
Engine No. : CZC159323

### TYRE CONDITION

Front L.H : 7 mm  
Make : Pirelli

Front R.H : 7 mm  
Make : Pirelli

Rear L.H : 7 mm  
Make : Pirelli

Rear R.H : 7 mm  
Make : Pirelli

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good  
Paintwork : Good  
Handbrake : Serviceable  
Footbrake : Serviceable  
Steering : Serviceable  
Apparent Engine Modification : Nil

### PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Orion Autoclinic Pte Ltd  
25, Kaki Bukit Road 4, Synergy@KB, #03-31, Singapore 417800

### ASSESSMENT

Repairer's Estimate : \$ 3,533.54  
Revised Amount : \$ 3,173.54  
Less Excess : \$ -  
Recommended Reserve : \$ 2,540.00 (Lump Sum)

Estimated Normal Period of Repair : 4 Working Days



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address 1 Simei St 3 #02-24 S(529890)

Mobile 9295 2204 Fax 6722 8508 Email pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SLS6402S

Report No. : PAS/TP/0021019

## APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	1 pc	Rr bumper	Dented/Deformed	\$ 1,077.00	\$ / 1,077.00
2	6 pcs	Rr bumper clip	Necessary	\$ 18.00	\$ / 18.00
3	2 pcs	Rr bumper retainer R/L	Necessary	\$ 92.00	SVC \$ X 92.00
4	1 pc	Rr sport rim RH	Dented/Defaced	\$ 783.60	\$ / 783.60
5	1 pc	Rr fender RH	Dented/Repair		(Refer labour no. 3 & 4)
				\$ 1,970.60	\$ 1,970.60
				Less Discount : 10%	10% \$ 197.06
				List Parts Sub-Total :	\$ 1,773.54
1	1 pc	Rr tyre RH (Depreciate 10%)	Cut	\$ 300.00	SVC \$ X 270.00
				Special Net Sub-Total :	\$ 270.00
				Parts Total :	\$ 2,073.54
					\$ 2,043.54

S/No.	Labour Descriptions	Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	To remove and transfer rear reverse sensors to new bumper & reset control unit.	\$ 200.00	40 \$ 180.00
2	To check and adjust wheels alignment.	\$ 60.00	/ \$ 60.00
3	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs. To straighten, repair, realign on affected area and replace damaged parts.	\$ 600.00	200 \$ 440.00
4	To spray painting, blending on affected and adjacent area.	\$ 600.00	400 \$ 450.00
Labour Total :		\$ 1,460.00	\$ 1,130.00
Total (Parts & Labour) :		\$ 3,533.54	\$ 3,173.54

### For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 2,540.00

Under normal circumstances, the repairs should be completed within a reasonable period

of 4 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

16 Photographs were taken at the time of inspection.

**N.B:** By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Sep 2019 09:50		26 Sep 2019 16:26 <a href="#">Edit Adj Rpt</a>	<b>S\$1,900.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,900.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>GRAB RENTALS PTE LTD</b> , Co. Reg. No.: 201617200G								
Main Claimant:	<b>TAN HUA GEOK JENNIFER</b> , ID: S1667727B								
Vehicle Reg. No.:	<b>SLS6402S</b>	Date of Loss:	20/09/2019 22:00 - :59 [23 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 606507</b>	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	<b>SLJ6138C</b>	Policy No. (Claimant):	D19MTPV01013417						
		Excess:							
Repairer:	<b>Orion Autoclinic (HQ)</b> NO.25 K BT RD 4 #03-31 SYNERGY @ KBT, 417800 Kaki Bukit - Tel: 91444476								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>NG CHEN HOW</b> - 6643 1391]								
Claimant's Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 19/12/2019]								
Driver/Custodian (Insured):	LEE CHUAN CHENG (44 / Male) , NRIC: S7515359G, Tel: +6583096269 Email:								
Adj Asg. Remarks:	on WP. (change of workshop). OI:Grab. Liab: unclear. Disagree on SJE. Contact: Janice @ 9328 0092.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (17/12/2019): Report Send Back Alerts - SLS6402S (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents




\*SLS6402S (606507)  
[SLJ6138C]  
TP  
TAN HUA GEOK JENNIFER  
Sep 20 2019 10:00PM  
[GRAB RENTALS PTE LTD]  
Orion Autoclinic

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Video									1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)								Thumbnail	Print			
1	27/09/19 11:24	Video - Accident- 3P front								Load MP4				
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)								Thumbnail	Print			
1	23/09/19 14:04	Video - Accident [Linked Accident Report Documents]								Load MP4				
Photos/Images									3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
2	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
3	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
4	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
5	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
6	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
7	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
8	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
9	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
10	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
11	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
12	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
13	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
14	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
15	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
16	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
17	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
18	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
19	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
20	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
21	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
22	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
23	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
24	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
25	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
26	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
27	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
28	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
29	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
30	07/10/19 10:19	General View								Load JPG	<input checked="" type="checkbox"/>			
31	07/10/19 10:19	Photo After Spray								Load JPG	<input checked="" type="checkbox"/>			
32	07/10/19 10:19	Photo After Spray								Load JPG				

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	07/10/19 10:19	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
34	07/10/19 10:19	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
35	07/10/19 10:19	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
36	07/10/19 10:19	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
37	07/10/19 10:19	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
38	07/10/19 10:19	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
39	07/10/19 10:19	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
40	07/10/19 10:19	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/09/19 13:56	Email from Volkswagen	Load PDF	
2	26/09/19 13:56	Email from Law Firm	Load PDF	
3	26/09/19 13:56	Workshop Details	Load PDF	
4	26/09/19 13:56	Disagree on SJE	Load PDF	
5	17/12/19 17:40	3P Survey report	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/20 14:35	Colour Photo	Load PDF	
2	31/01/20 14:35	PRS Invoice	Load PDF	

## Linked Accident Report Documents

Video			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print	
1	23/09/19 14:04	Video - Accident	Load MP4		
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print	
1	27/09/19 08:24	Addendum Sheet	Load TIFF		
2	06/12/19 18:21	Accident Statement	Load HTM		
3	06/12/19 18:47	Accident Statement	Load HTM		
4	06/12/19 18:50	Accident Statement	Load HTM		
5	06/12/19 18:50	Accident Statement	Load HTM		
6	06/12/19 18:56	Accident Statement	Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print	
1	23/09/19 14:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
2	23/09/19 14:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
3	23/09/19 14:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
4	23/09/19 14:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
5	23/09/19 14:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
6	23/09/19 14:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
7	23/09/19 14:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
8	23/09/19 14:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
9	23/09/19 14:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
10	23/09/19 14:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
11	23/09/19 14:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
12	23/09/19 14:02	Driving License	Load JPG	<input checked="" type="checkbox"/>	
13	23/09/19 14:02	Driving License	Load JPG	<input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	23/09/19 14:03	Accident Sketch Plan	 Load TIFF	
2	23/09/19 14:03	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	23/09/19 14:03	Common Statement	 Load TIFF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19017025/GQF3E2-1

Date: 31/01/2020

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29114756

Claimant Vehicle No : SLS6402S

Insured Vehicle No : SLJ6138C

Date of Loss: 20/09/2019

Nature of Claim: TP

Claim No: 606507

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLS6402S

Make &amp; Model: VOLKSWAGEN GOLF, 1.4 TSI (A7) (5G13GZ) (A)

Engine No: CZC159323

Reg. Date: 29/09/2017 (Man. Year: 2016)

Chassis No: WWWZZZAUZHW113844

Colour: Red

Odometer: 35896 km

Engine Capacity: 1395 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes

Engine Modification: No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,073.54	1,690.74	382.80	18.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	700.00	760.00	52.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>3,533.54</b>	<b>2,390.74</b>	<b>1,142.80</b>	<b>32.34</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,900.00</b>		
<b>Nett Amount (\$\$)</b>	<b>3,533.54</b>	<b>1,900.00</b>	<b>1,633.54</b>	<b>46.23</b>

## INSPECTION

Date of Assignment: 26/09/2019

Date Inspected: 01/10/2019 Inspected At:

Orion Autoclinic (HQ)  
NO.25 K BT RD 4 #03-31 SYNERGY @  
KBT  
Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jan 2020)
<b>Parts:</b>	144	VOLKSWAGEN GOLF 1.4 TSI (A7) (5G13GZ) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLS6402S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Dented / Deformed	1,077.00 FL	*1,077.00 FL
2	6		*RR BUMPER CLIP	Necessary	18.00 FL	*18.00 FL
3	2		*RR BUMPER RETAINER R/L	Serviceable	92.00 FL	*- FL
4	1		*RR SPORT RIM RH	Dented / Defaced	783.60 FL	*783.60 FL
5	1		*RR FENDER RH (NPA)	Repair	0.00 FL	*- FL
6	1		*RR TYRE RH	Serviceable	300.00 FS	*- FS
					<b>Sub Total (S\$)</b>	<b>2,270.60</b>
					<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>197.06</b>
					<b>Total Parts (S\$)</b>	<b>2,073.54</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR REVERSE SENSORS TO NEW BUMPER & RESET CONTROL UNIT	New	200.00	40.00
2	TO CHECK AND ADJUST WHEELS ALIGNMENT	New	60.00	60.00
3	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS. TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	600.00	200.00
4	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA	New	600.00	400.00
Gross Labour Cost (S\$)			<b>1,460.00</b>	<b>700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >