

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 23129

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1486/2019/NS
Date : 17-Dec-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Koh Long Yi Adilson
Address : 23 Jalan Raja Udang
#33-08
Singapore 329216
Telephone : (HP) +65 82220917
Type of Claim : Own Damage Claims
Policy No. : 1900010892
Vehicle No. : **SKG 3293 J**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : 31/1/2019
Engine No. : CVK 075791
Chassis No. : WAUZZZF5XKA022277
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Dec-19
Place of Accident : Sentosa Gateway

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurer's Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKG 3293]

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00	1000. 1250
3	To respray front bumper and lhs front fender.	\$ 2,200.00	1100
4	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓	
5	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 5,952.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKG 3293 J

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER	\$ 2660.00	2073.00	de ✓ 2128
2	FRONT BUMPER FIXING PARTS	\$	368.00	? X
3	FRONT BUMPER SECURING STRIP	\$	32.00	? X
4	FRONT BUMPER GRILLE - CENTRE	\$	178.00	? X
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$	207.00	? X
6	FRONT BUMPER SPOILER	\$	489.00	? X
7	FRONT BUMPER AIR GUIDE - LH	\$	56.00	? X
8	FRONT BUMPER AIR GUIDE GRILLE - LH	\$	431.00	X
9	FRONT BUMPER GUIDE SECTION - LH	\$	33.00	? X
10	FRONT PARKING AID SENSOR - OUTER / INNER	\$	231.00	? X
11	FRONT PARKING AID SEAL RING	4 \$	12.00	net - 9.60
12	FRONT FENDER - LH	\$	968.00	bt - 774.40
13	FRONT FENDER ATTACHMENT PARTS	\$	48.00	net - X nn
14	FRONT FENDER CLOSING ELEMENT - LH	\$	68.00	? X nn
15	FRONT FENDER BRACKET - LH	\$	32.00	? X nn
16	FRONT FENDER BRACE - LH	\$	107.00	? ✓ 85.60 bt ✓
17	FRONT FENDER BRACKET	\$	32.00	? X
18	DEFORMATION ELEMENT BRACKET - LH	\$	45.00	? X
19	FRONT WHEEL HOUSING LINER - LH	\$	256.00	? X
20	WHEEL HOUSING LINER ATTACHMENT PARTS	\$	82.00	? X
SUB TOTAL SPARE PARTS		\$ 5,748.00		

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKG 3293 J

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	WHEEL SPOILER	\$ 66.00	? ✓ 52.32 de ✓
22	WHEEL SPOILER TRIM - LH / RH	\$ 32.00	? X } nn X
23	STONE CHIP GUARD - LH	\$ 46.00	? X } nn X
24	TRIM BRACKET - LH	\$ 22.00	? X } nn X
25	FRONT FENDER TRIM - LH	\$ 145.00	? ✓ 115.60 de
26	FENDER LEDGE COVER	\$ 32.00	? X nn
27	FENDER LEDGE TOP COVER - LH	\$ 14.00	? X nn
28	LED HEADLIGHT - LH	\$ CRA 7,204.00	? ✓ 5763.20
29	LIFT CYLINDER - LH	\$ 181.00	X nn
30	FRONT ALUMINIUM RIM - LH	\$ 943.00	cut - 754.40
31	ALUMINIUM RIM RUBBER VALVE	4 \$ 13.00	re - 10.40
32	SUNDRIES	\$ 400.00	? ✓ 36.48 rec

TOTAL SPARE PARTS	:	\$ 14,846.00	
TOTAL LABOUR CHARGES	:	\$ 5,952.00	
GRAND TOTAL	:	<u>\$ 20,798.00</u>	21,385.00

All charges are not inclusive of GST.
 Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
 Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

[Handwritten signature]
20/12/19
Taufiq 1744544
Not Authorise
Exp: to be advise.
04 days
18/12/19 @ 220pm
Resurvey before paint
suo@lkhauts.com.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant