

V006/11

2VI

ASSIGNMENT (Office)

From (Person): Cheng Ban Sen

of

CTIDate/Time: 19.12.19 9.00am

Estimated Cost:

Bill to:

OD / TP / VS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SME 99263Insured: GBH 1538Tat Workshop no: Cheng Auto BodyworksTel: 6631 0707of 5 Soon Lee Street #01-62Policy No: DMCVSIV30120419011Claim No: SMM1912206024

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14.12.2019

(Chief's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 19.12.19 10.00am

Person Contacted:

Redue1

H.O.D. Endorsement:

Vehicle: IN / OUT

Date/Time

Action/Instruction (☒) EstimateGBH 1538T XSME 99263 X

Surveyor

Steve

REF: C12

ASSIGNMENT

From:

Date:

19.12.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMF 9926J

at Workshop n/s

Chung Auto Bodyworks

of

5 Soon Lai Street #01-62

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

my 1st

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SMF 9926J

Yr Regd:

11/2/99

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz C280

C.C.

1796

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

119638

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

W 0020442 4218187

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

in

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

14/12/19

D.O.A.

19/12/19

Survey held at

Chung Auto

Des. of Damages: ☒ Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/2/20

Mr - 62k

Final 5900, 4 days (Rachel) Used to 8363.89, 59.1%

RECEIVED 05 FEB 2020

Date/Time, File Pass to?

☐

Prel. Report

05/2/2019

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

MER-TP

Lump Sum / I.B. (\$

5900

Survey Fee:

Transportation:

) 5 + RS, 28

) Photos

) Others

) 1

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Not Fed	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2019 Sendback Est	18 Dec 2019 17:11 S\$14,263.89	19 Dec 2019 09:00 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	TECHWAYS TECHNICAL SERVICES & SUPPLY PTE LTD, Co. Reg. No.: 200706905G		
Main Claimant:	FENG ZHE, ID: S8473813A		
Vehicle Reg. No.:	SMF9926J	Date of Loss:	14/12/2019 19:00 - :59 [130 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D206024/GBH1538T/CBS	Policy/Cover Note No.:	DMCVSN30120419011
Vehicle Reg. No. (Insured):	GBH1538T	Policy No. (Claimant):	GA443422 / 1
		Excess:	S\$0.00
Repairer:	Cheng Auto Bodyworks (HQ) 5 Soon Lee Street #01-62 Pioneer Point, 627607 Pioneer - Tel: 6631 0707		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/12/2019]		
Driver/Custodian (Insured):	GURDIP SINGH JOGINUAR SINGH (/ Male) Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Steve Chen (LKK Auto)

From: CLAIMS@CHENGAUTO.COM
Sent: Tuesday, February 04, 2020 11:59 AM
To: Steve Chen (LKK Auto)
Cc: Shiau Chan (LKKAuto)
Subject: RE: SMF 9926J - Finalize

Dear Mr Steve,

We accept the offer of S\$5,900.00 & 04 repair days.

Thanks & Best Regards,
Claims Department

Rachel Lai



CHENG AUTO BODYWORKS

HP: 8666 7775 | Office-Tel: 6631 0707 | Fax: 6316 2431

Reporting Centre

Address: 5 Soon Lee Street #01-60 Pioneer Point, Singapore 627607

Email: claims@chengauto.com

Workshop

Address: 5 Soon Lee Street #01-62 Pioneer Point, Singapore 627607

Email: cab@chengauto.com

Spraypainting

Address: 1 Soon Lee Street #06-41 Pioneer Centre, Singapore 627605

Email: cab@chengauto.com

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>

Sent: Monday, 20 January, 2020 9:17 AM

To: CLAIMS@CHENGAUTO.COM

Cc: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Subject: SMF 9926J - Finalize

Dear Sir,

Kindly follow up.

Thanks

Best Regards,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 813A

Vehicle Details

Vehicle No.: SMF9926J
Vehicle to be Exported: No
Intended Deregistration Date: 19 Dec 2019
Vehicle Make: MERCEDES BENZ
Vehicle Model: C 200 KOMPRESSOR
Primary Colour: Grey
Manufacturing Year: 2008
Engine No.: 27195031138536
Chassis No.: WDD2040412A218187
Maximum Power Output: 135.0 kW (181 bhp)
Open Market Value: \$43,115.00
Original Registration Date: 11 Feb 2009
First Registration Date: 11 Feb 2009
Transfer Count: 5
Actual ARF Paid: \$43,115.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 10 Feb 2029
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
PQP Paid: \$31,933.00
COE Rebate Amount: \$29,203.00
Total Rebate Amount: \$29,203.00

The information contained herein is correct as at 19 Dec 2019

OK

Cheng Auto Bodyworks (Co.Reg.No:53315238X)

5 Soon Lee Street #01-62 Pioneer Point

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**TECHWAYS TECHNICAL SERVICES & SUPPLY PTE LTD**

Singapore

Claimant Insurer: AXA Insurance Pte Ltd**PARTICULARS OF CLAIM**

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	14/12/2019
Vehicle Reg. No.:	SMF9926J	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	FENG ZHE	Driver (Insured):	GURDIP SINGH JOGINUAR SINGH
Make/Model:	MERCEDES-BENZ C200, 1.8 Kompressor (A)	Vehicle Reg. Date:	11/02/2009
Vehicle Colour:	Grey		
Engine No:	27195031138536	Chassis No:	WDD2040412A218187
Odometer:	119638 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	ON THE 14/12/2019 AT 1935HRS, MY VEHICLE A (SMF9926J) WAS PARKED ALONG 5 SOON LEE STREET AFTER REPAIRED BY CHENG AUTO BODYWORKS. VEHICLE B (GBH1538T) REVERSED AND COLLIDED INTO MY FRONT.		
Present Location:	CHENG AUTO BODYWORKS (HQ)		

COST OF CLAIMS	Amount
Parts	11,593.89
Miscellaneous Items	400.00
Labour	1,470.00
Paintwork Labour	800.00
Towing	0.00
Gross Total (S\$)	14,263.89
+ GST 7.00% (S\$)	998.47
Nett Amount (S\$)	15,262.36

This claim is handled by: LAI WAN SUN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Dec 2019)
 Parts: 143 MERCEDES-BENZ C200 1.8 Kompressor (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Auto Bodyworks/SMF9926J/18/12/2019 17:11
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET / DD	10.00	0.00	*2,455.80 FL 1819.00.
2	1		*BONNET LOGO / INT	10.00	0.00	*150.20 FL /
3	1		*BONNET HINGE RH x NM	10.00	0.00	*183.20 FL
4	1		*BONNET HINGE LH x NM	10.00	0.00	*183.20 FL
5	1		*BONNET ABSORBER RH x NM	10.00	0.00	*180.30 FL
6	1		*BONNET ABSORBER LH x NM	10.00	0.00	*180.30 FL
7	1		*BONNET INSULATOR x NM	10.00	0.00	*352.20 FL
8	1		*BONNET CABLE x NM	10.00	0.00	*159.40 FL
9	1		*BONNET RUBBER x NM	10.00	0.00	*352.50 FL
10	1		*BONNET LOCK ASSY / DT	10.00	0.00	*350.20 FL /
11	1		*BONNET LOCK CATCH x NM	10.00	0.00	*75.20 FL
12	1		*CENTRE GRILLE ASSY / DR	10.00	0.00	*852.50 FL 695 /
13	1		*RADIATOR TOP COVER x NM	10.00	0.00	*180.50 FL
14	1		*HEADLAMP RH / DR	10.00	0.00	*1,240.20 FL /
15	1		*HEADLAMP LH / DR	10.00	0.00	*1,240.20 FL /
16	1		*FRONT SUPPORT PANEL ASSY x NM	10.00	0.00	*650.40 FL
17	1		*BRACE BRACKET x NM	10.00	0.00	*65.20 FL
18	1		*FRONT BUMPER / DR	10.00	0.00	*1,714.20 FL 1315.32.
19	1		*FRONT BUMPER RETAINER RH / DR	10.00	0.00	*75.20 FL /
20	1		*FRONT BUMPER RETAINER LH / DR	10.00	0.00	*75.20 FL /
21	1		*FRONT BUMPER BRACKET RH x NM	10.00	0.00	*75.40 FL
22	1		*FRONT BUMPER BRACKET LH x NM	10.00	0.00	*75.40 FL
23	1		*FRONT REINFORCEMENT x NM	10.00	0.00	*850.40 FL
24	1		*FRONT SPONGE x NM	10.00	0.00	*155.20 FL
25	4		*FRONT PARKING SENSOR x NM	10.00	0.00	*1,009.60 FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$) 12,882.10
 - List Item Discount on L Items (\$\$) 1,288.21

Total Parts (\$\$) 11,593.89

Cheng Auto Bodyworks/SMF9926J/18/12/2019 17:11. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

6960.52
 - 10%
 6264.46

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT BONNET CLIPS <i>AK</i>	90 100.00
2	1	FRONT BUMPER CLIPS <i>NP</i>	20 100.00
3	1	SENSOR BRACKETS x 4 <i>MU</i>	X 200.00
Sub Total (S\$)			400.00

40

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	LABOUR	New	800.00 500
<u>Labour Items</u>			
2	LABOUR	New	1,200.00 500
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New	120.00 30
4	REMOVE AND REINSTALL BONNET MECHANISM TO NEW	New	150.00 50
Gross Labour Cost (S\$)			2,270.00

Cheng Auto Bodyworks/SMF9926J/18/12/2019 17:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1080

20/12/19

Steve (LKK)

WHL Phil 19/12/19, 1.20pm
4 days

L/S

My A 5/1

P-6264-46

N-40

L-1080

7384-46

L/S-5907.56

= 5900

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119022307/EQF3N2

Date: 06/02/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30120419011		
Claimant Vehicle No :	SMF9926J	Insured Vehicle No :	GBH1538T		
Date of Loss:	14/12/2019	Nature of Claim:	TP	Claim No:	SNM19D206024/GBH1538T/CBS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF9926J		Engine No:	27195031138536	
Make & Model:	MERCEDES-BENZ C200, 1.8 Kompressor (A)		Chassis No:	WDD2040412A218187	
Reg. Date:	11/02/2009 (Man. Year: 2008)		Odometer:	119638 km	
Colour:	Grey				
Engine Capacity:	1796 cc				
Market Value/New Car Price:	N/A				
Sum Insured (S\$):	Market Value/New Car Price				

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,593.89	6,264.47	5,329.42	45.97
Miscellaneous Items	400.00	40.00	360.00	90.00
Labour	1,470.00	580.00	890.00	60.54
Paintwork Labour	800.00	500.00	300.00	37.50
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,263.89	7,384.47	6,879.42	48.23
Approved Total (Overridden) (S\$)		5,900.00		
(S\$)	14,263.89	5,900.00	8,363.89	58.64
+ GST 7.00/7.00% (S\$)	998.47	413.00	585.47	58.64
Nett Amount (S\$)	15,262.36	6,313.00	8,949.36	58.64

INSPECTION

Date of Assignment:	19/12/2019	Present Location:	Cheng Auto Bodyworks (HQ)
Date Inspected:	19/12/2019	Inspected At:	Cheng Auto Bodyworks (HQ) 5 Soon Lee Street #01-62 Pioneer Point Singapore 627607
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Feb 2020)

Parts: 143 MERCEDES-BENZ C200 1.8 Kompressor (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMF9926J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,455.80 FL	*1,819.00 FL
2	1		*BONNET LOGO	Cut	150.20 FL	*150.20 FL
3	1		*BONNET HINGE RH	Not Necessary	183.20 FL	*- FL
4	1		*BONNET HINGE LH	Not Necessary	183.20 FL	*- FL
5	1		*BONNET ABSORBER RH	Not Necessary	180.30 FL	*- FL
6	1		*BONNET ABSORBER LH	Not Necessary	180.30 FL	*- FL
7	1		*BONNET INSULATOR	Not Necessary	352.20 FL	*- FL
8	1		*BONNET CABLE	Not Necessary	159.40 FL	*- FL
9	1		*BONNET RUBBER	Not Necessary	352.50 FL	*- FL
10	1		*BONNET LOCK ASSY	Bent	350.20 FL	*350.20 FL
11	1		*BONNET LOCK CATCH	Not Necessary	75.20 FL	*- FL
12	1		*CENTRE GRILLE ASSY	Broken	852.50 FL	*695.00 FL
13	1		*RADIATOR TOP COVER	Not Necessary	180.50 FL	*- FL
14	1		*HEADLAMP RH	Broken	1,240.20 FL	*1,240.20 FL
15	1		*HEADLAMP LH	Broken	1,240.20 FL	*1,240.20 FL
16	1		*FRONT SUPPORT PANEL ASSY	Not Necessary	650.40 FL	*- FL
17	1		*BRACE BRACKET	Not Necessary	65.20 FL	*- FL
18	1		*FRONT BUMPER	Broken	1,714.20 FL	*1,315.32 FL
19	1		*FRONT BUMPER RETAINER RH	Broken	75.20 FL	*75.20 FL
20	1		*FRONT BUMPER RETAINER LH	Broken	75.20 FL	*75.20 FL
21	1		*FRONT BUMPER BRACKET RH	Not Necessary	75.40 FL	*- FL
22	1		*FRONT BUMPER BRACKET LH	Not Necessary	75.40 FL	*- FL
23	1		*FRONT REINFORCEMENT	Not Necessary	850.40 FL	*- FL
24	1		*FRONT SPONGE	Not Necessary	155.20 FL	*- FL
25	4		*FRONT PARKING SENSOR	Not Necessary	1,009.60 FL	*- FL

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	12,882.10	6,960.52
- List Item Discount on L Items 10.00/10.00% (S\$)	1,288.21	696.05
Total Parts (S\$)	11,593.89	6,264.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BONNET CLIPS (Necessary)	100.00	20.00
2	1	FRONT BUMPER CLIPS (Necessary)	100.00	20.00
3	1	SENSOR BRACKETS x 4 (Not Necessary)	200.00	0.00
Sub Total (S\$)			400.00	40.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	LABOUR	New	800.00	500.00
Labour Items				
2	LABOUR	New	1,200.00	500.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New	120.00	30.00
4	REMOVE AND REINSTALL BONNET MECHANISM TO NEW	New	150.00	50.00
Gross Labour Cost (S\$)			2,270.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >