		ASSIGNME				
From (Person	Gruce te	of	SMO	Dat	e/Time: 10/12/10	@ 10.58cm
Estimated Co	it:		Bill to:			
		ES/EVA/INV/MV/CS			con Sheal	
at Workshop	m/s	SLQ 4108R Gsteen Pora	Enmaine	Insured:	64841221	656211
of		385 Sin Minor	Arve	Tel	67532112	0300-1
Pelicy No:		31111	Claim No: (MID 10	105 866/apl	
Sum Insured:			Excess:		, ,	
Make of Veh			2010-2010-	D.C	A 14/12/2	rola
(Client's Record	d)			80,00		
CA I DEV	Din					
CA I DEV	Din					
CA I DEV	REP. / REV 24	HRS Person Contacted: (/) Estinute	Curmen	Jenny P	LO.D. Endorzement:	
CA / REV Date/Time:	REP. REV 24	HRS Person Contacted: (/) Estingly	Curmen	Jenny P	LO.D. Endorzement:	

	ASSIGNMENT	21 .1
From Unit: 23/12/1	9 Veh No. SLQ 4108	R VI Royn: 07 17
Estimated Cost:	Type: M.Cycle / Bus / Van /	Lorry / Taxi / Prime Mover /
OD TP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or	(4)
To Inspect Vehicle No. SLQ 4108R	Make To A17	1588
at Workshop m/s Esteem Performance		A/C Insured / Std / NI / NA
of BIK 5033 AMK Ind. Park 2 #01-	259 Sp. Reading 181682	T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:	
Policy No.		REH104560579
Claims No.	Gen. Cond. Bood / Fair / Poor / Burn	nt
Sum Insured: Excess:	Steering: Inguler / Jammed / Leaker	I/Burnt or
(Client's Record)	Brake: Inorder Jammed / Leaker	f/Bumt or
Make of Veh: After 12pm	Modi: Nil / S/Rim / STE A/Rim	ot
111 12 12 1400	Tyre Size: F: Aic 2	15/45RIZ
(Policy Condition)	R: Nexes .	
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZ/	A / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or	
Bal, or Market Value:	Front	Rear
IDAC Accident Rport Consistent? : Yes or No	R/Bal. 7 mm	R/Bal. 9 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 7 mm	L/Bal. 9 mm
Est. Repairs: days Res.: Yes or No	D.DA. 14/12/18	DOL 23/12/19
Lum Sum: % 3 Val. Yes or No	Survey held at	
CA / REV / REP. / 24 HRS (4P)	Des. of Damages : Frt / Rear?/ O/S	I N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS 'Yehicle: Vehicle:	IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Bo	dy Structure affected due to collision.
Date / Time Action / Instruction		
	2 - 111 2020	
	RECEIVED 1 5 JAN 2020	
Constitue, File Pass to? : Prell. Report	Days Of Repair:	
		Common Prince
Date/Date, File Roams to 2	Resurvey No. of Trip:	Survey Fee: Transportation
TAX DO MY	dd Fee: Site Insp. (\$) 8-98 0
15/1 -typist	Interview (\$) Florin
Report Format : TP	: Tech, live: (8) (400)
Linny Sim / LE 1: /2 200 2	(Mae) stud 18	
	L. Tartestandone	250
		250

1.

51 UIII AVE 1, 402-25 PAYA UIII INDUSTRIAL PARK, SINGAPORE 400933 TEL: (065) 62563561 TAX: (065) 62564315

Your ref:

CMTD1905866/GPL

Our ref:

CS/SMO19022308/Kvd3

Date:24/12/2019

The Motor Claims Department M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO.SLQ 4108R

We thank for your instruction on

19/12/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on ESTEEM PERFORMANCE PTE LTD 23/12/2019 at the premises of M/s

Workshop Estimate Amount	: S\$	2,799.03
Revised Estimate Amount	: S\$	200.00
"Check" Items Amount	: S\$	
Market Value	: S\$	
LTA Reimbursement Value	; S\$	
Nett Value	: S\$	

Description of Damage:

The vehicle sustained damages at the


rear portion

Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong Licensed Appraiser nearside



front

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Tuesday, 24 December 2019 11:24 AM

To:

'Teo, Grace'; SUR; 'Gnoh, Pau Loong'

Cc:

'Ye, Yong Kang Melvin'; 'Henry, Irene James'

Subject:

RE: CMTD1905866/GPL - LKK/ FBP5069L & SLQ4108R ACC ON 14.12.19

Attachments:

SLQ 4108R PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLQ 4108R

Date of survey: 23/12/2019

Number of days (estimated): 1 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Thursday, 19 December 2019 11:08 AM

To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Gnoh, Pau Loong' <PauLoong.Gnoh@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>;

'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com> Subject: RE: CMTD1905866/GPL - LKK/ FBP5069L & SLQ4108R ACC ON 14.12.19

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer arrange on 23/12/2019.



Wishes you a Merry Christmas & Happy New Year 2020

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Thursday, 19 December 2019 10:58 AM

To: jenny chong <<u>jenny@esteemperf.com.sg</u>>; 'admin-d@lkkauto.com' <<u>admin-d@lkkauto.com</u>>; 'assignments@lkkauto.com' <<u>assignments@lkkauto.com</u>>

Cc: Gnoh, Pau Loong < PauLoong.Gnoh@sompo.com.sg >; carmen@esteemperf.com.sg;

serence@esteemperf.com.sg; kaeley@esteemperf.com.sg; shanice@esteemperf.com.sg; Ye, Yong Kang Melvin

<melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg> Subject: CMTD1905866/GPL - LKK/ FBP5069L & SLQ4108R ACC ON 14.12.19

Our Reference: CMTD1905866/GPL

Your Reference: SLQ4108R

Without Prejudice

EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Attention:

Date: 19/12/2019

M/S ESTEEM PERFORMANCE PTE LTD

Dear Jenny,

ACCIDENT INVOLVING FBP5069L & SLQ4108R ON 14.12.2019

We refer to your email reply of today.

We will appoint LKK Auto Consultants to conduct the survey.

Hi LKK Auto,

Please refer to the email below and make the arrangement to survey for SLQ4108R on a without prejudice basis and revert with your report upon completion of survey to my colleague, Mr. Pau Loong.

Thank you.

Our office will be closed on Christmas, New Year's Eve and New Year Day. Business will resume on 26th December 2019 and 2nd January 2020 respectively.

We wish you a Merry Christmas and a Happy New Year!

Best Regards **Grace Teo**Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sq | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @





For Travel, Personal Accident & Home Insurance | 2 For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: jenny chong < jenny@esteemperf.com.sg > Sent: Thursday, December 19, 2019 10:53 AM

To: Teo, Grace <grace.teo@sompo.com.sg>

Cc: Gnoh, Pau Loong < PauLoong.Gnoh@sompo.com.sg >; carmen@esteemperf.com.sg;

serence@esteemperf.com.sg; kaeley@esteemperf.com.sg; shanice@esteemperf.com.sg; Ye, Yong Kang Melvin

<melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: Re: CMTD1905866/GPL - PRI/ FBP5069L & SLQ4108R ACC ON 14.12.19

Dear Grace

We are prefer LKK kenneth to survey the car.

Thank you

Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221 F: 6484 7829

E: jenny@esteemperf.com.sq

www.esteemperformance.com

5033 Ang Mo Kio Industrial Park 2 #01-259 (Head Office) 385 Sin Ming Drive Vicom Inspection Centre

(Showroom)







Our Reference: CMTD1905866/GPL		
Your Reference: SLQ4108R		
	Without Prejudice	
Date: 19/12/2019	EMAIL ONLY	
	OUR Email: motorsurvey@sompo.com.sg	
Attention:		
M/S ESTEEM PERFORMANCE PTE LTD)	
Terry's		
Dear Jenny,		
ACCIDENT INVOLVING ERREGER P. SI	104108P ON 14 12 2019	
ACCIDENT INVOLVING FBP5069L & SL	14.12.2013	
We refer to your Notice of Accident d	ated 19/12/2019	
	ated 13/12/2013.	
	u Loong is the handler of this case who can be contact	ed at 63295 217/
PauLoong.Gnoh@sompo.com.sg .		
We intend to conduct a pre-repair sur	rvey of the damage to your client's/your customer's ve	hicle jointly with your
client/your motor workshop. We prop	pose to use one of the motor surveyors named in the a	ttached list to conduc
the joint pre-repair survey as a single		

•	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Our office will be closed on Christmas, New Year's Eve and New Year Day. Business will resume on 26th December 2019 and 2nd January 2020 respectively.

We wish you a Merry Christmas and a Happy New Year!

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sq | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG







For Travel, Personal Accident & Home Insurance | 2 For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click <a href="https://example.com/hereauth-new-collection-new-collectio

From: jenny chong < jenny@esteemperf.com.sg > Sent: Thursday, December 19, 2019 9:34 AM

To: Claims - Motor Survey < Motor Survey@sompo.com.sg>

Cc: carmen lim <carmen@esteemperf.com.sg>; serence ctc <serence@esteemperf.com.sg>; Kaeley Ng

<kaeley@esteemperf.com.sg>; Shanice Leong <shanice@esteemperf.com.sg>

Subject: REQUEST FOR PRI SURVEY SLQ4108R



Dear Sir / Mdm.

Accident involving SLO4108R & FBP5069L on 14.12.2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOAL FOR NON INJURY MOTOR ACCICDENT CASES (NIMA)

We act for Goldbell car Rental Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no . SLQ 4108 R

Please be informed that the said vehicle can be inspected at :

Name of workshop: Esteem Performance Pte Ltd

Address: BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 (S) 569536

Tel: 8799 0066

Fax: 6259 3326

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

Vehicle will be in for survey on 23.12.2019 12:00pm

Thank you.

Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221

F: 6484 7829

E: jenny@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com









Nivitha (LKK Auto)

From: Teo, Grace < grace.teo@sompo.com.sg>
Sent: Thursday, 19 December 2019 10:58 AM

To: jenny chong; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'

Cc: Gnoh, Pau Loong; carmen@esteemperf.com.sg; serence@esteemperf.com.sg;

kaeley@esteemperf.com.sg; shanice@esteemperf.com.sg; Ye, Yong Kang Melvin;

Henry, Irene James

Subject: CMTD1905866/GPL - LKK/ FBP5069L & SLQ4108R ACC ON 14.12.19

Attachments: SLQ 4108R.PDF

Our Reference: CMTD1905866/GPL

Your Reference: SLQ4108R

Without Prejudice EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Attention:

Date: 19/12/2019

M/S ESTEEM PERFORMANCE PTE LTD

Dear Jenny,

ACCIDENT INVOLVING FBP5069L & SLQ4108R ON 14.12.2019

We refer to your email reply of today.

We will appoint LKK Auto Consultants to conduct the survey.

Hi LKK Auto,

Please refer to the email below and make the arrangement to survey for SLQ4108R on a without prejudice basis and revert with your report upon completion of survey to my colleague, Mr. Pau Loong.

Thank you.

Our office will be closed on Christmas, New Year's Eve and New Year Day. Business will resume on 26th December 2019 and 2nd January 2020 respectively.

We wish you a Merry Christmas and a Happy New Year!

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission1 & Product Purchase2 via Sompo SG

Download now @





⁴ For Travel, Personal Accident & Home Insurance | ³ For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: jenny chong <jenny@esteemperf.com.sg> Sent: Thursday, December 19, 2019 10:53 AM To: Teo, Grace <grace.teo@sompo.com.sg>

Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; carmen@esteemperf.com.sg;

serence@esteemperf.com.sg; kaeley@esteemperf.com.sg; shanice@esteemperf.com.sg; Ye, Yong Kang Melvin

<melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: Re: CMTD1905866/GPL - PRI/ FBP5069L & SLQ4108R ACC ON 14.12.19

Dear Grace

We are prefer LKK kenneth to survey the car.

Thank you

Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221 F: 6484 7829

E: jenny@esteemperf.com.sq

5033 Ang Mo Kio Industrial Park 2 #01-259 (Head Office) 385 Sin Ming Drive Vicom Inspection Centre (Showroom)

www.esteemperformance.com







On Thu, Dec 19, 2019 at 10:42	AM Teo, Grace <grace.teo@sompo.com.sg> wrote:</grace.teo@sompo.com.sg>
Our Reference: CMTD1905866/	GPL
Your Reference: SLQ4108R	
	Without Prejudice
Date: 19/12/2019	EMAIL ONLY
	OUR Email: motorsurvey@sompo.com.sg
Attention:	
M/S ESTEEM PERFORMANCE PT	ELTD
Dear Jenny,	
ACCIDENT INVOLVING FBP5069	& SLQ4108R ON 14.12.2019
We refer to your Notice of Accid	ent dated 19/12/2019.
Please be informed that Mr. Gno PauLoong, Gnoh@sompo.com.sg	oh Pau Loong is the handler of this case who can be contacted at 63295 217/

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

	Pre-Repair Survey		
1	Motor Surveyor Raleigh Services	Surveyor Andrew Ow Yong	Selection (Indicate as tick)
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Jeffrey Ong

Our office will be closed on Christmas, New Year's Eve and New Year Day. Business will resume on 26th December 2019 and 2th January 2020 respectively.

We wish you a Merry Christmas and a Happy New Year!

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission1 & Product Purchase2 via Sompo SG

Download now @





³ For Travel, Personal Accident & Home Insurance | ³ For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: jenny chong < jenny@esteemperf.com.sg > Sent: Thursday, December 19, 2019 9:34 AM

To: Claims - Motor Survey < Motor Survey@sompo.com.sg>

Cc: carmen lim <carmen@esteemperf.com.sg>; serence ctc <serence@esteemperf.com.sg>; Kaeley Ng

<kaeley@esteemperf.com.sg>; Shanice Leong <shanice@esteemperf.com.sg>

Subject: REQUEST FOR PRI SURVEY SLQ4108R

Dear Sir / Mdm.

Accident involving SLQ4108R & FBP5069L on 14.12.2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOAL FOR NON INJURY MOTOR ACCICDENT CASES (NIMA) We act for Goldbell car Rental Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no . SLQ 4108 R

Please be informed that the said vehicle can be inspected at :

Name of workshop: Esteem Performance Pte Ltd

Address: BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 (S) 569536

Tel: 8799 0066

Fax: 6259 3326

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

Vehicle will be in for survey on 23.12.2019 12:00pm

Thank you.

Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221 F: 6484 7829

E: jenny@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com



CERTIFICATE OF INSURANCE Pg. 1



CERTIFICATE OF INSURANCE

MOTHER SHARE, 64 (1990) PARTY TIGHT HOS CONSTRUCTION FROM EXC., THE

SCHOOL SERVICE AND DESCRIPTIONS

NOTHIN MERCALES (THING PARTY BISHS HAVE A SHEEP AND ATTEMPT

Cities bishoot excesses by exhibited the STRTE

\$\$2,000.00 ** (1) POLICY EXCESS

Comprehensive Commercial Motor CERTIFICATE NO.

989504314

WINDSCREEN EXCESS

Goldbell Car Rental Ple Ltd

5\$100.00

SUM INSURED

INSURING WITH COE/PARE Yes.

Market Vision

SLO4108R

2) NAME OF POLICYHOLDER

3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE

1) VEHICLE REGISTRATION NO.

01 January 2019

FOR THE PURPOSES OF THE ACT

31 March 2020

4) DATE OF EXPIRY OF INSURANCE

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

Any person who is driving on the Insteed's order or with their personation

Additional Excess of \$1000 applies to all claims for Oriners before 25 years old and to eith Driving Experience less than 12 months. Additional excess of \$1000 applies to all elemin for accident consider Singapore.

" Fully Excess very according to Vehicle Usage: Rivler to Policy for review details.

Provided that the person mixing in personnel is accordance with the immuning or other man or regulations to fitting the Money Vehicle as has been to personnel and in and discussified by order of a Clean of Law or by resonnel and procedure or regulations that behalf from diving the Matter Vehicle.

6) LIMITATION AS TO USE"

- U. Use for exclus, domestic, pressure purposes and framese purposes of trissend
- 2] Dies für pockel, diemenlic, pleassen propriess med husbrane propriess of any person editors the well-cal in his ed
- I) One for the earnings of passingest for one or reward by any person to object the vehicle is bised.

The Policy does and cover: I] the Kr tuden, driving ten, earning, pace making, mitability that or speed learning, 2) this udded crossing a bake variety for binary just for the property of any one disability copyrish velocie. 3) the for any prepare is connection offs the Motor Trade.

LOSS OF USE

Not included:

HIRE PURCHASE COMPANY

Maybarik

Simulations reminent engangine by Section it of the Mater Vehicles (Trick Parly Released Compression) that (Chapter 1910) and Section 85 of the blood Sunngeon July, 1967 (Malayara), or not to be included wider these teachings.

13 Van breitig Cettly that the policy to which this Cereficate related in moved in accordance with the processor of the filters Vehicles (Nov.): Percy Fish's and Compensations FCS (Compensations FCS Compensation). The Process Francis Compensations FCS (Compensations).

tissied in Diegapore 17 Jan 2019

000125-000 Acres International Network Plant Ltd. 48 Chargi South St 1 Level 3 SINGAPORE 488130

AIG Asia Pacific Insurance Ptr. Ltd.

BANKWI

CHRISINAL



Repair Estimates

Parts (a) Cost / List Price Items

ESTEEM PERFORMANCE PTE LTD

Not Nothonker Renowy Afre Paint

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Plus/Less 25%	\$	319.68		
Total of Cost / List	\$	959.03	LICIC Auto Cons	ultrasts hence notify
(b) Nett Price Items	8		* To discovery before	the society protect
Less			A Transmiss assessment	- N. CHINA STATE
Total of Nett Item				
(c) Special Nett Items	\$	200.00	Administrator Con	The same of the sa
Total Parts Cost	\$	1,159.03	Pignatous: Date:	
Labour	\$	1,640.00		
Total	\$	2,799.03		
The above total will be subjected to Name of Surveyor			Kennesh	
Company	8			
Survey conducted on	20	23	3/12/19 at	
Remarks By Surveyor				
(a) The repair of this vehicle is	authorized /	is not authorized until fu	irther notice.	
(b) Recommended Days of Re	epair :	01	day(s)	
(c) Resurvey	100	Required / Not Require	d	
(d) Excess	:\$_		0	
(e) Signature of surveyor	21		Je Date	23/12/19

SLQ 4108 R

\$

1,278.70



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :	SLQ 4108 R	Submit By		JENNY
Make & Model:	TOYOTA ALTIS	Year Manufacture	:	2016
Chassis No :	MR053REH104560574	Engine No.	:	
-		Cost / List		

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	54	1	\$200.00	S.N	×
2	Rear bumper	n	1	\$496.50		X
3	Rear bumper clip	No	10	\$38.90		×
4	Rear bumper side retainer LH	54	1	\$110.40		×
5	Rear bumper side retainer RH	14	1	\$110.40		×
6	Rear bumper sponge	1	1	N/A		×
7	Rear bumper reinforcement	11	1	\$386.70		X
8	Rear bumper reflector LH	1	1	\$67.90		×
9	Rear bumper reflector RH	-	1	\$67.90		X
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No.	: _	SLQ 4108 R	Submit By :	Carmen Lim	
Make & Model		TOYOTA ALTIS	Year of Manufacture:	2016	

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL)	\$600.00	X
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL)	\$600.00	2001
3	TO check wiring	\$50.00	X
4	To remove & refit spare tyre, spare tyre board, carpet trim	\$150.00	X
	to assist work load.		
5	To conduct water leakage tests to ensure proper air and	\$120.00	×
	sealing		
6	To remove & refit reverse sensor	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



Repair Estimates

SLQ 4108 R

Blk 5033 Ang Mo IGo, Ind Park 2 #01-251/ 259, 569536. Tel: +85-6484 1221 Fax: +85-6484 7829 Website: www.esteemperf.com.sg

Not Nothering Afra Pains

2.1	\$	1,278.70		
Plus/Less 25%	\$	319.68		
Total of Cost / List	\$	959.03		
(b) Nett Price Items				
Less				
Total of Nett Item				
(c) Special Nett Items	\$	200.00		
otal Parts Cost	\$	1,159.03		
abour	\$ 2000	1,640.00		
otal	\$ 200.0	OU 2,799.03		
Name of Surveyor	Ē		Kennesh	
Name of Surveyor			Kenneth	
Name of Surveyor Company Survey conducted on	-	23	Kenneth UKK 112118 at	
Company	-	23.	Kenneth UKK 112118 at	
Company Survey conducted on		23.	112119 at	
Company Survey conducted on Remarks By Surveyor	: _	23.	112119 at	
Company Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is	:	23.	ther notice. day(s)	
Company Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is (b) Recommended Days of Re	:	not authorized until fun	ther notice. day(s)	23/12/19

ESTEEM PERFORMANCE

Blk 5033 Ang Mo Ko, Ind Park 2 #01-251/259, 569536. Tel: +85-6484 1221 Fex: +85-6484 7829 Website: www.esteempert.com.sg

Spare Parts

Vehicle No. : Make & Model : Chassis No : **SLQ 4108 R**

TOYOTA ALTIS MR053REH104560574 Submit By

Year Manufacture Engine No. JENNY

2016

Cost / List

S/No.	Part Description	Qt	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	S4 1	\$200.00	S.N	7
2	Rear bumper	18 1	\$496.50		X
3	Rear bumper clip	N = 10	\$38.90		×
4	Rear bumper side retainer LH	Se 1	\$110.40		*
5	Rear bumper side retainer RH	1- 1	\$110.40		X
6	Rear bumper sponge	1 1	N/A		×
7	Rear bumper reinforcement	1 1	\$386,70		X
8	Rear bumper reflector LH	1 1	\$67.90		×
9	Rear bumper reflector RH	-c 1	\$67.90		X
10	Total ballipor follows:				
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569598. Teb #65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperl.com.sg

St. Sec.	ъ.	-	40.0	
1 71	п	O	18.1	ч
-	•	_	*	•

Vehicle No.	ā	SLQ 4108 R	Submit By	:	Carmen Lim	
		TOYOTA ALTIS	Year of Manufacture :	100	2016	
Marke & Model		TOYCHA AL IIS	Tear of Manageries .		90-0-7-0	

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL)	\$800.00	X
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		0 - 1
	REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL)	\$600.00	2001
3_	TO check wiring	\$50.00	Χ
4	To remove & refit spare tyre, spare tyre board, carpet trim	\$150.00	X
	to assist work load.		
5	To conduct water leakage tests to ensure proper air and	\$120.00	Х
	sealing		
6	To remove & refit reverse sensor	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Veron Chen (LKKAuto)

From:

jenny chong <jenny@esteemperf.com.sg>

Sent:

Tuesday, 14 January 2020 5:08 PM

To:

Veron Chen (LKKAuto); Kenneth Kong (LKKAuto)

Cc:

carmen lim; serence ctc FINALISED SLO4108R

Subject: Attachments:

20200114170531136.pdf; 5df77324-1d4e-49ac-bce6-b5269f4f7dee.jpg; 3711af47-8ce9-4baa-89a0-71e501bfaf5d.jpg; b846dc9a-1c02-4b2b-a6ed-8ef7a3c957eb.jpg; caaee30e-5cd3-4e90-8890-84547d27ab48.jpg; e93b98ee-3992-4699-bbad-a09d375adbcf.jpg; f0a8a157-0dc1-4ac9-

acb2-550fde120569.jpg

Dear Veron

Pls refer as attached.

Kindly confirm the finalised amount asap.

Thank you



Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221

F: 6484 7829

E: jenny@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com







----- Forwarded message ------

From: <RicohMPC2504@singnet.com.sg> Date: Tue, Jan 14, 2020 at 5:03 PM

Subject: Message from "RNP002673C346EA" To: jaynee < jenny@esteemperf.com.sg> This E-mail was sent from "RNP002673C346EA" (MP C2504).

Scan Date: 01.14.2020 17:05:31 (+0800) Queries to: <u>RicohMPC2504@singnet.com.sg</u>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	- Williams	Affiliated to Federation Internation	onale Des Experts En Autor	mobile	
SOM	PO INSURANCE	SINGAPORE PL	Ref : CS/SMO19022	2308/Kvd3n2	
#05-0		OWERSINGAPORE 048623	Date: 16-01-2020 Code: SMO		
1.	and the same	Policy Particulars	:- THIRD PARTY CLA	IM	
	Insured Veh.	FBP 5069L	Veh. Inspected	SLQ 4108R	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CMTD1905866/GPL	Excess (\$)	0.00	
	Assign From	GRACE TEO	Assign Date	19/12/2019	
2.		Vehicle Part	iculars & Condition		
	Make & Model	TOYOTA ALTIS (A)	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	MR053REH104560574	Colour	METALLIC BLACK	
	Odometer	181692	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.		Condit	tions of Tyres	ST - S - 1/1 1/2 S - S - S - S - S - S - S - S - S - S	
		Size	Make	Balance	
	R/H Front Tyre	215/45 R17	MICHELIN	7 mm	
	L/H Front Tyre	215/45 R17	MICHELIN	7 mm	
	R/H Rear Tyre	215/45 R17	NEXEN	9 mm	
	L/H Rear Tyre	215/45 R17	NEXEN	9 mm	
4.		Descript	ion of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE RE	EAR PORTION.		
5.		- MARKET	al Information		
	Accident Date	14/12/2019	Inspection Date	23/12/2019	
	Survey held at	ESTEEM PERFORMANCE PTE	ELTD		
	BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536				
5a.		THE RESERVE OF THE PERSON OF T	Remarks		
		ON WAS CONDUCTED ON A WI			
5b.	THE ROOM OF THE	Estimate	Days of Repair		

1 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 4108R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	496.50	i
10	REAR BUMPER CLIP	NOT NECESSARY	38.90	1
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	110.40	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	110.40	
1	REAR BUMPER SPONGE (NPA)	SERVICEABLE		-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	386.70	
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	67.90	
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	67.90	
	LESS 25% DISCOUNT		-319.68	
			959.02	
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	SERVICEABLE	200.00	
			200.00	
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER, TAIL DOOR, END PANEL).	NOT NECESSARY	600.00	
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL).		600.00	200.00
	TO CHECK WIRING.	NOT NECESSARY	50.00	
	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	9
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.	NOT NECESSARY	120.00	
	TO REMOVE & REFIT REVERSE SENSOR.	NOT NECESSARY	120.00	9
	•			
	•			
			1,640.00	200.00
	GRAND TOTAL		2,799.02	200.00

Report Ref No. CS/SMO19022308/Kvd3n2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 200.00

Report Ref No. CS/SMO19022308/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.